Draft Closeout Report for IHSS Group 500-3 UBC 559 – Service Analytical Laboratory, UBC 528 – Temporary Waste Holding Building, IHSS 500-159 – Radioactive Site, Building 559, and Portions of IHSS 000-121, including Tank 7 and Tanks 33, 34, & 35



ADMIN RECORD

June 2005

Draft Closeout Report for IHSS Group 500-3 UBC 559 – Service Analytical Laboratory, UBC 528 – Temporary Waste Holding Building, IHSS 500-159 – Radioactive Site, Building 559, and Portions of IHSS 000-121, including Tank 7 and Tanks 33, 34, & 35

Approval received from the Colorado Department of Public Health and Environment

().

Approval letter contained in the Administrative Record.

TABLE OF CONTENTS

| 1.0 INTRODUCTION | 1 |
|--|----|
| 2.0 SITE CHARACTERIZATION | 3 |
| 2.1 Site History and Historical Data | 3 |
| 2.1.1 UBC 559 – Service Analytical Laboratory | 3 |
| 2.1.2 UBC 528 – Temporary Waste Holding Building | 5 |
| 2.1.3 IHSS 500-159 – Radioactive Site, Building 559 | 6 |
| 2.1.4 IHSS 000-121 - Tank 7 - OPWL Process Waste Pit | 6 |
| 2.1.5 IHSS 000-121 – OPWL Tanks 33, 34, and 35 | 7 |
| 2.2 Accelerated Action Characterization Data | 7 |
| 2.3 SORs | 35 |
| 3.0 ACCELERATED ACTION | 37 |
| 3.1 Evaluation of WRW AL Exceedances | 38 |
| 3.2 RAOs and Accelerated Action Goals | 39 |
| 3.3 D&D Activities | 40 |
| 3.4 Accelerated Action Soil Removal Activities | |
| 4.0 CONFIRMATION SAMPLING | |
| 5.0 RCRA UNIT CLOSURE | |
| 6.0 POST-ACCELERATED ACTION CONDITIONS | |
| 7.0 SSRS | 45 |
| 8.0 STEWARDSHIP EVALUATION | |
| 8.1 Current Site Conditions | |
| 8.2 Near-Term Management Recommendations | |
| 8.3 Long-Term Stewardship Recommendations | 50 |
| 9.0 DEVIATIONS FROM THE ER RSOP | 51 |
| 10.0 WASTE MANAGEMENT | |
| 11.0 SITE RECLAMATION | 51 |
| 12.0 NLR SAMPLING LOCATIONS | 51 |
| 13.0 DQA | |
| 13.1 DQA Process. | |
| 13.2 V&V of Results | 53 |
| 13.2.1 Accuracy | 54 |
| 13.2.2 Precision | 62 |
| 13.2.3 Completeness | |
| 13.2.4 Sensitivity | |
| 13.3 Summary of Data Quality | |
| 14.0 CONCLUSIONS | 67 |
| 15.0 REFERENCES | 67 |

LIST OF FIGURES

| Figure 1 | IHSS Group 500-3 Location | 2 |
|-----------|--|-----|
| Figure 2 | IHSS Group 500-3 Preaccelerated Action Soil Sampling Results Greater Than MDLs or Background Means Plus Two Standard Deviations | 4 |
| Figure 3 | IHSS Group 500-3 Surface Soil Results Greater Than RLs or Background Means Plus Two Standard Deviations | 31 |
| Figure 4 | IHSS Group 500-3 Subsurface Soil Results Greater Than RLs or Background Means Plus Two Standard Deviations – UBC 559 | 32 |
| Figure 5 | IHSS Group 500-3 Subsurface Soil Results Greater Than RLs or Background Means Plus Two Standard Deviations – Outside of UBC 559 | 33 |
| Figure 6 | IHSS Group 500-3 Features Removed and Remaining | 41 |
| Figure 7 | IHSS Group 500-3 Excavation Boundaries and Confirmation Sampling Data Greater Than Background Means Plus Two Standard Deviations | 43 |
| Figure 8 | IHSS Group 500-3 Surface Soil Residual Contamination Greater Than RLs or Background Means Plus Two Standard Deviations | 46 |
| Figure 9 | IHSS Group 500-3 Subsurface Soil Residual Contamination Greater Than RLs or Background Means Plus Two Standard Deviations – UBC 559 | 47 |
| Figure 10 | IHSS Group 500-3 Subsurface Soil Residual Contamination Greater Than RLs or Background Means Plus Two Standard Deviations - Outside of UBC 559 | 48 |
| | LIST OF TABLES | |
| Table 1 | IHSS Group 500-3 Sampling and Analysis Summary | 7 |
| Table 2 | IHSS Group 500-3 Sampling and Analysis Specifications and Deviations from the IASAP Addendum | 8 |
| Table 3 | IHSS Group 500-3 Results Greater Than RLs or Background Means Plus Two Standard Deviations | 19 |
| Table 4 | IHSS Group 500-3 Surface Soil Summary Statistics | 34 |
| Table 5 | IHSS Group 500-3 Subsurface Soil Summary Statistics | 34 |
| Table 6 | IHSS Group 500-3 Radionuclide SORs | 36 |
| Table 7 | IHSS Group 500-3 Nonradionuclide SORs for Surface Soil Samples | 37 |
| Table 8 | IHSS Group 500-3 Accelerated Action Activities | 3.7 |
| Table 9 | IHSS Group 500-3 Historical and Accelerated Action WRW AL Exceedances in Soil | 38 |
| | | |

| Table 10 | IHSS Group 500-3 Confirmation Sampling Results Greater Than RLs or Background Means Plus Two Standard Deviations | 44 |
|----------|--|----|
| Table 11 | Confirmation Sample Radionuclide SORs | 45 |
| Table 12 | IHSS Group 500-3 Accelerated Action Slab and Soil Waste Removal Summary | 51 |
| Table 13 | NLR Sampling Locations | 52 |
| Table 14 | LCS Summary | 55 |
| Table 15 | LCS Evaluation Summary | 57 |
| Table 16 | Surrogate Recovery Summary | 59 |
| Table 17 | Field Blank Summary | 59 |
| Table 18 | Sample MS Evaluation Summary | 61 |
| Table 19 | Sample MSD Evaluation Summary | 63 |
| Table 20 | Field Duplicate Sample Frequency Summary | 65 |
| Table 21 | RPD Evaluation Summary | 65 |
| Table 22 | Validation and Verification Summary | 66 |

LIST OF APPENDICES

Appendix A - Correspondence

Appendix B – Project Photographs

ENCLOSURE

Compact Disc - IHSS Group 500-3 Accelerated Action Data

ACRONYMS AND ABBREVIATIONS

AAESE Accelerated Action Ecological Screening Evaluation

AL action level

ALARA as low as reasonably achievable

AR Administrative Record
ASD Analytical Services Division

B validation code - possible laboratory contamination
B1 verification code - possible laboratory contamination

bgs below ground surface
BMP best management practice

BZ Buffer Zone

CAD/ROD Corrective Action Decision/Record of Decision

CAS Chemical Abstracts Service

CD compact disc

CDPHE Colorado Department of Public Health and Environment CERCLA Comprehensive Environmental Response, Compensation, and

Liability Act

CHWA Colorado Hazardous Waste Act

CMS/FS Corrective Measures Study/Feasibility Study

COC contaminant of concern counts per minute

CRA Comprehensive Risk Assessment

D&D Decontamination and Decommissioning

DOE U.S. Department of Energy DQA Data Quality Assessment DQO data quality objective

EMC Elevated Measurements Comparison

EPA U.S. Environmental Protection Agency (same as USEPA)

ER Environmental Restoration

ER RSOP Environmental Restoration RFCA Standard Operating Protocol for

Routine Soil Remediation

FB field blank

ft feet

ft² square feet

HPGe high-purity germanium HRR Historical Release Report

HVAC heating, ventilation, and air conditioning

IA Industrial Area

IABZSAP Industrial Area and Buffer Zone Sampling and Analysis Plan

IASAP Industrial Area Sampling and Analysis Plan

IHSS Individual Hazardous Substance Site
IM/IRA Interim Measure/Interim Remedial Action

IML Intermodal container
ISOCS In-Situ Counting System

validation code - estimated J verification code - estimated J1 К-Н Kaiser-Hill Company, L.L.C. laboratory control sample LCS LLW low-level waste method detection limit **MDL** milligrams per kilogram mg/kg milligrams per liter mg/L micrograms per kilogram (may be found as ug/kg) μg/kg micrograms per liter (may be found as ug/L) μg/L matrix spike MS matrix spike duplicate MSD not applicable NA nanocuries per gram nCi/g No Further Accelerated Action **NFAA** no longer representative NLR New Process Waste Lines **NPWL Original Process Waste Lines OPWL** polynuclear aromatic hydrocarbon **PAH** precision, accuracy, representativeness, completeness, **PARCCS** comparability, and sensitivity polychlorinated biphenyl **PCB** picocuries per gram pCi/g picocuries per liter pCi/L

QC quality control
R validation code - rejected
R1 verification code - rejected
remedial action objective

RCRA Resource Conservation and Recovery Act

polyvinyl chloride

RFCA Rocky Flats Cleanup Agreement

RFETS or Site Rocky Flats Environmental Technology Site

RFI/RI RCRA Facility Investigation/Remedial Investigation

RIN report identification number

RL reporting limit RNS rinse blank

PVC

RPD relative percent difference

RSOP RFCA Standard Operating Protocol

SAP Sampling and Analysis Plan

SOR sum of ratios

SSRS Subsurface Soil Risk Screen

SWD Soil Water Database

TB trip blank TRU transuranic

U validation code - below laboratory detection limit
U1 verification code - below laboratory detection limit

| UBC | Under Building Contamination |
|-------|--|
| USEPA | U.S. Environmental Protection Agency (same as EPA) |
| V&V | verification and validation |
| VOC | volatile organic compound |
| WRW | wildlife refuge worker |
| WSRIC | Waste Stream and Residue Identification and Characterization |

EXECUTIVE SUMMARY

This Closeout Report summarizes accelerated action activities conducted at Individual Hazardous Substance Site (IHSS) Group 500-3, which consists of Under Building Contamination Site (UBC) 559 – Service Analytical Laboratory; UBC 528 – Temporary Waste Holding Building; IHSS 500-159 – Radioactive Site, Building 559; and portions of IHSS 000-121, including Tanks 7 and Tanks 33, 34, and 35. Accelerated action activities were planned and executed in accordance with the Industrial Area (IA) Sampling and Analysis Plan (SAP) (IASAP) (DOE 2001), the Environmental Restoration (ER) Rocky Flats Cleanup Agreement (RFCA) Standard Operating Protocol (RSOP) for Routine Soil Remediation (ER RSOP) Modification 2 (DOE 2004a), IASAP Addendum #IA-03-12 (DOE 2003a), and ER RSOP Notification #05-02 (DOE 2005a).

Accelerated action activities were conducted between October 13, 2003 and May 26, 2005, and included soil characterization, removal, and confirmation sampling. Associated Decontamination and Decommissioning (D&D) activities included removal of the Building 559 slab and footers; Building 528 Pit; and all Original Process Waste Lines (OPWL), New Process Waste Lines (NPWL), sanitary sewers, and storm drains beneath and adjacent to Buildings 559 and 528. The majority of planned characterization samples were collected in August and September 2004. D&D and further characterization sampling took place from January through April 2005. Soil remediation and confirmation sampling occurred in March and April 2005.

Historical and accelerated action characterization data indicated contaminant activities and concentrations in soil greater than wildlife refuge worker (WRW) action levels (ALs) included plutonium-239/240 and americium-241 in surface soil at one location beneath Room 130 of Building 559, and benzo(a)pyrene in one historical surface soil sample collected near Building 528. Two additional areas of radionuclide exceedance were identified in subsurface soil adjacent to the Building 559 air tunnel and beneath a manway that was removed between Buildings 559 and 528.

Soil at the Room 130 hot spot location was partially excavated prior to complete removal of the Building 559 slab, and was further excavated after slab removal. The two other hot spots with plutonium-239/240 activities exceeding the WRW AL were both deeper than 3 feet (ft) below the final grade and did not require remediation under RFCA. However, both were excavated as a best management practice (BMP) and confirmation samples were collected to demonstrate the effectiveness of the remediation.

Following D&D and soil removal activities, the Building 528 and Building 559 excavations were backfilled with clean fill and the area was regraded and reseeded. Residual contamination at levels less than the WRW ALs (but greater than reporting limits [RLs] or background means plus two standard deviations) remains in surface and subsurface soil in the area.

No Further Accelerated Action (NFAA) is warranted for soil at IHSS Group 500-3. All ER RSOP remedial action objectives (RAOs) (DOE 2005a) and accelerated action goals established for remediation of IHSS Group 500-3 soil were achieved. The soil removal activities conducted at IHSS Group 500-3 contributed to the protection of human health and the environment by

removing potential sources of contamination. As part of the as low as reasonably achievable (ALARA) evaluation process mandated by RFCA, radionuclide contamination in subsurface soil that was exposed during D&D was remediated to the same WRW ALs applicable to surface soil. BMPs were used during removal activities to minimize the potential spread of contamination. The removal activities minimized the need for short- and long-term management actions. The post-remediation Subsurface Soil Risk Screen (SSRS) and stewardship evaluation presented in this document indicate no additional accelerated action is required and NFAA status is warranted for IHSS Group 500-3. Long-term stewardship actions include restricting site access, controlling soil excavation, and prohibiting groundwater pumping.


1.0 INTRODUCTION

This Closeout Report documents the accelerated action activities conducted at Individual Hazardous Substance Site (IHSS) Group 500-3, located at the U.S. Department of Energy's (DOE's) Rocky Flats Environmental Technology Site (RFETS or Site) near Golden, Colorado, and demonstrates attainment of the cleanup goals stipulated for IHSS Group 500-3. Figure 1 shows the location of IHSS Group 500-3 at RFETS. IHSS Group 500-3 consists of Under Building Contamination Site (UBC) 559 – Service Analytical Laboratory; UBC 528 – Temporary Waste Holding Building; IHSS 500-159 –Radioactive Site, Building 559; and portions of IHSS 000-121, including Tanks 7 and Tanks 33, 34, and 35.

The accelerated action activities conducted at IHSS Group 500-3 were planned and conducted in accordance with the Industrial Area (IA) Sampling and Analysis Plan (SAP) (IASAP) (DOE 2001) and the Environmental Restoration (ER) Rocky Flats Cleanup Agreement (RFCA) Standard Operating Protocol (RSOP) for Routine Soil Remediation (ER RSOP) Modification 2 (DOE 2004a). Accelerated action characterization activities were conducted in accordance with IASAP Addendum #IA-03-12 (DOE 2003a). Accelerated action soil removal activities were conducted in accordance with ER RSOP Notification #05-02 (DOE 2005a).

This IHSS Group 500-3 Closeout Report includes the following:

- Historical information;
- Deviations from IASAP Addendum #IA-03-12 sampling specifications (DOE 2003a);
- Characterization data presented in tables and shown on maps;
- Sums of ratios (SORs) and summary statistics for the accelerated action data;
- Evaluation of historical and accelerated action data greater than wildlife refuge worker (WRW) action levels (ALs);
- Remedial action objectives (RAOs) and accelerated action goals;
- Description of accelerated action activities;
- Confirmation sampling results;
- Map of the remediated areas including excavation boundaries and confirmation sampling results;
- Subsurface Soil Risk Screen (SSRS);
- Stewardship evaluation;
- Deviations from the ER RSOP;



- Maps of residual soil contamination exceeding reporting limits (RLs) for organics and background means plus two standard deviations for inorganics;
- Disposition of waste and site reclamation;
- Table of sampling locations that are no longer representative (NLR) because of being remediated;
- Data Quality Assessment (DQA);
- Conclusions;
- References;
- Contact records;
- A compact disc (CD) containing the accelerated action data set for the project with real and quality control (QC) data in separate files.

Approval of this Closeout Report constitutes regulatory agency concurrence that IHSS Group 500-3 is a No Further Accelerated Action (NFAA) site. This information and NFAA determination will be documented in the 2005 Historical Release Report (HRR) (DOE 2005b). This Closeout Report and associated documentation will be retained in the RFETS Administrative Record (AR).

2.0 SITE CHARACTERIZATION

IHSS Group 500-3 has been characterized based on site history, historical data, and accelerated action sampling data.


2.1 Site History and Historical Data

The following historical information on IHSS Group 500-3 is summarized from the 1992 HRR (DOE 1992), IASAP (DOE 2001), and IA Data Summary Report (DOE 2000).

Figure 2 presents historical soil results greater than method detection limits (MDLs) or background means plus two standard deviations. The only WRW AL exceedance is for benzo(a)pyrene in surface soil at a location near Building 528. This exceedance occurs outside the footprints of the IHSS and UBC areas that make up IHSS Group 500-3 but is in the immediate vicinity. Asphalt pavement is present in the area of the exceedance and is considered the likely source of the benzo(a)pyrene.

2.1.1 UBC 559 – Service Analytical Laboratory

Building 559, Service Analytical Laboratory, was constructed in 1967 and began operations in January 1968. Both the Production Support and Plant Support laboratories were located in the building, which housed facilities for conducting spectrochemical, chemical, and mass spectrometric analyses on samples of recovered, cast, and purified materials from the Plant. The



northern side of the building contained offices, radiation monitoring, a computer room, restrooms, a locker room, store rooms, and maintenance equipment. Four large bays in the remainder of the building housed laboratories as well as mechanical equipment.

The footprint area of Building 559 was approximately 35,000 square feet (ft²). An east-west tunnel approximately 12 feet (ft) wide and 200 ft long ran beneath the laboratory bays in the southern portion of the building. A north-south tunnel approximately 13 ft wide and 30 ft long connected the southeastern portion of Building 559 with the northeastern portion of Building 561, which housed filter plenums for Building 559. Air ducts constructed of transite pipe were present beneath the Building 559 slab (refer to RFETS Drawing 39410-105 M).

Specific laboratories included the spectrochemical analysis laboratory, chemistry laboratory, and mass spectroscopy laboratory. Radioactive materials were received and shipped from a loading dock on the south side of the building. A second loading dock at the western end of the building received other building supplies. The Production Support laboratory performed quantitative and qualitative chemical analyses for plutonium operations to ensure that raw materials, produced materials, and final products conformed to specifications. Samples consisted chiefly of plutonium and plutonium alloys, other metals and their alloys, plutonium and uranium oxides, solutions of plutonium and other elements, and various gases. Quantitative analyses included gallium in plutonium alloy, plutonium assay, carbon-hydrogen-nitrogen content, ion analysis, tritium content, emission spectrometric analysis, atomic absorption, coulometric analysis, x-ray fluorescence spectroscopy, and identification of various isotopes.

The Plant Support laboratory performed analyses on materials for functions indirectly related to production (for example, radiation monitoring and waste treatment). Specific tasks included Raschig ring analysis and certification, duct remediation, polychlorinated biphenyl (PCB) analysis, and low-level waste (LLW) characterization. Construction of Building 561 in 1973—expanded the capabilities of the laboratory. Later projects included the Waste Isolation Pilot Project Bin and Alcove test program, the Waste Stream and Residue Identification and Characterization (WSRIC) program, and consolidation and stabilization of nuclear materials. This group performed mass spectrometry analyses of isotopes of plutonium, uranium, lithium, and boron (thermal ionization), as well as organic compounds and gases. Other analyses included infrared analysis for impurities, thermal characterization analysis to determine phase changes as a function of temperature, and titrimetry to determine the water content of organic solvents.

The facility was originally built with Pyrex glass process waste lines. As discussed more thoroughly in Section 2.1.3, several documented releases occurred as a result of breakage of the glass lines.

2.1.2 UBC 528 - Temporary Waste Holding Building

Constructed in 1969, Building 528 was a below-grade concrete vault structure holding two 2,000-gallon in-sump steel tanks designed to receive process waste from Building 559 (see Tank 7 below). These wastes were mainly aqueous solutions of hydrochloric acid, nitric acid, sulfuric acid, potassium hydroxide, detergent, radionuclides, and metals. Pesticides, herbicides, and PCBs may have been present as constituents of samples analyzed. Waste was held in the Building 528 tanks until it was pumped to Building 374 for treatment.

2.1.3 IHSS 500-159 - Radioactive Site, Building 559

When Building 559 began operation, the process waste lines installed beneath the building and adjacent support buildings were made of Pyrex glass. The glass lines proved to be too brittle to withstand the strain imposed by the normal settling and shifting of the new building, and broken lines led to releases of process waste to the surrounding soil. IHSS 500-159 is a 5,400-ft² area east of Building 559 where radioactive soil associated with Original Process Waste Lines (OPWL) breaks was excavated and removed.

In 1968, less than a year after Building 559 began operation, a break was discovered in the process waste line from the building to the pump house. In response to the 1968 incident, an area of several hundred square feet was excavated and contaminated soil was removed and disposed of off site (DOE 1992).

In May 1972, a process waste line beneath Building 559 was discovered to be leaking, and the rupture of the process waste line from Building 559 to the process waste tank valve pit caused soil contamination with a gross activity of 4,500 picocuries per gram (pCi/g). The specific radionuclides associated with this activity were not reported. The contamination decreased from the pit to the concrete pad along the southern side of Building 559. As a result, polyvinyl chloride (PVC) pipe was installed to bypass the Pyrex line beneath the southern half of Building 559, and the remaining lines were static leak tested. In addition, 82 drums of contaminated soil were removed from above and horizontally adjacent to the process waste line from Building 559 to the process waste tank pit south of the building, and the pit building (Building 528) was decontaminated. The soil beneath the process waste line was not removed. Building 559 suspended generation of process waste water, and groundwater was pumped from the footing manhole to the process waste holding tanks. No documentation was found that indicated the duration for which process waste generation was suspended (DOE 1992).

In May 1977, "contaminated" groundwater was discovered in the manhole next to the southwestern corner of Building 559. The contamination was believed to be the residue of contamination released in 1972. Also in May 1977, 4,600 gallons of contaminated water leaked into a process waste collection tank in Building 528. The water leaked through a drip leg of the double-contained process waste lines and was fed by a broken 3-inch PVC process water supply line running from Building 559 to Building 561. Gross alpha radiation in the water from the drip leg was measured at 160,000 picocuries per liter (pCi/L). It was concluded that the process water supply line, process waste line, and shell of the process waste line were probably broken. The primary material of concern was process waste generated at Building 559 (DOE 1992).

2.1.4 IHSS 000-121 - Tank 7 - OPWL Process Waste Pit

Tank 7 consists of two 2,000-gallon, in-sump steel tanks that are housed in Building 528, also known as the Building 559 Process Waste Pit. Building 528 is located approximately 30 ft southeast of Building 559.

Tank 7 was installed in 1969 and received process waste from Building 559. These wastes were mainly aqueous solutions of hydrochloric acid, nitric acid, sulfuric acid, potassium hydroxide, detergent, radionuclides, and metals. Pesticides, herbicides, and PCBs may have been present as constituents of samples analyzed. If present they would be constituents of a waste mixture expected to contain laboratory solvents, as well as acids and radionuclides. According to

Building 559 personnel, Tank 7 was used as a 90-day transuranic (TRU) waste accumulation tank.

Soil from a borehole drilled adjacent to the northwestern corner of Tank 7 had plutonium-239/240 activities greater than background at a depth of 0.0 to 0.5 ft. A groundwater sample from the same location contained arsenic, barium, chromium, cobalt, copper, lead, lithium, mercury, nickel, selenium, strontium, zinc, gross alpha, gross beta, uranium-235, uranium-233/234, and uranium-238 above background levels. In a groundwater sample at the borehole adjacent to the northeastern corner of Tank 7, arsenic, strontium, manganese, sodium, zinc, uranium-233/234, and uranium-238 exceeded background concentrations (DOE 1992).

2.1.5 IHSS 000-121 - OPWL Tanks 33, 34, and 35

Based on field reconnaissance, it was concluded that these three tanks were a single tank located in the northeastern portion of Building 561. According to the Version 7.0 WSRIC Report, the function of the tank was to hold deluge water in case of a plenum fire in any of the four plenums housed in Building 561. Because this event did not occur, the tank was reportedly never used (DOE 2004b).

2.2 Accelerated Action Characterization Data

Table 1 presents a summary of planned versus actual sampling and analyses for IHSS Group 500-3. The number "planned" includes all characterization samples specified in IASAP Addendum #IA-03-12, whereas the actual number includes "planned" samples plus additional characterization samples and confirmation samples.

Table 2 presents actual accelerated action sampling specifications, and includes explanations for deviations from IASAP Addendum #IA-03-12 specifications (DOE 2003a). Confirmation samples and supplemental characterization samples not proposed in IASAP Addendum #IA-03-12 are also included.

Table 1
IHSS Group 500-3 Sampling and Analysis Summary

| IHSS Group 500-3 | Number Planned (per #IA-03-12) | Actual Number |
|---------------------------------|-----------------------------------|---------------|
| Sampling Locations | 31 | 76 . |
| Number of Samples | 60 | 116 |
| Surface Soil Samples | 27 | 24 |
| Subsurface Soil Samples | 33 | 92 |
| Number of Metal Analyses | 60 | 77 |
| Number of Radionuclide Analyses | 60 | 115 |
| Number of VOC Analyses | 60 | 76 |
| Number of Pesticide Analyses | 2 | 2 |
| Number of Herbicide Analyses | 2 | 2 |
| Number of PCB Analyses | 2 | 2 |

The number of characterization samples was expanded significantly beyond the number proposed in IASAP Addendum #IA-03-12 (DOE 2003a), because additional samples were collected opportunistically during removal of the Building 559 slab and associated OPWL.

Table 2
IHSS Group 500-3 Sampling and Analysis Specifications and Deviations from the IASAP Addendum

| Location Code | Actual Northing | Actual Easting | Proposed Northing | Proposed Easting | Actual Media | Actual Depth Interval (ft) | Actual Analytes | Offset Distance (ft) and Direction | Comments |
|------------------|--------------------|----------------------|----------------------|---------------------|--------------------|-------------------------------------|--------------------------------|------------------------------------|--|
| CA42-036 | 750199.340 | 2083458.966 | NA . | NA | Subsurface Soil | 0-4.0 | Radionuclides | NA | Confirmation sample for UBC 559, Room 130 hot spot excavation, northern sidewall, composite. |
| CA42-039 | 750190.136 | 2083465.145 | NA | NA | Subsurface Soil | 0-4.0 | Radionuclides | NA . | Confirmation sample for UBC 559, Room 130 hot spot excavation, eastern sidewall, composite. |
| CC43-000 | 750139.060 | 2083312.670 | 750138.932 | 2083320.144 | Surface Soil | 0-0.4 | Metals, Radionuclides, VOCs | .7.5 W | Relocated to target OPWL. B interval (0.5-2.5') not sampled due to shallow groundwater. |
| GG42 001 | 750110 400 | 0110 400 000000 000 | 250100 066 | 2083285.747 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | | Relocated to target OPWL. Refusal at 1.0' because of |
| CC43-001 | 750118.480 | 2083285.890 | 750120.066 | | Subsurface Soil | 0.5-1.0 | Metals, Radionuclides, VOCs | 1.6 S | cobbles; however, all analyses were completed. |
| | | | | | Subsurface Soil | 4.5-6.0 | Metals, Radionuclides, VOCs | | Biased sample originally targeted nonexistent OPWL on west side of Building 559. |
| CC43-030 | 750098.180 | 2083515.490 | 750132.021 | 2083258.184 | Subsurface Soil | 6.5-7.5 | Metals, Radionuclides, VOCs | 259.5 SE | Sample was relocated to target an OPWL near the SE corner of Building 559. |
| CC44 000 | 750196 640 | 0186.640 2083317.370 | 750106 021 | 1 2083315.431 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | 9.6 SE | Location biased for coverage. Relocated to avoid sanitary sewer line. Refusal at 0.9' because of cobbles, however all analyses were completed. |
| CC44-000 750 | 730180.040 | | 730190.021 | | Subsurface Soil | 0.5-0.9 | Metals, Radionuclides, VOCs | 9.0 SE | |

| Location Code | Actual Northing | Actual Easting | Proposed Northing | Proposed Easting | Actual Media | Actual Depth Interval (ft) | Actual Analytes | Offset Distance (ft) and Direction | Comments |
|---------------------|--------------------|----------------------|----------------------|---------------------|--------------------|-------------------------------------|--------------------------------|---|--|
| CC44-001 | 750167.950 | 2083314.200 | 750165.225 | | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | 2.8 NW | Statistical sample relocated to avoid ventilation duct. Refusal at 1.0' because of |
| CC44-001 | 750107.950 | 2083314.200 | 730103.223 | | Subsurface Soil | 0.5-1.0 | Metals, Radionuclides, VOCs | 2.0 1111 | cobbles; however, all analyses were completed. |
| CC44-002 750234,370 | 2083331.520 | 750235 127 | 2083331.920 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | <1 | Statistical sample. No significant change in location. Refusal at 0.9' because of | |
| CC44-002 | 730234.370 | 2083331.320 | 730233.127 | 2003331.920 | Subsurface Soil | 0.5-0.9 | Metals, Radionuclides, VOCs | | cobbles; however, all analyses were completed. |
| CC44-003 | 750173.210 | 2083266.818 | 750173.976 | 2083264.860 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | 2.1 SE | Relocated to target West Loading Dock. |
| CD43-000 | 750131.995 | 2083521.803 | 750138.332 | 2083521.704 | Subsurface Soil | 6.5-8.5 | Metals, Radionuclides, VOCs | 6.3 S | Relocated to avoid HVAC equipment and target OPWL. |
| CD43-001-01 | 750075.979 | 2083537.001 | 750076.374 | 2083536.539 | Subsurface Soil | 6.5-8.5 | Metals, Radionuclides, VOCs | <1 | Statistical sample. No significant change in location. |
| | | 0080.988 2083519.093 | | 2083517.608 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | | Relocated to target OPWL. |
| CD43-002-01 | 750080.988 | | 750080.929 | | Subsurface Soil | 0.5-2.5 | Metals, Radionuclides, VOCs | | |
| | | | | | Subsurface Soil | 6.5-8.5 | Metals, Radionuclides, VOCs | | |
| | | | | | Surface Soil | 0-0.5 | Metals, Radionuclides | | Statistical sample. No significant change in location. |
| CD43-003 | 750115.019 | 2083530.017 | 750114.782 | 2083529.854 | Subsurface Soil | 0.5-2.5 | Metals, Radionuclides, VOCs | <1 | VOCs not analyzed in surface |
| | | | | | Subsurface Soil | 6.5-8.5 | Metals, Radionuclides, VOCs | | soil because asphalt was present. |
| CD43-004 | 750139.060 | 2083361.670 | 750143.907 | 2083393.471 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | 32.2 SW | Relocated to target OPWL in tunnel. Refusal at 0.5' because of cobbles. B interval (0.5-2.5') not sampled. |


| Location Code | Actual Northing | Actual Easting | Proposed Northing | Proposed Easting | Actual Media | Actual Depth Interval (ft) | Actual Analytes | Offset Distance (ft) and Direction | Comments | |
|------------------|--------------------|-------------------|----------------------|---------------------|--------------------|----------------------------|--------------------------------|------------------------------------|--|--|
| OD 42,005 | | | 750000 402 | 2002452.011 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | 00 NE | Relocated to target OPWL. Refusal at 0.9' because of | |
| CD43-005 | 750103.940 | 2083461.890 | , 750099.492 | 2083453.011 | Subsurface Soil | 0.5-0.9 | Metals, Radionuclides, VOCs | | cobbles; however, all analyses were completed. | |
| | 750150 060 | 2002440.040 | 550150 553 | 2002452 150 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | 3.6 NW | Relocated to target OPWL. Refusal at 1.0' because of | |
| CD43-006 | 750159.960 | 2083449.840 | 750158.573 | 2083453.179 | Subsurface Soil | 0.5-1.0 | Metals, Radionuclides, VOCs | | cobbles; however, all analyses were completed. | |
| CD 42 007 | 750116 400 | 2002277 120 | 750115 221 | 2002266 574 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | 10.5 E | Statistical sample. Refusal at 1.0' because of cobbles; | |
| CD43-007 | 750116.480 | 2083377.120 | /50115.331 | 2083366.574 | Subsurface Soil | 0.5-1.0 | Metals, Radionuclides, VOCs | | however, all analyses were completed. | |
| CD43-008 | 750138.050 | 2083439.620 | 750135.338 | 2083435.738 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | 4.7 NE | Statistical sample. Refusal at 0.5' because of cobbles. B interval (0.5-2.5') not sampled. | |
| GD 42 000 | 750152 400 | 2002502.470 | 750155 246 | 2082504 002 | Surface Soil | 0.7-1.2 | Metals, Radionuclides, VOCs | 3.1 SW | Statistical sample. Refusal at 1.6' because of cobbles. All | |
| CD43-009 | 750153.480 | 2083502:470 | /30155.346 | 2083504.902 | Subsurface Soil | 1.2-1.6 | Metals, Radionuclides, VOCs | 3.1 SW | analyses were completed. Concrete at 0-0.7'. | |
| | | | | | Subsurface Soil | 16.5-18.5 | Metals, Radionuclides, VOCs | | | |
| CD43-010 | 750047.960 | 2083496.110 | 750048.704 | 2083488.194 | Subsurface Soil | 18.5-20.5 | Metals, Radionuclides, VOCs | 8.0 E | Relocated to the outside of Building 561 to target downgradient side of tank. | |
| · . | | | , | | Subsurface Soil | 20.5-22.5 | Metals, Radionuclides, VOCs | | downgradient side of tank. | |

| Location Code | Actual Northing | Actual Easting | Proposed Northing | Proposed Easting | Actual Media | Actual Depth Interval (ft) | Actual Analytes | Offset Distance (ft) and Direction | Comments | |
|------------------|--------------------|-------------------|----------------------|---------------------|--------------------|-------------------------------------|--------------------------------|------------------------------------|--|--|
| | | | | | Subsurface Soil | 6.5-8.5 | Metals, Radionuclides, VOCs | | | |
| | | | | | Subsurface Soil | 8.5-10.2 | Metals, Radionuclides, VOCs | - | | |
| | | | | | Subsurface Soil | 10.5-12.5 | Metals, Radionuclides, VOCs | | | |
| CD43-013 | 750068.854 | 2002521 020 | 750056 048 | 2002526 551 | Subsurface Soil | 12.5-14.5 | Metals, Radionuclides, VOCs | | Relocated to target Tank 7 from the exterior of Building 528. Collected at the depth that the OPWL entered Building 528. | |
| CD43-013 | 730008.834 | 8.854 2083521.830 | 750050.048 | 2083526.551 | Subsurface Soil | 14.5-16.5 | Metals, Radionuclides, VOCs | 13.0 144 | | |
| - | : | | · | | | | Subsurface Soil | 16.5-18.5 | Metals, Radionuclides, VOCs | |
| | | | | | Subsurface Soil | 18.5-20.5 | Metals, Radionuclides, VOCs | _ | - | |
| i i | | | | | Subsurface Soil | 20.5-22.5 | Metals, Radionuclides, VOCs | | | |
| CD43-014 | 750098.092 | 2083380.070 | 750097.743 | 2083379.861 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | <1 | Biased location targeted for south loading dock. No significant change in location. | |
| CD43-015 | 750137.050 | 2083467.610 | 750135.357 | 2083463.808 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | 4.2 NE | Relocated to target east end of tunnel. B interval (0.5'-2.5') not recovered due to cobbles. | |
| | | | | | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | | | |
| CD43-016 | 750098.926 | 2083498.975 | 750102.310 | 2083505.241 | Subsurface Soil | 0.5-2.5 | Metals, Radionuclides, VOCs | 7.1 SW | Relocated to target OPWL. | |
| | | | | | Subsurface Soil | 6.5-8.5 | Metals, Radionuclides, VOCs | | | |



| Location Code | Actual Northing | Actual Easting | Proposed Northing | Proposed Easting | Actual Media | Actual Depth Interval (ft) | Actual Analytes | Offset Distance (ft) and Direction | Comments |
|------------------|--------------------|-------------------|----------------------|---------------------|--------------------|-------------------------------------|--------------------------------|------------------------------------|---|
| | | | | | Surface Soil | | Metals, Radionuclides, VOCs | | Biased for chemical storage closet. No significant change |
| CD43-017 | 750115.480 | 2083433.140 | 750114.641 | 2083432.734 | Subsurface Soil | 0.5-0.8 | Metals, Radionuclides, VOCs | <1 | in location. Refusal at 0.8' because of cobbles; however, all analyses were completed. |
| CD43-018 | 750097.401 | 2083514.302 | 750097.416 | 2083514.261 | Subsurface Soil | 6.5-8.5 | Metals, Radionuclides, VOCs | <1 | Biased for 7-ft-deep OPWL. No significant change in location. |
| CD43-021 | 750083.639 | 2083529.285 | NA | NA | Subsurface Soil | 15.0-16.0 | Radionuclides | NA | Northern sidewall of Building 528 excavation. Sampled from excavator bucket. |
| CD43-022 | 750034.797 | 2083549.844 | NA | NA | Subsurface Soil | 17.0-18.0 | Radionuclides | NA | Southern sidewall of Building 528 excavation. Sampled from excavator bucket. |
| CD43-023 | 750048.825 | 2083501.976 | NA | NA | Subsurface Soil | 17.0-18.0 | Radionuclides | NA | Western sidewall of Building 528 excavation. Sampled from excavator bucket. |
| CD43-024 | 750059.305 | 2083539.531 | NA | NA | Subsurface Soil | 20.0-21.0 | Radionuclides | NA | Center of Building 528 excavation. Sampled from excavator bucket. |
| CD43-025 | 750036.850 | 2083505.458 | NA | NA | Subsurface Soil | 0-0.5 | Radionuclides | NA | Soil characterization sample collected from Building 528 excavation waste staging area. |
| CD43-026 | 750026.414 | 2083507.211 | NA | NA | Subsurface Soil | 0-0.5 | Radionuclides | NA | Soil characterization sample collected from Building 528 excavation waste staging area. |
| CD43-027 | 750037.133 | 2083513.661 | NA | NA | Subsurface Soil | 0-0.5 | Radionuclides | NA | Soil characterization sample collected from Building 528 excavation waste staging area. |
| CD43-028 | 750025.414 | 2083513.554 | NA | NA | Subsurface Soil | 0-0.5 | Radionuclides | NA | Soil characterization sample collected from Building 528 excavation waste staging area. |





| Location Code | Actual Northing | Actual Easting | Proposed Northing | Proposed Easting | Actual Media | Actual Depth Interval (ft) | Actual Analytes | Offset Distance (ft) and Direction | Comments |
|------------------|--------------------|-------------------|----------------------|---------------------|--------------------|-------------------------------------|--------------------------------|------------------------------------|---|
| CD43-029 | 750060.129 | 2083480.533 | NA | NA | Subsurface Soil | 20.0-22.0 | | NA | Characterization sample collected beneath Building 561 tank. |
| CD43-030 | 750137.676 | 2083282.648 | NA | NA | Subsurface Soil | 12.0-12.5 | Metals, Radionuclides, VOCs | NA | Western end of UBC 559 tunnel. |
| CD43-031 | 750134.355 | 2083384.698 | NA | NA | Subsurface Soil | 12.0-12.5 | I VOCS | NA | Midpoint of UBC 559 tunnel. |
| CD43-032 | 750134.796 | 2083458.820 | NA | NA | Subsurface Soil | 12.0-12.5 | Metals, Radionuclides, VOCs | NA | Eastern end of UBC 559 tunnel. |
| CD43-033 | 750112.386 | 2083516.974 | NA | NA | Subsurface Soil | 5.0-5.5 | VOCs | NA | Location sampled because an odor was noticed during excavation. |
| CD43-034 | 750198.392 | 2083468.364 | NA | NA | Subsurface Soil | 2.0-2.3 | Radionuclides | NA | OPWL characterization sample, east-west line, northeastern UBC 559. |
| CD43-035 | 750199.742 | 2083478.123 | NA | NA | Subsurface Soil | 2.0-2.3 | Radionuclides | NA | OPWL characterization sample, east-west line, northeastern UBC 559. |
| CD43-036 | 750198.434 | 2083489.273 | NA | NA | Subsurface Soil | 3.0-3.3 | Radionuclides | NA | OPWL characterization sample, east-west line, northeastern UBC 559. |
| CD43-037 | 750088.960 | 2083519.330 | NA | NA | Subsurface Soil | 8.0-8.3 | Radionuclides | NA | OPWL characterization sample, between Buildings 528 and 559. |
| CD43-038 | 750197.160 | 2083459.436 | NA | NA | Subsurface Soil | 0.0-4.0 | Radionuclides | NA | Confirmation sample, UBC 559, Room 130 hot spot excavation, northern sidewall, composite. |
| CD43-039 | 750193.377 | 2083459.532 | NA | ŅA | Subsurface Soil | 4.0-4.3 | Radionuclides | NA | Confirmation grab sample, UBC 559, Room 130 hot spot excavation, center of pit. |



| Location Code | Actual Northing | Actual Easting | Proposed Northing | Proposed Easting | Actual Media | Actual Depth Interval (ft) | Actual Analytes | Offset Distance (ft) and Direction | Comments |
|------------------|--------------------|------------------------|----------------------|---------------------|--------------------|-------------------------------------|--------------------------------|------------------------------------|---|
| CD43-041 | 750192.254 | 2083466.888 | NA | NA | Subsurface Soil | 0.0-4.0 | Radionuclides | NA | Confirmation sample, UBC 559, Room 130 hot spot excavation, eastern sidewall, composite. |
| CD43-042 | 750190.131 | 2083451.486 | NA | NA | Subsurface Soil | 0.0-4.5 | Radionuclides | NA | Confirmation sample, UBC 559, Room 130 hot spot excavation, western sidewall, composite. |
| CD43-044 | 750182.935 | 2083455.786 | NA | NA | Subsurface Soil | 2.5-5.0 | Radionuclides | NA | Confirmation sample, UBC 559, Room 130 hot spot excavation, southern sidewall, composite. Concrete at 0-2.5'. |
| CD43-054 | 750102.153 | 2083516.970 | NA | NA | Subsurface Soil | 7.5-7.8 | Radionuclides | NA | OPWL characterization sample beneath manway between Buildings 528 and 559. |
| CD43-055 | 750099.934 | 2083519.552 | NA | NA | Subsurface Soil | 9.0-9.5 | Metals, Radionuclides, VOCs | NA | Confirmation sample for hot spot excavated beneath manway between Buildings 528 and 559. |
| CD44-000 | 750188.878 | 2083530.912 | 750185.019 | 2083535.230 | Subsurface Soil | 6.5-8.5 | Metals, Radionuclides, VOCs | 5.8 NW | Sample biased for coverage. Relocated to avoid concrete sidewalk. |
| | | | | | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | | Statistical sample relocated to |
| CD44-001 | 750172.090 | 2083532.417 | 750176.167 | 2083518.905 | Subsurface Soil | 0.5-2.5 | Metals, Radionuclides, VOCs | 14.1 SE | avoid conex box and HVAC equipment. |
| | | | | | Subsurface Soil | 6.5-8.5 | Metals, Radionuclides, VOCs | | \ \ |
| CD44-002 | 750174.950 | 2083353.140 | 750172.350 | 2083361.509 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | RRNW | Relocated to target cutting line area. Refusal at 1.0' |
| 2211 002 | /301/4.930 | 0174.950 2083353.140 | | 2003301.309 | Subsurface Soil | 0.5-1.0 | Metals, Radionuclides, VOCs | | because of cobbles; however, all analyses were completed. |



| | | | F | | | A adisari | | Offset | |
|----------|------------|-------------|------------|-------------|--------------------|--------------|--------------------------------|-----------|---|
| | | | | | | Actual Depth | | Distance | |
| Location | Actual | Actual | Proposed | Proposed | Actual | Interval | | (ft) and | |
| Code | Northing | Easting | Northing | Easting | Media | (ft) | Actual Analytes | Direction | Comments |
| | | _ _ | | | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | | Statistical sample relocated to avoid OPWL line. Refusal at |
| CD44-003 | 750187.640 | 2083380.890 | 750185.232 | 2083383.829 | Subsurface Soil | 0.5-1.0 | Metals, Radionuclides, VOCs | 3.8 NW | 1.0' because of cobbles; however, all analyses were completed. |
| CD44-005 | 750184.640 | 2083459.240 | 750184.794 | 2083463.207 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | 4.0 W | Relocated to target sump. B interval (0.5-2.5') not sampled to avoid spreading contamination detected on field instruments (30,000 cpm - core; 3,000 cpm - soil). |
| CD44-006 | 750147.076 | 2083455.714 | NA | NA | Subsurface Soil | 4.0-4.3 | Radionuclides | NA | OPWL characterization sample. |
| CD44-007 | 750156.945 | 2083470.888 | NA | NA | Subsurface Soil | 4.0-4.3 | Radionuclides | NA | OPWL characterization sample. |
| CD44-008 | 750141.180 | 2083472.109 | NA | ŅA | Subsurface Soil | 4.0-4.3 | Radionuclides | NA | Characterization sample adjacent to east end of air tunnel. |
| CD44-009 | 750125.190 | 2083465.114 | NA | NÁ | Subsurface Soil | 5.0-5.3 | Radionuclides | NA | In-process sample collected at hot spot east of air tunnel. |
| CD44-010 | 750125.622 | 2083431.811 | NA | . NA | Subsurface Soil | 5.0-5.3 | Radionuclides | NA | Adjacent to south side of air tunnel. |
| CD44-011 | 750127.319 | 2083374.294 | NA | NA | Subsurface Soil | 5.0-5.3 | Radionuclides | NA | Adjacent to south side of air tunnel. |
| CD44-012 | 750126.916 | 2083466.281 | NA | NA | Subsurface Soil | 9.0-9.3 | Radionuclides | NA | In-process sample collected at hot spot south of air tunnel. |
| CD44-013 | 750124.718 | 2083467.964 | NA | NA | Subsurface Soil | 9.0-9.3 | Radionuclides | NA | Confirmation sample, eastern side of hot spot south of air tunnel. |
| CD44-014 | 750122.689 | 2083466.845 | NA | NA | Subsurface Soil | 9.0-9.3 | Radionuclides | NA | Confirmation sample, southern side of hot spot south of air tunnel. |
| CD44-015 | 750124.613 | 2083461.325 | NA | NA | Subsurface Soil | 9.0-9.3 | Radionuclides | NA | In-process sample collected at hot spot south of air tunnel. |



| Location Code | Actual Northing | Actual Easting | Proposed Northing | Proposed Easting | Actual Media | Actual Depth Interval (ft) | Actual Analytes | Offset Distance (ft) and Direction | Comments | |
|------------------|-------------------------|-------------------|----------------------|---------------------|--------------------|----------------------------|--------------------------------|------------------------------------|---|--------------------------|
| CD44-016 | 750124.973 | 2083466.293 | NA | NA | Subsurface Soil | 9.0-9.3 | Radionuclides | NA | Confirmation sample, hot spot east of air tunnel, center of excavation. | |
| CD44-017 | 750126.729 | 2083464.618 | NA | NA | Subsurface Soil | 11.0-11.3 | Radionuclides | NA | Confirmation sample, northern side of hot spot east of air tunnel. | |
| CD44-018 | 750125.263 | 2083458.306 | NA NA | NA | Subsurface Soil | 11.0-11.3 | Radionuclides | NA | Confirmation sample, western side of hot spot east of air tunnel. | |
| CD44-019 | 750167.909 | 2083435.156 | NA | NA | Subsurface Soil | 4.0-4.3 | Radionuclides | NA | OPWL characterization sample for newly discovered OPWL along the center of the northern side of UBC 559 slab. | |
| | | | | | Subsurface Soil | 6.5-7.1 | Metals, Radionuclides, VOCs | , | | |
| | | | | | Subsurface Soil | 8.5-10.1 | Metals, Radionuclides, VOCs | | | |
| | | | , , | | Subsurface Soil | 10.5-11.5 | Metals, Radionuclides, VOCs | | | |
| GE 42 000 | 750054 407 | 2002555 220 | 750051 504 | 2082562 500 | 2083563.590 | Subsurface Soil | 12.5-14.0 | Metals, Radionuclides, VOCs | 8.8 NW | Relocated to target OPWL |
| CE43-000 | 13-000 750054.497 2 | | /50051.504 | 2083303.390 | Subsurface Soil | 14.7-15.8 | Metals, Radionuclides, VOCs | 6.6 NW | and Building 528 basement. | |
| | | | | | Subsurface Soil | 16.5-18.5 | Metals, Radionuclides, VOCs | | | |
| | | ; | | | Subsurface Soil | 18.5-20.5 | Metals, Radionuclides, VOCs | | | |
| | | | | | Subsurface Soil | 20.5-22.4 | Metals, Radionuclides, VOCs | | | |



| Location Code | Actual Northing | Actual Easting | Proposed Northing | Proposed Easting | Actual Media | Actual Depth Interval (ft) | Actual Analytes | Offset Distance (ft) and Direction | Comments |
|------------------|--------------------|-------------------|---|---------------------|------------------------------------|-------------------------------------|---|------------------------------------|--|
| CE43-001 | 750149.154 | 2083546.442 | 750148 636 | 2083542.100 | Surface Soil Subsurface Soil | 0-0.5 | Metals, Radionuclides Metals, Radionuclides, VOCs | 11 E | Statistical sample moved to avoid abandoned communications line (encased in red |
| CE45-001 | 750145.154 | 2003340.442 | , | 20030 121100 | Subsurface Soil | 6.5-8.5 | Metals, Radionuclides, VOCs | | concrete). VOCs not analyzed in surface soil because asphalt was present. |
| GE 42 000 | 750053.000 | 2092541 000 | 750052 207 | 2083540.803 | Surface Soil | 0-0.5 | Metals, Radionuclides, VOCs | <1 | Statistical sample. No |
| CE43-002 | 750053.000 | 2083541.000 | /30033.397 | 2083340.803 | Subsurface Soil | 0.5-1.5 | Metals, Radionuclides, VOCs | | significant change in location. |
| GT 42 000 | ### DOC 000 | 2002524.546 | 750057 612 | 2083550.064 | Subsurface Soil | 19.5-20.5 | Metals, PCBs, Pesticides, Herbicides, Radionuclides, VOCs | | Biased for tank and sump. Relocated to avoid OPWL |
| CE43-003 | 750068.022 | 2083334.340 | 730037.613 | 2083330.004 | Subsurface Soil | 21.5-22.5 | Metals, PCBs, Pesticides, Herbicides, Radionuclides, VOCs | | line and building footer. |
| CE43-020 | 750089.814 | 2083577.667 | NA | NA | Subsurface Soil | 17.0-18.0 | Radionuclides | NA | Eastern sidewall of Building 528 excavation. Sampled from excavator bucket. |
| CE43-021 | 750075.377 | 2083513.984 | NA | NA | Subsurface Soil | 12.0-13.0 | Radionuclides | NA | OPWL characterization sample associated with an OPWL line that broke during excavation at Building 528. |
| CE43-022 | 750075.377 | 2083513.984 | NA | NA | Subsurface Soil | 8.0-9.0 | Radionuclides | NA | OPWL characterization sample associated with an OPWL line that broke during excavation at Building 528. |

In addition to being more economical than collecting samples by coring through the slab, sampling based on visual inspection of the lines as they were being removed allowed samples to be targeted more closely to specific areas of concern. In addition to any lines that may have been broken historically, some lines were broken during removal. Although no waste was observed escaping from any of the lines that broke as they were removed, samples were collected in areas where lines broke during removal.

As shown in Table 1, three fewer surface soil samples were collected than were specified in IASAP Addendum #IA-03-12 (DOE 2003a). This occurred because three sampling locations that were originally planned to be sampled by coring through the floor of the Building 528 Pit were instead moved to locations immediately outside the building, and the samples were collected by drilling from the ground surface. Based on engineering drawings, the bottom of the sump within the 528 Pit was 20.8 ft deep. Therefore, the initial depth interval sampled through the floor of the sump would be equivalent to 20.8 ft deep if sampled from the ground surface outside of Building 528. The Building 528 sampling was specifically targeted to sump depth, thus the three locations moved to the outside of the building changed from surface soil to subsurface soil.

Analytical suites were generally consistent with those specified in IASAP Addendum #IA-03-12 (DOE 2003a). The OPWL characterization samples collected during OPWL removal were all subsurface soil samples and were typically analyzed for radionuclides by gamma spectroscopy. Some were also analyzed for metals and volatile organic compounds (VOCs). Confirmation samples associated with the removal of radionuclide-contaminated soil were analyzed for radionuclides by both alpha spectroscopy and gamma spectroscopy.

IHSS Group 500-3 accelerated action soil results greater than RLs (for organic analytes) or background means plus two standard deviations (for inorganic analytes) are presented in Table 3. WRW AL exceedances are displayed in bold in Table 3. Plutonium-239/240 and uranium-234 activities inferred from high-purity germanium (HPGe) gamma spectroscopy results for americium-241 and uranium-238 are italicized in Table 3. Figures 3, 4, and 5 present surface and subsurface soil data for characterization samples, with WRW AL exceedances shown in red. Confirmation sample data are presented in Section 4.0.

The summary statistics for IHSS Group 500-3 surface and subsurface soil samples are presented in Tables 4 and 5, respectively. Both characterization and confirmation samples are included. For inorganics, only those detections greater than the background means plus two standard deviations are included in the detection frequency and average calculations.

As Figures 3, 4, and 5 indicate, three hot spots were identified as a result of soil sampling in IHSS Group 500-3. The surface soil sample collected at CD44-005 had a plutonium-239/240 activity of 8,130 pCi/g and an americium-241 activity of 1,200 pCi/g. A second hot spot was identified immediately south of the eastern end of the Building 559 air tunnel. Three characterization samples collected at depths ranging from 5.0 to 9.3 ft below ground surface (bgs) had plutonium activities ranging from 61 to 158 pCi/g. The third hot spot was detected after a manway vault between Buildings 528 and 559 was removed. A soil sample collected beneath the manway at a depth of 7.5 to 7.8 ft bgs had a plutonium-239/240 activity of 1,810 pCi/g and an americium-241 activity of 318 pCi/g.



Table 3
IHSS Group 500-3 Results Greater Than RLs or Background Means Plus Two Standard Deviations

| | | | Sample Starting | Sample Ending | | | | | Background Mean Plus Two | |
|----------------------|------------|-------------|--------------------|------------------|-------------------|---------|------|---------|--------------------------------|-------|
| | | | Depth | Depth | | | | | Standard | |
| Location Code | Northing | Easting | (ft bgs) | (ft bgs) | Analyte | Result | RL | WRW AL | Deviations | Unit |
| CA42-036 | 750199.340 | 2083458.966 | 0.0 | 4.0 | Americium-241 | 5.07 | NA | 76 | 0.023 | pCi/g |
| CA42-036 | 750199.340 | 2083458.966 | 0.0 | 4.0 | Plutonium-239/240 | 25.3 | NA | 50 | 0.066 | pCi/g |
| CA42-039 | 750190.136 | 2083465.145 | 0.0 | 4.0 | Americium-241 | 6.21 | NA | 76 | 0.023 | pCi/g |
| CA42-039 | 750190.136 | 2083465.145 | 0.0 | 4.0 | Plutonium-239/240 | 45.2 | NA | 50 | 0.066 | pCi/g |
| CC43-000 | 750139.060 | 2083312.670 | 0.0 | 0.4 | Barium | 717 | NA | 26400 | 141.260 | mg/kg |
| CC43-000 | 750139.060 | 2083312.670 | 0.0 | 0.4 | Chromium | 32.4 | NA . | 268 | 16.990 | mg/kg |
| CC43-000 | 750139.060 | 2083312.670 | 0.0 | 0.4 | Cobalt | 12 | NA | 1550 | 10.910 | mg/kg |
| CC43-000 | 750139.060 | 2083312.670 | 0.0 | 0.4 | Copper | 155 | NA | 40900 | 18.060 | mg/kg |
| CC43-000 | 750139.060 | 2083312.670 | 0.0 | 0.4 | Iron | 35700 | NA | 307000 | 18037.000 | mg/kg |
| CC43-000 | 750139.060 | 2083312.670 | 0.0 | 0.4 | Manganese | 627 | NA | 3480 | 365.080 | mg/kg |
| CC43-000 | 750139.060 | 2083312.670 | 0.0 | 0.4 | Nickel | 46.1 | NA | 20400 | 14.910 | mg/kg |
| CC43-000 | 750139.060 | 2083312.670 | 0.0 | 0.4 | Strontium | 246 | NA _ | 613000 | 48.940 | mg/kg |
| CC43-000 | 750139.060 | 2083312.670 | 0.0 | 0.4 | Tin | 30.4 | NA . | 613000 | 2.900 | mg/kg |
| CC43-000 | 750139.060 | 2083312.670 | 0.0 | 0.4 | Vanadium | 58.6 | NA | 7150 | 45.590 | mg/kg |
| CC43-000 | 750139.060 | 2083312.670 | 0.0 | 0.4 | Zinc | 74.7 | NA | 307000 | 73.760 | mg/kg |
| CC43-001 | 750118.480 | 2083285.890 | 0.0 | 0.5 | Aluminum | 20000 | NA | 228000 | 16902.000 | mg/kg |
| CC43-001 | 750118.480 | 2083285.890 | 0.0 | 0.5 | Beryllium | 1.1 | NA | 921 | 0.966 | mg/kg |
| CC43-001 | 750118.480 | 2083285.890 | 0.0 | 0.5 | Chromium | 17 | NA _ | 268 | 16.990 | mg/kg |
| CC43-001 | 750118.480 | 2083285.890 | 0.0 | 0.5 | Copper | 19 | NA | 40900 | 18.060 | mg/kg |
| CC43-001 | 750118.480 | 2083285.890 | 0.0 | 0.5 | Naphthalene | 6.88 | 5.62 | 3090000 | NA | μg/kg |
| CC43-001 | 750118.480 | 2083285.890 | 0.0 | 0.5 | Nickel | 16 | NA | 20400 | 14.910 | mg/kg |
| CC43-001 | 750118.480 | 2083285.890 | 0.0 | 0.5 | Xylene | 15.5 | 11.2 | 2040000 | NA | μg/kg |
| CC43-001 | 750118.480 | 2083285.890 | 0.5 | 1.0 | Uranium-235 | . 0.125 | NA | 8 | 0.120 | pCi/g |
| CC43-001 | 750118.480 | 2083285.890 | 0.5 | 1.0 | Xylene | 19.8 | 12.1 | 2040000 | NA | μg/kg |
| CC43-030 | 750098.180 | 2083515.490 | 4.5 | 6.0 | Americium-241 | 0.919 | NA | 76 | 0.020 | pCi/g |
| CC43-030 | 750098.180 | 2083515.490 | 4.5 | 6.0 | Plutonium-239/240 | 5.236 | NA | 50 | 0.020 | pCi/g |



Draft Closeout Report for IHSS Group 500-3

| X. | | | Sample Starting | Sample Ending | | | | | Background Mean Plus Two | |
|---------------|------------|-------------|--------------------|------------------|-------------|--------|-------|---------|--------------------------------|-------|
| | | | Depth | Depth | | | | | Standard | |
| Location Code | Northing | Easting | (ft bgs) | (ft bgs) | Analyte | Result | RL | WRW AL | Deviations : | Unit |
| CC43-030 | 750098.180 | 2083515.490 | 6.5 | 7.5 | Uranium-235 | 0.159 | NA NA | 8 | 0.120 | pCi/g |
| CC44-000 | 750186.640 | 2083317.370 | 0.0 | 0.5 | Uranium-234 | 2.405 | NA NA | 300 | 2.253 | pCi/g |
| CC44-000 | 750186.640 | 2083317.370 | 0.0 | 0.5 | Uranium-235 | 0.264 | NA | 8 | 0.094 | pCi/g |
| CC44-000 | 750186.640 | 2083317.370 | 0.0 | 0.5 | Uranium-238 | 2.405 | NA | 351 | 2.000 | pCi/g |
| CC44-000 | 750186.640 | 2083317.370 | 0.5 | 0.9 | Uranium-234 | 2.918 | NA | 300 | 2.640 | pCi/g |
| CC44-000 | 750186.640 | 2083317.370 | 0.5 | 0.9 | Uranium-235 | 0.184 | NA . | 8 | 0.120 | pCi/g |
| CC44-000 | 750186.640 | 2083317.370 | 0.5 | 0.9 | Uranium-238 | 2.918 | NA | 351 | 1.490 | pCi/g |
| CC44-001 | 750167.950 | 2083314.200 | 0.0 | 0.5 | Uranium-234 | 2.388 | NA | 300 | 2.253 | pCi/g |
| CC44-001 | 750167.950 | 2083314.200 | 0.0 | 0.5 | Uranium-235 | 0.182 | NA . | 8 | 0.094 | pCi/g |
| CC44-001 | 750167.950 | 2083314.200 | 0.0 | 0.5 | Uranium-238 | 2.388 | NA | 351 | 2.000 | pCi/g |
| CC44-001 | 750167.950 | 2083314.200 | 0.0 | 0.5 | Xylene | 21.8 | 10.5 | 2040000 | NA | μg/kg |
| CC44-001 | 750167.950 | 2083314.200 | 0.5 | 1.0 | Uranium-234 | 4.51 | NA | 300 | 2.640 | pCi/g |
| CC44-001 | 750167.950 | 2083314.200 | 0.5 | 1.0 | Uranium-235 | 0.173 | NA | 8 | 0.120 | pCi/g |
| CC44-001 | 750167.950 | 2083314.200 | 0.5 | 1.0 | Uranium-238 | 4.51 | NA · | 351 | 1.490 | pCi/g |
| CC44-001 | 750167.950 | 2083314.200 | 0.5 | 1.0 | Xylene | 9.72 | 9.46 | 2040000 | NA | μg/kg |
| CC44-002 | 750234.370 | 2083331.520 | 0.0 | 0.5 | Antimony | 0.48 | NA | 409 | 0.470 | mg/kg |
| CC44-002 | 750234.370 | 2083331.520 | 0.0 | 0.5 | Chromium | 17 | NA | 268 | 16.990 | mg/kg |
| CC44-002 | 750234.370 | 2083331.520 | 0.0 | 0.5 | Cobalt | 24 | NA | 1550 | 10.910 | mg/kg |
| CC44-002 | 750234.370 | 2083331.520 | 0.0 | 0.5 | Copper | 65 | NA | 40900 | 18.060 | mg/kg |
| CC44-002 | 750234.370 | 2083331.520 | 0.0 | 0.5 | Nickel | 19 | NA | 20400 | 14.910 | mg/kg |
| CC44-002 | 750234.370 | 2083331.520 | 0.0 | 0.5 | Tin | 6.6 | NA | 613000 | 2.900 | mg/kg |
| CC44-002 | 750234.370 | 2083331.520 | 0.0 | 0.5 | Uranium-234 | 4.687 | NA | 300 | 2.253 | pCi/g |
| CC44-002 | 750234.370 | 2083331.520 | 0.0 | 0.5 | Uranium-235 | 0.188 | NA | 8 | 0.094 | pCi/g |
| CC44-002 | 750234.370 | 2083331.520 | 0.0 | 0.5 | Uranium-238 | 4.687 | NA | 351 | 2.000 | pCi/g |
| CC44-002 | 750234.370 | 2083331.520 | 0.5 | 0.9 | Uranium-234 | 4.375 | NA | 300 | 2.640 | pCi/g |
| CC44-002 | 750234.370 | 2083331.520 | 0.5 | 0.9 | Uranium-235 | 0.296 | NA | 8 | 0.120 | pCi/g |
| CC44-002 | 750234.370 | 2083331.520 | 0.5 | 0.9 | Uranium-238 | 4.375 | NA | 351 | 1.490 | pCi/g |
| CC44-003 | 750173.210 | 2083266.818 | 0.0 | 0.5 | Aluminum | 18000 | NA | 228000 | 16902.000 | mg/kg |
| CC44-003 | 750173.210 | 2083266.818 | 0.0 | 0.5 | Beryllium | 1.2 | NA | 921 | 0.966 | mg/kg |

Draft Closeout Report for IHSS Group 500-3

| | | | | 147 5 51 | | | | | Background | |
|---------------------------|---------------------|---------------------|-----------------|-----------------|---------------------|-------------|----------|----------|---------------------|-------|
| | | | Sample | Sample | | | | | Mean Plus | |
| | | | Starting | Ending | | | | | Two | |
| , | N T 41. | 77 | Depth | Depth | A 1 4 | Devil | RL | WRW AL | Standard Deviations | Ünit |
| Location Code CC44-003 | Northing 750173.210 | Easting 2083266.818 | (ft bgs) 0.0 | (ft bgs) 0.5 | Analyte Chromium | Result 20 | NA | 268 | 16.990 | mg/kg |
| CC44-003 | 750173.210 | 2083266.818 | 0.0 | 0.5 | Cobalt | 22 | NA NA | 1550 | 10.910 | mg/kg |
| CC44-003 | | 2083266.818 | 0.0 | 0.5 | | 53 | NA NA | 40900 | 18.060 | mg/kg |
| | 750173.210 | 2083266.818 | 0.0 | 0.5 | Copper Nickel | 23 | NA NA | 20400 | 14.910 | mg/kg |
| CC44-003 | 750173.210 | | | | | 56 | NA NA | 613000 | 48.940 | mg/kg |
| CC44-003 | 750173.210 | 2083266.818 | 0.0 | 0.5 | Strontium | | NA NA | 300 | 2.253 | |
| CC44-003 | 750173.210 | 2083266.818 | 0.0 | 0.5 | Uranium-234 | 4.687 | | 8 | 0.094 | pCi/g |
| CC44-003 | 750173.210 | 2083266.818 | 0.0 | 0.5 | Uranium-235 | 0.225 | NA NA | 351 | 2.000 | pCi/g |
| CC44-003 | 750173.210 | 2083266.818 | 0.0 | 0.5 | Uranium-238 | 4.687 | NA | | | pCi/g |
| CC44-003 | 750173.210 | 2083266.818 | 0.0 | 0.5 | Zinc | 130 | NA | 307000 | 73.760 | mg/kg |
| CD43-001-01 | 750075.979 | 2083537.001 | 6.5 | 8.5 | Uranium-235 | 0.121 | NA | . 8 | 0.120 | pCi/g |
| CD43-002-01 | 750080.988 | 2083519.093 | 0.5 | 2.5 | Toluene | 12.7 | 5.02 | 31300000 | NA | μg/kg |
| CD43-002-01 | 750080.988 | 2083519.093 | 0.5 | 2.5 | Uranium-234 | 4.319 | NA NA | 300 | 2.640 | pCi/g |
| CD43-002-01 | 750080.988 | 2083519.093 | 0.5 | 2.5 | Uranium-235 | 0.242 | NA | 8 | 0.120 | pCi/g |
| CD43-002-01 | 750080.988 | 2083519.093 | 0.5 | 2.5 | Uranium-238 | 4.319 | NA | 351 | 1.490 | pCi/g |
| CD43-002-01 | 750080.988 | 2083519.093 | 0.5 | 2.5 | Xylene | 82.2 | 10 | 2040000 | NA | μg/kg |
| CD43-002-01 | 750080.988 | 2083519.093 | 6.5 | 8.5 | Ethylbenzene | 18.8 | 5.66 | 4250000 | NA | μg/kg |
| CD43-002-01 | 750080.988 | 2083519.093 | 6.5 | 8.5 | Toluene | 27.4 | 5.66 | 31300000 | NA_ | μg/kg |
| CD43-002-01 | 750080.988 | 2083519.093 | 6.5 | 8.5 | Uranium-235 | 0.162 | NA | 8 | 0.120 | pCi/g |
| CD43-002-01 | 750080.988 | 2083519.093 | 6.5 | 8.5 | Xylene | 116 | 11.3 | 2040000 | NA | μg/kg |
| CD43-003 | 750115.019 | 2083530.017 | 0.5 | 2.5 | Lead | 27 | NA | 1000 | 24.970 | mg/kg |
| CD43-003 | 750115.019 | 2083530.017 | 0.5 | 2.5 | Uranium-235 | 0.142 | NA | 8 | 0.120 | pCi/g |
| CD43-003 | 750115.019 | 2083530.017 | 0.5 | 2.5 | Xylene | 23.2 | 10.3 | 2040000 | NA | μg/kg |
| CD43-003 | 750115.019 | 2083530.017 | 6.5 | 8.5 | Arsenic | 15 | NA | 22.2 | 13.140 | mg/kg |
| CD43-004 | 750139.060 | 2083361.670 | 0.0 | 0.5 | Arsenic | 17.7 | NA | 22.2 | 10.090 | mg/kg |
| CD43-004 | 750139.060 | 2083361.670 | 0.0 | 0.5 | Barium | 801 | NA | 26400 | 141.260 | mg/kg |
| CD43-004 | 750139.060 | 2083361.670 | 0.0 | 0.5 | Chromium | 54.9 | NA | 268 | 16.990 | mg/kg |
| CD43-004 | 750139.060 | 2083361.670 | 0.0 | 0.5 | Cobalt | 12.7 | NA | 1550 | 10.910 | mg/kg |
| CD43-004 | 750139.060 | 2083361.670 | 0.0 | 0.5 | Iron | 41600 | NA | 307000 | 18037.000 | mg/kg |
| CD43-004 | 750139.060 | 2083361.670 | 0.0 | 0.5 | Manganese | 670 | NA | 3480 | 365.080 | mg/kg |

| | | | | | | 25.00 | | | | |
|---------------|------------|-------------|--------------------|------------------|-----------------|--------|-----------------|--|------------------|-------|
| | | | | | • • | | | | Background | |
| | | | Sample Starting | Sample Ending | | | | n e transition de la companya de la La companya de la co | Mean Plus Two | 1.00 |
| Ì | | | Depth | Depth | | | | , | Standard | |
| Location Code | Northing | Easting | (ft bgs) | (ft bgs) | Analyte | Result | RL | WRW AL | Deviations | Unit |
| CD43-004 | 750139.060 | 2083361.670 | 0.0 | 0.5 | Nickel | 59.8 | NA | 20400 | 14.910 | mg/kg |
| CD43-004 | 750139.060 | 2083361.670 | 0.0 | 0.5 | Strontium | 216 | NA | 613000 | 48.940 | mg/kg |
| CD43-004 | 750139.060 | 2083361.670 | 0.0 | 0.5 | Uranium-235 | 0.194 | NA · | 8 | 0.094 | pCi/g |
| CD43-004 | 750139.060 | 2083361.670 | 0.0 | 0.5 | Vanadium | 111 | NA | 7150 | 45.590 | mg/kg |
| CD43-004 | 750139.060 | 2083361.670 | 0.0 | 0.5 | Zinc | 86.1 | NA | 307000 | 73.760 | mg/kg |
| CD43-005 | 750103.940 | 2083461.890 | 0.0 | 0.5 | Uranium-234 | 5.139 | NA | 300 | 2.253 | pCi/g |
| CD43-005 | 750103.940 | 2083461.890 | 0.0 | 0.5 | Uranium-235 | 0.245 | NA | 8 | 0.094 | pCi/g |
| CD43-005 | 750103.940 | 2083461.890 | 0.0 | 0.5 | Uranium-238 | 5.139 | NA | 351 | 2.000 | pCi/g |
| CD43-006 | 750159.960 | 2083449.840 | 0.0 | 0.5 | Uranium-235 | 0.127 | · NA | 8 | 0.094 | pCi/g |
| CD43-007 | 750116.480 | 2083377.120 | 0.0 | 0.5 | Cobalt | 17 | NA | 1550 | 10.910 | mg/kg |
| CD43-007 | 750116.480 | 2083377.120 | 0.0 | 0.5 | Copper | 39 | NA | 40900 | 18.060 | mg/kg |
| CD43-007 | 750116.480 | 2083377.120 | 0.0 | 0.5 | Uranium-235 | 0.16 | NA | 8 | 0.094 | pCi/g |
| CD43-007 | 750116.480 | 2083377.120 | 0.5 | 1.0 | Uranium-234 | 3.724 | NA | 300 | 2.640 | pCi/g |
| CD43-007 | 750116.480 | 2083377.120 | 0.5 | 1.0 | Uranium-235 | 0.131 | NA | 8 | 0.120 | pCi/g |
| CD43-007 | 750116.480 | 2083377.120 | 0.5 | 1.0 | Uranium-238 | 3.724 | NA | 351 | 1.490 | pCi/g |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Arsenic | 19.7 | NA | 22.2 | 10.090 | mg/kg |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Barium | 909 | NA | 26400 | 141.260 | mg/kg |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Chromium | 44.2 | NA | 268 | 16.990 | mg/kg |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Cobalt | 13.4 | NA | 1550 | 10.910 | mg/kg |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Iron | 37300 | NA | 307000 | 18037.000 | mg/kg |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Manganese | 1280 | NA | 3480 | 365.080 | mg/kg |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Nickel | 49.7 | NA | 20400 | 14.910 | mg/kg |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Strontium | 222 | NA | 613000 | 48.940 | mg/kg |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Tin | 20.9 | NA | 613000 | 2.900 | mg/kg |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Uranium-235 | 0.192 | NA | 8 | 0.094 | pCi/g |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Uranium-238 | 2.105 | NA ⁻ | 351 | 2.000 | pCi/g |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Vanadium | 90.3 | NA | 7150 | 45.590 | mg/kg |
| CD43-008 | 750138.050 | 2083439.620 | 0.0 | 0.5 | Zinc | 122 | NA | 307000 | 73.760 | mg/kg |
| CD43-009 | 750153.480 | 2083502.470 | 1.2 | 1.6 | Trichloroethene | 2.3 | 0.92 | 19600 | NA | μg/kg |


Draft Closeout Report for IHSS Group 500-3

| | | | . C1- | Sa-mala | | | | | Background Mean Plus | |
|---------------|------------|-------------|--------------------|------------------|-------------------|--------|-------------|--------|-------------------------|---------|
| | | - | Sample Starting | Sample Ending | | | | | Two | |
| | | | Depth | Depth | | | | | Standard | |
| Location Code | Northing | Easting | (ft bgs) | (ft bgs) | Analyte | Result | RL | WRW AL | Deviations | Unit |
| CD43-009 | 750153.480 | 2083502.470 | 1.2 | 1.6 | Uranium-235 | 0.134 | NA | 8 | 0.120 | pÇi/g |
| CD43-010 | 750047.960 | 2083496.110 | 16.5 | 18.5 | Trichloroethene | 29.9 | 6.22 | 19600 | NA | μg/kg |
| CD43-010 | 750047.960 | 2083496.110 | 16.5 | 18.5 | Uranium-235 | 0.165 | NA | 8 | 0.120 | pCi/g |
| CD43-010 | 750047.960 | 2083496.110 | 16.5 | 18.5 | Uranium-238 | 2.008 | NA | 351 | 1.490 | pCi/g |
| CD43-010 | 750047.960 | 2083496.110 | 18.5 | 20.5 | Trichloroethene | 21 | 5.46 | 19600 | NA | μg/kg |
| CD43-010 | 750047.960 | 2083496.110 | 20.5 | 22.5 | Trichloroethene | 11.7 | 5.7 | 19600 | NA | μg/kg |
| CD43-010 | 750047.960 | 2083496.110 | 20.5 | 22.5 | Uranium-235 | 0.124 | NA | 8 | 0.120 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 6.5 | 8.5 | Americium-241 | 2.224 | ŅA | 76 | 0.020 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 6.5 | 8.5 | Plutonium-239/240 | 12.677 | . <i>NA</i> | 50 | 0.020 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 6.5 | 8.5 | Uranium-238 | 1.626 | NA | 351 | 1.490 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 8.5 | 10.2 | Americium-241 | 0.5132 | NA | 76 - | 0.020 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 8.5 | 10.2 | Plutonium-239/240 | 2.925 | NA NA | 50 | 0.020 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 10.5 | 12.5 | Americium-241 | 1.05 | NA | - 76 | 0.020 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 10.5 | 12.5 | Plutonium-239/240 | 5.985 | NA | 50 | 0.020 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 10.5 | 12.5 | Uranium-235 | 0.224 | NA | 8 | 0.120 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 10.5 | 12.5 | Uranium-238 | 1.554 | NA | 351 | 1.490 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 12.5 | 14.5 | Uranium-235 | 0.139 | NA_ | 8 . | 0.120 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 14.5 | 16.5 | Americium-241 | 0.609 | NA | 76 | 0.020 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 14.5 | 16.5 | Plutonium-239/240 | 3.470 | NA | 50 | 0.020 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 16.5 | 18.5 | Arsenic | 15 | NA | 22.2 | 13.140 | mg/kg |
| CD43-013 | 750068.854 | 2083521.830 | 16.5 | 18.5 | Uranium-234 | 3.284 | NA | 300 | 2.640 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 16.5 | 18.5 | Uranium-235 | 0.180 | NA | 8 | 0.120 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 16.5 | 18.5 | Uranium-238 | 3.284 | NA | 351 | 1.490 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 18.5 | 20.5 | Uranium-234 | 4.637 | NA | 300 | 2.640 | ∙ pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 18.5 | 20.5 | Uranium-235 | 0.210 | NA | 8 | 0.120 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 18.5 | 20.5 | Uranium-238 | 4.637 | NA | 351 | 1.490 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 20.5 | 22.5 | Uranium-234 | 3.439 | NA | 300 | 2.640 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 20.5 | 22.5 | Uranium-235 | 0.167 | NA | 8 | 0.120 | pCi/g |
| CD43-013 | 750068.854 | 2083521.830 | 20.5 | 22.5 | Uranium-238 | 3.439 | NA | 351 | 1.490 | pCi/g |


Draft Closeout Report for IHSS Group 500-3

| | | | Sample Starting Depth | Sample Ending Depth | | | | | Background Mean Plus Two Standard | |
|---------------|------------|-------------|-----------------------------|---------------------------|--------------------|--------|------|-----------|--|-------|
| Location Code | Northing | Easting | (ft bgs) | (ft bgs) | Analyte | Result | RL | WRW AL | Deviations | Unit |
| CD43-014 | 750098.092 | 2083380.070 | 0.0 | 0.5 | Copper | 28 | NA | 40900 | 18.060 | mg/kg |
| CD43-014 | 750098.092 | 2083380.070 | 0.0 | 0.5 | Uranium-234 | 4.668 | NA | 300 | 2.253 | pCi/g |
| CD43-014 | 750098.092 | 2083380.070 | 0.0 | 0.5 | Uranium-235 | 0.171 | NA | 8 | 0.094 | pCi/g |
| CD43-014 | 750098.092 | 2083380.070 | 0.0 | 0.5 | Uranium-238 | 4.668 | NA | 351 | 2.000 | pCi/g |
| CD43-015 | 750137.050 | 2083467.610 | 0.0 | 0.5 | Acetone | 17 | 5.8 | 102000000 | NA | μg/kg |
| CD43-015 | 750137.050 | 2083467.610 | 0.0 | 0.5 | Antimony | 0.53 | NA | 409 | 0.470 | mg/kg |
| CD43-015 | 750137.050 | 2083467.610 | 0.0 | 0.5 | Cobalt | 26 | NA . | 1550 | 10.910 | mg/kg |
| CD43-015 | 750137.050 | 2083467.610 | 0.0 | 0.5 | Copper | 67 | NA | 40900 | 18.060 | mg/kg |
| CD43-015 | 750137.050 | 2083467.610 | 0.0 | 0.5 | Methylene chloride | 2.6 | 1 | 2530000 | NA | μg/kg |
| CD43-015 | 750137.050 | 2083467.610 | 0.0 | 0.5 | Plutonium-239/240 | 0.138 | NA | 50 | 0.066 | pCi/g |
| CD43-015 | 750137.050 | 2083467.610 | 0.0 | 0.5 | Strontium | 60 | NA | 613000 | 48.940 | mg/kg |
| CD43-015 | 750137.050 | 2083467.610 | 0.0 | 0.5 | Tin | 6.8 | NA | 613000 | 2.900 | mg/kg |
| CD43-016 | 750098.926 | 2083498.975 | 0.0 | 0.5 | Uranium-234 | 3.84 | NA | 300 | 2.253 | pCi/g |
| CD43-016 | 750098.926 | 2083498.975 | 0.0 | 0.5 | Uranium-235 | 0.245 | NA | 8 | 0.094 | pCi/g |
| CD43-016 | 750098.926 | 2083498.975 | 0.0 | 0.5 | Uranium-238 | 3.84 | NA | .351 | 2.000 | pCi/g |
| CD43-016 | 750098.926 | 2083498.975 | 0.5 | 2.5 | Uranium-234 | 4.627 | NA | 300 | 2.640 | pCi/g |
| CD43-016 | 750098.926 | 2083498.975 | 0.5 | 2.5 | Uranium-235 | 0.217 | NA | 8 | 0.120 | pCi/g |
| CD43-016 | 750098.926 | 2083498.975 | 0.5 | 2.5 | Uranium-238 | 4.627 | NA | 351 | 1.490 | pCi/g |
| CD43-016 | 750098.926 | 2083498.975 | 6.5 | 8.5 | Uranium-235 | 0.183 | NA | 8 | 0.120 | pCi/g |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Aluminum | 22000 | NA | 228000 | 16902.000 | mg/kg |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Antimony . | 0.58 | NA | 409 | 0.470 | mg/kg |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Beryllium | 1.3 | NA | 921 | 0.966 | mg/kg |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Chromium | 26 | NA | 268 | 16.990 | mg/kg |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Cobalt | 11 | NA | 1550 | 10.910 | mg/kg |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | . Iron. | 19000 | NA | 307000 | 18037.000 | mg/kg |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Lithium | 13 | NA | 20400 | 11.550 | mg/kg |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Manganese | 430 | NA | 3480 | 365.080 | mg/kg |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Nickel | 25 | NA | 20400 | 14.910 | mg/kg |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Uranium-234 | 3.333 | NA | 300 | 2.253 | pCi/g |





| | | | 医多种皮质炎 医 | | | 138(38) 784 4 . | | September 1881 | Background | |
|----------------------|------------|-------------|----------|----------|----------------------|-----------------|-------|----------------|------------|-------|
| | | | Sample | Sample | | | | | Mean Plus | |
| | | | Starting | Ending | | | | | Two | |
| | | | Depth | Depth | | | | | Standard | |
| Location Code | Northing | Easting | (ft bgs) | (ft bgs) | Analyte | Result | RL | WRW AL | Deviations | Unit |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Uranium-235 | 0.191 | NA | 8 | 0.094 | pCi/g |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Uranium-238 | 3.333 | NA | 351 | 2.000 | pCi/g |
| CD43-017 | 750115.480 | 2083433.140 | 0.0 | 0.5 | Xylene | 39.9 | 10.4 | 2040000 | NA | μg/kg |
| CD43-017 | 750115.480 | 2083433.140 | 0.5 | 0.8 | 4-Methyl-2-pentanone | 62.6 | 55.9 | 16400000 | NA NA | μg/kg |
| CD43-017 | 750115.480 | 2083433.140 | 0.5 | 0.8 | Uranium-238 | 1.634 | NA | 351 | 1.490 | pCi/g |
| CD43-017 | 750115.480 | 2083433.140 | 0.5 | 0.8 | Xylene | 41.5 | 11.1 | 2040000 | NA | μg/kg |
| CD43-018 | 750097.401 | 2083514.302 | 6.5 | 8.5 | Chromium | 140 | NA | 268 | 68.270 | mg/kg |
| CD43-021 | 750083.639 | 2083529.285 | 15.0 | 16.0 | Uranium-235 | 0.149 | NA | . 8 | 0.120 | pCi/g |
| CD43-022 | 750034.797 | 2083549.844 | 17.0 | 18.0 | Americium-241 | 1.363 | NA | 76 | 0.020 | pCi/g |
| CD43-022 | 750034.797 | 2083549.844 | 17.0 | - 18.0 | Plutonium-239/240 | 7.769 | NA NA | 50 | 0.020 | pCi/g |
| CD43-022 | 750034.797 | 2083549.844 | 17.0 | 18.0 | Uranium-235 | 0.173 | NA | 8 | 0.120 | pCi/g |
| CD43-023 | 750048.825 | 2083501.976 | 17.0 | 18.0 | Uranium-235 | 0.131 | NA | 8 | 0.120 | pCi/g |
| CD43-024 | 750059.305 | 2083539.531 | 20.0 | 21.0 | Americium-241 | 1.002 | NA | 76 | 0.020 | pCi/g |
| CD43-024 | 750059.305 | 2083539.531 | 20.0 | 21.0 | Plutonium-239/240 | 5.711 | NA | 50 | 0.020 | pCi/g |
| CD43-024 | 750059.305 | 2083539.531 | 20.0 | 21.0 | Uranium-238 | 1.675 | NA_ | 351 | 1.490 | pCi/g |
| CD43-025 | 750036.850 | 2083505.458 | 0.0 | 0.5 | Americium-241 | 0.184 | NA | 76 | 0.020 | pCi/g |
| CD43-025 | 750036.850 | 2083505.458 | 0.0 | 0.5 | Plutonium-239/240 | 1.13 | NA | 50 | 0.020_ | pCi/g |
| CD43-026 | 750026.414 | 2083507.211 | 0.0 | 0.5 | Uranium-234 | 4.388 | NA_ | 300 | 2.640 | pCi/g |
| CD43-026 | 750026.414 | 2083507.211 | 0.0 | 0.5 | Uranium-235 | 0.129 | NA | 8 | 0.120 | pCi/g |
| CD43-026 | 750026.414 | 2083507.211 | 0.0 | 0.5 | Uranium-238 | 4.388 | NA | 351 | 1.490 | pCi/g |
| CD43-027 | 750037.133 | 2083513.661 | 0.0 | 0.5 | Uranium-234 | 4.328 | NA | 300 | 2.640 | pCi/g |
| CD43-027 | 750037.133 | 2083513.661 | 0.0 | 0.5 | Uranium-235 | 0.269 | NA | 8 | 0.120 | pCi/g |
| CD43-027 | 750037.133 | 2083513.661 | 0.0 | 0.5 | Uranium-238 | 4.328 | NA | 351 | 1.490 | pCi/g |
| CD43-028 | 750025.414 | 2083513.554 | 0.0 | 0.5 | Uranium-234 | 2.749 | NA | 300 | 2.640 | pCi/g |
| CD43-028 | 750025.414 | 2083513.554 | 0.0 | 0.5 | Uranium-235 | 0.202 | NA | 8 | 0.120 | pCi/g |
| CD43-028 | 750025.414 | 2083513.554 | 0.0 | 0.5 | Uranium-238 | 2.749 | NA | 351 | 1.490 | pCi/g |
| CD43-029 | 750060.129 | 2083480.533 | 20.0 | 22.0 | Uranium-238 | 1.624 | NA | 351 | 1.490 | pCi/g |
| CD43-030 | 750137.676 | 2083282.648 | 12.0 | 12.5 | Barium | 699 | NA | 26400 | 289.380 | mg/kg |
| CD43-031 | 750134.355 | 2083384.698 | 12.0 | 12.5 | Barium | 739 | NA | 26400 | 289.380 | mg/kg |



| | | | , | | | | | | Background | 7.7 |
|----------------------|------------|-------------|----------|----------|--------------------|---------|-------|-----------|-------------------|-------|
| | _ | | Sample | Sample | • | | | | Mean Plus | |
| | | | Starting | Ending | | | | | Two | |
| | | | Depth | Depth | t | • | | | Standard | |
| Location Code | Northing | Easting | (ft bgs) | (ft bgs) | Analyte | Result | RL | WRW AL | Deviations | Unit |
| CD43-031 | 750134.355 | 2083384.698 | 12.0 | 12.5 | Iron | 42700 | NA | 307000 | 41046.520 | mg/kg |
| CD43-031 | 750134.355 | 2083384.698 | 12.0 | 12.5 | Uranium-235 | 0.186 | NA | 8 | 0.120 | pCi/g |
| CD43-032 | 750134.796 | 2083458.820 | 12.0 | 12.5 | Arsenic | 16.5 | NA | 22.2 | 13.140 | mg/kg |
| CD43-032 | 750134.796 | 2083458.820 | 12.0 | 12.5 | Barium | 751 | NA | 26400 | 289.380 | mg/kg |
| CD43-032 | 750134.796 | 2083458.820 | 12.0 | 12.5 | Iron | 48200 | NA | 307000 | 41046.520 | mg/kg |
| CD43-032 | 750134.796 | 2083458.820 | 12.0 | 12.5 | Vanadium | 99.5 | NA | 7150 | 88.490 | mg/kg |
| CD43-035 | 750199.742 | 2083478.123 | 2.0 | 2.3 | Uranium-235 | 0.125 | NA | 8 | 0.120 | pCi/g |
| CD43-036 | 750198.434 | 2083489.273 | 3.0 | 3.3 | Americium-241 | 1.159 | NA | 76 | 0.020 | pCi/g |
| CD43-036 | 750198.434 | 2083489.273 | 3.0 | 3.3 | Plutonium-239/240 | 6.606 | NA | 50 | 0.020 | pCi/g |
| CD43-036 | 750198.434 | 2083489.273 | 3.0 | 3.3 | Uranium-235 | 0.143 | NA | 8 | 0.120 | pCi/g |
| CD43-037 | 750088.960 | 2083519.330 | 8.0 | 8.3 | Americium-241 | 1.51 | NA | 76 | 0.020 | pCi/g |
| CD43-037 | 750088.960 | 2083519.330 | 8.0 | 8.3 | Plutonium-239/240 | 8.607 | NA | 50 | 0.020 | pCi/g |
| CD43-038 | 750197.160 | 2083459.436 | 0.0 | 4.0 | Americium-241 | 0.218 | NA | 76 | 0.020 | pCi/g |
| CD43-038 | 750197.160 | 2083459.436 | 0.0 | 4.0 | Plutonium-239/240 | 1.26 | . NA | 50 | 0.020 | pCi/g |
| CD43-039 | 750193.377 | 2083459.532 | 4.0 | 4.3 | Americium-241 | 2.32 | NA NA | 76 | 0.020 | pCi/g |
| CD43-039 | 750193.377 | 2083459.532 | 4.0 | 4.3 | Plutonium-239/240 | 12 | NA | 50 | 0.020 | pCi/g |
| CD43-041 | 750192.254 | 2083466.888 | 0.0 | 4.0 | Americium-241 | 0.306 | NA NA | 76 | 0.020 | pCi/g |
| CD43-041 | 750192.254 | 2083466.888 | 0.0 | 4.0 | Plutonium-239/240 | 2.57 | NA | 50 | 0.020 | pCi/g |
| CD43-042 | 750190.131 | 2083451.486 | 0.0 | 4.5 | Americium-241 | 2.97 | NA . | 76 | 0.020 | pCi/g |
| CD43-042 | 750190.131 | 2083451.486 | 0.0 | 4.5 | Plutonium-239/240 | 17.6 | NA | 50 | 0.020 | pCi/g |
| CD43-044 | 750182.935 | 2083455.786 | 2.5 | 5.0 | Americium-241 | 1.59 | NA | 76 | 0.020 | pCi/g |
| CD43-044 | 750182.935 | 2083455.786 | 2.5 | 5.0 | Plutonium-239/240 | 10.3 | NA | 50 | 0.020 | pCi/g |
| CD43-054 | 750102.153 | 2083516.970 | 7.5 | 7.8 | Americium-241 | 317.5 | NA | 76 | 0.020 | pCi/g |
| CD43-054 | 750102.153 | 2083516.970 | 7.5 | 7.8 | Plutonium-239/240 | 1809.75 | NA | 50 | 0.020 | pCi/g |
| CD43-055 | 750099.934 | 2083519.552 | 9.0 | 9.5 | 2-Butanone | 1.9 | 1.8 | 192000000 | NA | μg/kg |
| CD43-055 | 750099.934 | 2083519.552 | 9.0 | 9.5 | Acetone | 11 | 1.6 | 102000000 | NA | μg/kg |
| CD43-055 | 750099.934 | 2083519.552 | 9.0 | 9.5 | Americium-241 | 1.64 | NA | 76 | 0.020 | pCi/g |
| CD43-055 | 750099.934 | 2083519.552 | 9.0 | 9.5 | Ethylbenzene | 0.31 | 0.1 | 4250000 | NA | μg/kg |
| CD43-055 | 750099.934 | 2083519.552 | 9.0 | 9.5 | Methylene chloride | 2.4 | 0.36 | 2530000 | NA | μg/kg |

Draft Closeout Report for IHSS Group 500-3

| | | | Sample Starting | Sample Ending Depth | | | | | Background Mean Plus Two Standard | |
|---------------|------------|-------------|--------------------|---------------------------|------------------------|--------|-------|-----------|--|-------|
| Location Code | Northing | Easting | Depth (ft bgs) | (ft bgs) | Analyte | Result | RL | WRW AL | Deviations | Unit |
| CD43-055 | 750099.934 | 2083519.552 | 9.0 | 9.5 | Plutonium-239/240 | 12 | NA | 50 | 0.020 | pCi/g |
| CD43-055 | 750099,934 | 2083519.552 | 9.0 | 9.5 | Styrene | 0.099 | 0.081 | 123000000 | NA | μg/kg |
| CD43-055 | 750099.934 | 2083519.552 | 9.0 | 9.5 | Xylene | 1.4 | 0.035 | 2040000 | NA | μg/kg |
| CD44-001 | 750172.090 | 2083532.417 | 0.0 | 0.5 | Aluminum | 17000 | NA | 228000 | 16902.000 | mg/kg |
| CD44-001 | 750172.090 | 2083532.417 | 0.0 | 0.5 | Uranium-234 | 3.975 | NA | 300 | 2.253 | pCi/g |
| CD44-001 | 750172.090 | 2083532.417 | 0.0 | 0.5 | Uranium-235 | 0.242 | NA | · 8 | 0.094 | pCi/g |
| CD44-001 | 750172.090 | 2083532.417 | 0.0 | 0.5 | Uranium-238 | 3.975 | NA | 351 | 2.000 | pCi/g |
| CD44-001 | 750172.090 | 2083532.417 | 0.5 | 2.5 | Uranium-234 | 4.602 | NA . | 300 | 2.640 | pCi/g |
| CD44-001 | 750172.090 | 2083532.417 | 0.5 | 2.5 | Uranium-235 | 0.209 | NA | 8 | 0.120 | pCi/g |
| CD44-001 | 750172.090 | 2083532.417 | 0.5 | 2.5 | Uranium-238 | 4.602 | NA | 351 | 1.490 | pCi/g |
| CD44-002 | 750174.950 | 2083353.140 | 0.0 | 0.5 | Uranium-234 | 3.552· | NA | 300 | 2.253 | pCi/g |
| CD44-002 | 750174.950 | 2083353.140 | 0.0 | 0.5 | Uranium-235 | 0.191 | NA | 8 | 0.094 | pCi/g |
| CD44-002 | 750174.950 | 2083353.140 | 0.0 | 0.5 | Uranium-238 | 3.552 | NA | 351 | 2.000 | pCi/g |
| CD44-002 | 750174.950 | 2083353.140 | 0.0 | 0.5 | Xylene | 20.6 | 10.5 | 2040000 | NA | μg/kg |
| CD44-002 | 750174.950 | 2083353.140 | 0.5 | 1.0 | Ethylbenzene | 8.91 | 5.49 | 4250000 | NA | μg/kg |
| CD44-002 | 750174.950 | 2083353.140 | 0.5 | 1.0 | Xylene | 72.9 | 11 | 2040000 | NA | μg/kg |
| CD44-003 | 750187.640 | 2083380.890 | 0.0 | 0.5 | Uranium-234 | 2.946 | NA | 300 | 2.253 | pCi/g |
| CD44-003 | 750187.640 | 2083380.890 | 0.0 | 0.5 | Uranium-235 | 0.249 | NA | 8 | 0.094 | pCi/g |
| CD44-003 | 750187.640 | 2083380.890 | 0.0 | 0.5 | Uranium-238 | 2.946 | NA | 351 | 2.000 | pCi/g |
| CD44-003 | 750187.640 | 2083380.890 | 0.5 | 1.0 | Uranium-234 | 4.635 | NA | 300 | 2.640 | pCi/g |
| CD44-003 | 750187.640 | 2083380.890 | 0.5 | 1.0 | Uranium-235 | 0.165 | NA | 8 | 0.120 | pCi/g |
| CD44-003 | 750187.640 | 2083380.890 | 0.5 | 1.0 | Uranium-238 | 4.635 | NA | 351 | 1.490 | pCi/g |
| CD44-005 | 750184.640 | 2083459.240 | 0.0 | 0.5 | 1,2,4-Trichlorobenzene | 1 | 0.76 | 9230000 | NA | μg/kg |
| CD44-005 | 750184.640 | 2083459.240 | 0.0 | 0.5 | 4-Methyl-2-pentanone | 5.1 | 4.2 | 16400000 | NA | μg/kg |
| CD44-005 | 750184.640 | 2083459.240 | 0.0 | 0.5 | Acetone | 18 | 4.9 | 102000000 | NA | μg/kg |
| CD44-005 | 750184.640 | 2083459.240 | 0.0 | 0.5 | Americium-241 | 1200 | NA | 76 | 0.023 | pCi/g |
| CD44-005 | 750184.640 | 2083459.240 | 0.0 | 0.5 | Copper | 28 | NA | 40900 | 18.060 | mg/kg |
| CD44-005 | 750184.640 | 2083459.240 | 0.0 | 0.5 | Naphthalene | 1.8 | 0.92 | 3090000 | NA | μg/kg |
| CD44-005 | 750184.640 | 2083459.240 | 0.0 | 0.5 | Plutonium-239/240 | 8130 | NA | 50 | 0.066 | pCi/g |

Draft Closeout Report for IHSS Group 500-3

| | | | Sample Starting Depth | Sample Ending Depth | | | | | Background Mean Plus Two Standard | |
|----------------------|------------|-------------|-----------------------------|---------------------------|-------------------|---------|-------------|---------|--|-------|
| Location Code | Northing | Easting | (ft bgs) | (ft bgs) | Analyte | Result | RL | WRW AL | Deviations | Unit |
| CD44-005 | 750184.640 | 2083459.240 | 0.0 | 0.5 | Trichloroethene | 2.3 | 0.93 | 19600 | NA | μg/kg |
| CD44-005 | 750184.640 | 2083459.240 | 0.0 | 0.5 | Uranium-234 | 3.11 | NA . | 300 | 2.253 | pCi/g |
| CD44-005 | 750184.640 | 2083459.240 | 0.0 | 0.5 | Xylene | 4.3 | 3 | 2040000 | NA | μg/kg |
| CD44-006 | 750147.076 | 2083455.714 | 4.0 | 4.3 | Plutonium-239/240 | 0.486 | NA | 50 | 0.020 | pCi/g |
| CD44-007 | 750156.945 | 2083470.888 | 4.0 | 4.3 | Uranium-235 | 0.194 | NA | 8 | 0.120 | pCi/g |
| CD44-007 | 750156.945 | 2083470.888 | 4.0 | 4.3 | Uranium-238 | 2.33 | NA | 351 | 1.490 | pCi/g |
| CD44-008 | 750141.180 | 2083472.109 | 4.0 | 4,3 | Uranium-234 | 3.156 | NA | 300 | 2.640 | pCi/g |
| CD44-008 | 750141.180 | 2083472.109 | 4.0 | 4.3 | Uranium-235 | 0.151 | NA | 8 | 0.120 | pCi/g |
| CD44-008 | 750141.180 | 2083472.109 | 4.0 | 4.3 | Uranium-238 | 3.156 | NA | 351 | 1.490 | pCi/g |
| CD44-009 | 750125.190 | 2083465.114 | 5.0 | 5.3 | Americium-241 | 10.62 | NA | 76 | 0.020 | pCi/g |
| CD44-009 | 750125.190 | 2083465.114 | 5.0 | 5.3 | Plutonium-239/240 | 60.534 | NA | 50 | 0.020 | pCi/g |
| CD44-009 | 750125.190 | 2083465.114 | 5.0 | 5.3 | Uranium-235 | 0.192 | NA | 8 | 0.120 | pCi/g |
| CD44-009 | 750125.190 | 2083465.114 | 5.0 | 5.3 | Uranium-238 | 2.236 | NA | 351 | 1.490 | pCi/g |
| CD44-010 | 750125.622 | 2083431.811 | 5.0 | 5.3 | Uranium-234 | 3.27 | • <i>NA</i> | 300 | 2.640 | pCi/g |
| CD44-010 | 750125.622 | 2083431.811 | 5.0 | 5.3 | Uranium-235 | 0.162 | NA | 8 | 0.120 | pCi/g |
| CD44-010 | 750125.622 | 2083431.811 | 5.0 | 5.3 | Uranium-238 | 3.27 | NA | 351 | 1.490 | pCi/g |
| CD44-011 | 750127.319 | 2083374.294 | 5.0 | 5.3 | Uranium-235 | 0.141 | NA | 8 | 0.120 | pCi/g |
| CD44-012 | 750126.916 | 2083466.281 | 9.0 | 9.3 | Americium-241 | 13.1 | NA | 76 | 0.020 | pCi/g |
| CD44-012 | 750126.916 | 2083466.281 | 9.0 | 9.3 | Plutonium-239/240 | 74.67 | NA | 50 | 0.020 | pCi/g |
| CD44-013 | 750124.718 | 2083467.964 | 9.0 | 9.3 | Americium-241 | 1.3 | NA | 76 | 0.020 | pCi/g |
| CD44-013 | 750124.718 | 2083467.964 | 9.0 | 9.3 | Plutonium-239/240 | 5.7 | NA | 50 | 0.020 | pCi/g |
| CD44-014 | 750122.689 | 2083466.845 | 9.0 | 9.3 | Americium-241 | 0.122 | NA | 76 | 0.020 | pCi/g |
| CD44-014 | 750122.689 | 2083466.845 | 9.0 | 9.3 | Plutonium-239/240 | 0.21 | NA | 50 | 0.020 | pCi/g |
| CD44-015 | 750124.613 | 2083461.325 | 9.0 | 9.3 | Americium-241 | 27.69 | NA | 76 | 0.020 | pCi/g |
| CD44-015 | 750124.613 | 2083461.325 | 9.0 | 9.3 | Plutonium-239/240 | 157.833 | NA | 50 | 0.020 | pCi/g |
| CD44-015 | 750124.613 | 2083461.325 | 9.0 | 9.3 | Uranium-234 | 4.631 | NA | 300 | 2.640 | pCi/g |
| CD44-015 | 750124.613 | 2083461.325 | 9.0 | 9.3 | Uranium-238 | 4.631 | NA | 351 | 1.490 | pCi/g |
| CD44-016 | 750124.973 | 2083466.293 | 9.0 | 9.3 | Americium-241 | 3.06 | NA | 76 | 0.020 | pCi/g |
| CD44-016 | 750124.973 | 2083466.293 | 9.0 | 9.3 | Plutonium-239/240 | 18.5 | NA | 50 | 0.020 | pCi/g |

Draft Closeout Report for IHSS Group 500-3

| | | | | | | | | | | | | | | _ | | | | | | | | | | | | . , | | | | T | |
|-------------------------|----------|------------------------|---------------|-------------------|---------------|-------------------|-------------|-------------|--------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|--------------------|-------------|
| | | Unit | pCi/g | pCi/g | pCi/g | pCi/g | pCi/g | pCi/g | μg/kg | μg/kg | pCi/g | ug/kg | pCi/g | µg/kg | µg/kg | mg/kg | mg/kg | mg/kg | mg/kg | mg/kg | µg/kg | mg/kg |
| Background Mean Plus | Two | Standard Deviations | 0.020 | 0.020 | 0.020 | 0.020 | 0.120 | 1.490 | NA | NA | 0.120 | NA | 0.120 | 0.120 | 0.120 | 2.640 | 0.120 | 1.490 | 2.640 | 0.120 | 1.490 | 0.120 | NA | NA | 16902.000 | 141.260 | 996'0 | 16.990 | 18.060 | NA | 14.910 |
| | | WRW AL | 92 | 0\$ | 91 | 95 | 8 | 351 | 4250000 | 31300000 | 8 | 2040000 | 8 | 8 | 8 | 300 | 8 | 351 | 300 | 8 | 351 | 8 | 3090000 | 102000000 | 228000 | 26400 | 921 | 268 | 40900 | 2530000 | 20400 |
| | | RL | NA | NA | NA | NA | NA | NA | 5.83 | 5.83 | NA | 11.7 | NA | 5.47 | 5.8 | NA | NA | NA | NA | NA | 1 | NA |
| | | Result | 3.3 | 10 | 5.7 | 20.9 | 0.141 | 1.817 | 6.46 | 6.91 | 0.185 | 41.7 | 0.159 | 0.175 | 0.152 | 4.585 | 0.240 | 4.585 | 4.066 | 0.175 | 4.066 | 0.128 | 29.7 | 14 | 20000 | 180 | 1.6 | 23 | 99 | 2.2 | 20 |
| | * · | Analyte | Americium-241 | Plutonium-239/240 | Americium-241 | Plutonium-239/240 | Uranium-235 | Uranium-238 | Ethylbenzene | Toluene | Uranium-235 | Xylene | Uranium-235 | Uranium-235 | Uranium-235 | Uranium-234 | Uranium-235 | Uranium-238 | Uranium-234 | Uranium-235 | Uranium-238 | Uranium-235 | Naphthalene | Acetone | Aluminum | Barium | Beryllium | Chromium | Copper | Methylene chloride | Nickel |
| Sample | Ending | Depth (ft bgs) | 11.3 | 11.3 | 11.3 | 11.3 | 7.1 | 7.1 | 10.1 | 10.1 | 10.1 | 10.1 | 11.5 | 15.8 | 18.5 | 20.5 | 20.5 | 20.5 | 22.4 | 22.4 | 22.4 | 0.5 | 2.5 | 0.5 | 0.5 | 0.5 | 0.5 | 0.5 | 0.5 | 0.5 | 0.5 |
| Sample | Starting | Depth (ft bgs) | 11.0 | 11.0 | 11.0 | 11.0 | 6.5 | 6.5 | 8.5 | 8.5 | 8.5 | 8.5 | 10.5 | 14.7 | 16.5 | 18.5 | 18.5 | 18.5 | 20.5 | 20.5 | 20.5 | 0.0 | 0.5 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| | | Easting | 2083464.618 | 2083464.618 | 2083458.306 | 2083458.306 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083555.328 | 2083546.442 | 2083546.442 | 2083541.000 | 2083541.000 | 2083541.000 | 2083541.000 | 2083541.000 | 2083541.000 | 2083541.000 | 2083541.000 |
| | | Northing | 750126.729 | 750126.729 | 750125.263 | 750125.263 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750054.497 | 750149.154 | 750149.154 | 750053.000 | 750053.000 | 750053.000 | 750053.000 | 750053.000 | 750053.000 | 750053.000 | 750053.000 |
| | | Location Code | CD44-017 | CD44-017 | CD44-018 | CD44-018 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-000 | CE43-001 | CE43-001 | CE43-002 | CE43-002 |

Draft Closeout Report for IHSS Group 500-3

| | | | Sample Starting | Sample Ending | | | | | Background Mean Plus Two | |
|---------------|------------|-------------|--------------------|-------------------|--------------------|--------|------|-----------|--------------------------------|-------|
| Location Code | Northing | Easting | Depth (ft bgs) | Depth (ft bgs) | Analyte | Result | RL. | WRW AL | Standard Deviations | Unit |
| CE43-002 | 750053.000 | 2083541.000 | 0.0 | 0.5 | Strontium | 97 | NA | 613000 | 48.940 | mg/kg |
| CE43-002 | 750053.000 | 2083541.000 | 0.0 | 0.5 | Vanadium | 78 | NA | 7150 | 45.590 | mg/kg |
| CE43-002 | 750053.000 | 2083541.000 | 0.5 | 1.5 | Acetone | 16 | 5.6 | 102000000 | NA - | μg/kg |
| CE43-002 | 750053.000 | 2083541.000 | 0.5 | 1.5 | Methylene chloride | 2 | 0.98 | 2530000 | , NA | μg/kg |
| CE43-002 | 750053.000 | 2083541.000 | 0.5 | 1.5 | Uranium-235 | 0.14 | NA | 8 | 0.120 | pCi/g |
| CE43-003 | 750068.022 | 2083534.546 | 19.5 | 20.5 | МСРР | 960 | NA | NA | NA | μg/kg |
| CE43-003 | 750068.022 | 2083534.546 | 19.5 | 20.5 | Naphthalene | 19 | 6.42 | 3090000 | NA | μg/kg |
| CE43-003 | 750068.022 | 2083534.546 | 19.5 | 20.5 | Xylene | 14.9 | 12.8 | 2040000 | NA | μg/kg |
| CE43-003 | 750068.022 | 2083534.546 | 21.5 | 22.5 | Ethylbenzene | 8.81 | 6.04 | 4250000 | NA | μg/kg |
| CE43-003 | 750068.022 | 2083534.546 | 21.5 | 22.5 | МСРР | 830 | NA | NA | NA | μg/kg |
| CE43-003 | 750068.022 | 2083534.546 | 21.5 | 22.5 | Toluene | 10.6 | 6.04 | 31300000 | NA NA | μg/kg |
| CE43-003 | 750068.022 | 2083534.546 | 21.5 | 22.5 | Xylene | 46.1 | 12.1 | 2040000 | NA | μg/kg |
| CE43-021 | 750075.377 | 2083513.984 | 12.0 | 13.0 | Americium-241 | 0.678 | NA | 76 | 0.020 | pCi/g |
| CE43-021 | 750075.377 | 2083513.984 | 12.0 | 13.0 | Plutonium-239/240 | 3.866 | NA | 50 | 0.020 | pCi/g |
| CE43-022 | 750075.377 | 2083513.984 | 8.0 | 9.0 | Americium-241 | 1.474 | NA | 76 | 0.020 | pCi/g |
| CE43-022 | 750075.377 | 2083513.984 | 8.0 | 9.0 | Plutonium-239/240 | 8.402 | NA | 50 | 0.020 | pCi/g |

Results exceeding the WRW AL are indicated in bold. Italics indicate results for plutonium-239/240 and uranium-234 that were calculated based on gamma spectroscopy (HPGe) results for other analytes.

Table 4
IHSS Group 500-3 Surface Soil Summary Statistics

| | Total Number of | | | | | Background Mean Plus Two Standard | | |
|--------------------|-----------------------|------------------------|-------------------|-------------------|-------|--|---|-------|
| Analyte | Samples | Detection Frequency | Average Result | Maximum Result | RL | Deviations 1 | WRW AL | Unit |
| 1,2,4- | Analyzeu | Frequency | · Mixesuit | Result | .142 | 20111110115 | *************************************** | |
| Trichlorobenzene | 22 | 4.5% | 1.000 | 1.000 | 0.760 | NA | 9230000 | μg/kg |
| 4-Methyl-2- | | | | | | | - | |
| pentanone | 22 | 4.5% | 5.100 | 5.100 | 4.200 | NA NA | 16400000 | μg/kg |
| Acetone | 22 | 13.6% | 16.333 | 18.000 | 5.500 | NA | 102000000 | μg/kg |
| Aluminum | 19 | 26.3% | 19400.000 | 22000.000 | NA | 16902.000 | 228000 | mg/kg |
| Americium-241 | 24 | 12.5% | 403.760 | 1200.000 | NA | 0.023 | 76 | pCi/g |
| Antimony | 22 | 13.6% | 0.530 | 0.580 | NA | 0.470 | 409 | mg/kg |
| Arsenic | 22 | 9.1% | 18.700 | 19.700 | NA | 10.090 | 22.2 | mg/kg |
| Barium | 22 | 18.2% | 651.750 | 909.000 | NA | 141.260 | 26400 | mg/kg |
| Beryllium | 19 | 21.1% | 1.300 | 1.600 | NA | 0.966 | 921 | mg/kg |
| Chromium | 22 | 36.4% | 29.313 | 54.900 | NA | 16.990 | 268 | mg/kg |
| Cobalt | 22 | 36.4% | 17.263 | 26.000 | NA | 10.910 | 1550 | mg/kg |
| Copper | 22 | 40.9% | 57.111 | 155.000 | NA | 18.060 | 40900 | mg/kg |
| Iron | 22 | 18.2% | 33400.000 | 41600.000 | NA | 18037.000 | 307000 | mg/kg |
| Lithium | 19 | 5.3% | 13.000 | 13.000 | NA | 11.550 | 20400 | mg/kg |
| Manganese | 22 | 18.2% | 751.750 | 1280.000 | NA | 365.080 | 3480 | mg/kg |
| Methylene chloride | 22 | 9.1% | 2.400 | 2.600 | 1.000 | NA | 2530000 | μg/kg |
| Naphthalene | 22 | 9.1% | 4.340 | 6.880 | 3.270 | NA | 3090000 | μg/kg |
| Nickel | 22 | 36.4% | 32.325 | 59.800 | NA | 14.910 | 20400 | mg/kg |
| Plutonium-239/240 | 24 | 16.7% | 2050.160 | 8130.000 | NA | 0.066 | 50 | pCi/g |
| Strontium | 22 | 27.3% | 149.500 | 246.000 | NA | 48.940 | 613000 | mg/kg |
| Tin | 22 | 18.2% | 16.175 | 30.400 | NA | 2.900 | 613000 | mg/kg |
| Trichloroethene | 22 | 4.5% | 2.300 | 2.300 | 0.930 | NA | 19600 | μg/kg |
| Uranium-234 | 24 | 50.0% | 3.728 | 5.139 | NA | 2.253 | 300 | pCi/g |
| Uranium-235 | 24 | 62.5% | 0.204 | 0.264 | NA | 0.094 | 8.0 | pCi/g |
| Uranium-238 | 24 | 50.0% | 3.644 | 5.139 | NA | 2.000 | 351 | pCi/g |
| Vanadium | 22 | 18.2% | 84.475 | 111.000 | NA | 45.590 | 7150 | mg/kg |
| Xylene | 22 | 22.7% | 20.420 | 39.900 | 9.120 | NA | 2040000 | μg/kg |
| Zinc | 22 | 18.2% | 103.200 | 130.000 | NA | 73.760 | 307000 | mg/kg |

Table 5
IHSS Group 500-3 Subsurface Soil Summary Statistics

| | Total | | | | | Background | | |
|-------------|----------|-----------|------------|---------|--------|------------|-----------|-------|
| 1. 1 | Number | | | | | Mean Plus | | |
| · · | of | - | <i>i</i> . | | | Two | · | |
| | Samples | Detection | Average | Maximum | | Standard | | |
| Analyte | Analyzed | Frequency | Result | Result | RL | Deviations | WRW AL | Unit |
| 2-Butanone | 54 | 1.9% | 1.900 | 1.900 | 1.800 | NA | 192000000 | μg/kg |
| 4-Methyl-2- | | | | | | , | | |
| pentanone | 54 | 1.9% | 62.600 | 62.600 | 55.900 | l NA | 16400000 | μg/kg |

| Analyte | Total Number of Samples Analyzed | Detection Frequency | Average Result | Maximum Result | RL | Background Mean Plus Two Standard Deviations | WRW AL | Unit |
|--------------------|--|------------------------|-------------------|-------------------|--------|--|-----------|-------|
| Acetone | 54 | 3.7% | 13.500 | 16.000 | 3.600 | NA | 102000000 | μg/kg |
| Americium-241 | 91_ | 29.7% | 14.967 | 317.500 | NA | 0.020 | 76 | pCi/g |
| Arsenic | 55 | 5.5% | 15.500 | 16.500 | NA | 13.140 | 22 | mg/kg |
| Barium | 55 | 5.5% | 729.667 | 751.000 | NA | 289.380 | 26400 | mg/kg |
| Chromium | 55 | 1.8% | 140.000 | 140.000 | NA | 68.270 | 268 | mg/kg |
| Ethylbenzene | 54 | 9.3% | 8.658 | 18.800 | 4.624 | ŅA | 4250000 | μg/kg |
| Iron | 55 | 3.6% | 45450.000 | 48200.000 | NA | 41046.520 | 307000 | mg/kg |
| Lead | 55 | 1.8% | 27.000 | 27.000 | NA | 24.970 | 1000 | mg/kg |
| Methylene chloride | 54 | 3.7% | 2.200 | 2.400 | 0.670 | NA | 2530000 | μg/kg |
| Naphthalene | 54 | 3.7% | 24.350 | 29.700 | 5.945 | NA | 3090000 | μg/kg |
| Plutonium-239/240 | 91 | 30.8% | 81.668 | 1809.750 | NA | 0.020 | 50 | pCi/g |
| Styrene | 54 | 1.9% | 0.099 | 0.099 | 0.081 | NA | 123000000 | μg/kg |
| Toluene | 54 | 7.4% | 14.403 | 27.400 | 5.638 | NA | 31300000 | μg/kg |
| Trichloroethene | 54 | 7.4% | 16.225 | 29.900 | 4.575 | NA | 19600 | μg/kg |
| Uranium-234 | 91 · | 20.9% | 4.013 | 4.637 | NA | 2.640 | 300 | pCi/g |
| Uranium-235 | 91 | 49.5% | 0.171 | 0.296 | NA | 0.120 | 8 | pCi/g |
| Uranium-238 | 91 | 30.8% | 3.312 | 4.637 | NA | 1.490 | 351 | pCi/g |
| Vanadium | 55 | 1.8% | 99.500 | 99.500 | NA | 88.490 | 7150 | mg/kg |
| Xylene | 54 | 20.4% | 42.675 | 116.000 | 10.172 | NA | 2040000 | μg/kg |

2.3 SORs

RFCA radionuclide SORs were calculated for soil at sampling locations in IHSS Group 500-3 using accelerated action soil data for samples up to 3 ft bgs. Radionuclide SOR calculations include americium-241, plutonium-239/240, uranium-234, uranium-235, and uranium-238, and SORs were calculated where any radionuclide result was greater than background means plus two standard deviations. Where HPGe-detection gamma spectroscopy was used for the analysis, the plutonium-239/240 activity was calculated as 5.7 times the measured americium-241 activity. Radionuclide SORs for characterization samples are presented in Table 6. SORs for confirmation samples are presented in Section 4.0. All radionuclide SORs were less than 1, except for the 0- to 0.5-ft sample from CD44-005, which had a radionuclide SOR over 85. Although radionuclide SORs were not tabulated for historical samples, a review of historical sampling data indicates none of the historical soil samples collected at IHSS Group 500-3 would have a radionuclide SOR greater than 1.

Nonradionuclide SORs were calculated for surface (0 to 0.5 ft bgs) soil samples. Only analytes detected above 10 percent of their WRW AL were included in the summation. Aluminum, arsenic, iron, manganese, and polynuclear aromatic hydrocarbons (PAHs) can be included in the calculation if they are indicated as possible contaminants by historical information or process knowledge. Otherwise they are generally omitted. Nonradionuclide SORs are presented in Table 7. All are less than 1.



Table 6 IHSS Group 500-3 Radionuclide SORs

| Location Code | Sample Starting Depth (ft bgs) | Sample Ending Depth (ft.bgs) | SOR |
|------------------|---|---------------------------------------|----------|
| CC43-001 | 0.5 | 1 | 0.01560 |
| CC44-000 | 0 | 0.5 | 0.04786 |
| CC44-000 | 0.5 | 0.9 | 0.04109 |
| CC44-001 | 0 - | 0.5 | 0.03748 |
| CC44-001 | 0.5 | 1 | 0.04944 |
| CC44-002 | 0 | 0.5 | 0.05244 |
| CC44-002 | 0.5 | 0.9 | 0.06410 |
| CC44-003 | 0 | 0.5 | 0.05705 |
| CD43-002-01 | 0.5 | 2.5 | 0.05690 |
| CD43-003 | 0.5 | 2.5 | 0.01776 |
| CD43-004 | 0 - | 0.5 | 0.02419 |
| CD43-005 | 0 | 0.5 | 0.06236 |
| CD43-006 | 0 | 0.5 | 0.01585 |
| CD43-007 | 0 | 0.5 | 0.02000 |
| CD43-007 | 0.5 | 1 | 0.03942 |
| CD43-008 | 0 | 0.5 | 0.03005 |
| CD43-009 | 1.2 | 1.6 | 0.01675 |
| CD43-014 | 0 | 0.5 | 0.05022 |
| CD43-015 | 0 | 0.5 | 0.00119 |
| CD43-016 | 0 | 0.5 | 0.05438 |
| CD43-016 | 0.5 | 2.5 | 0.05572 |
| CD43-017 | 0 | 0.5 | 0.04447 |
| CD43-017 | 0.5 | 0.8 | 0.00466 |
| CD43-025 | 0 | 0.5 | 0.01216 |
| CD43-026 | 0 | 0.5 | 0.04324 |
| CD43-027 | 0 | 0.5 | 0.06033 |
| CD43-028 | 0 | 0.5 | 0.04220 |
| CD43-035 | 2 | 2.3 | 0.01558 |
| CD43-041 | 0 | 4 | 0.02618 |
| CD44-001 | 0 | 0.5 | 0.05477 |
| CD44-001 | 0.5 | 2.5 | 0.05461 |
| CD44-002 | 0 | 0.5 | 0.04583 |
| CD44-003 | . 0 | 0.5 | 0.04929 |
| CD44-003 | 0.5 | 1 | 0.04928 |
| CD44-005 | 0 | 0.5 | 85.88605 |
| CD44-011 | . 5 | 5.3 | 0.01759 |
| CE43-001 | 0 | 0.5 | 0.01595 |
| CE43-002 | 0.5 | 1.5 | 0.01750 |

Table 7
IHSS Group 500-3 Nonradionuclide SORs for Surface Soil Samples

| Location | Sample Starting Depth (ft.bgs) | | SOR |
|----------|---|-----|---------|
| CC43-000 | 0.0 | 0.4 | 0.12090 |
| CD43-004 | 0.0 | 0.5 | 0.20485 |
| CD43-008 | 0.0 | 0.5 | 0.16493 |

Nonradionuclide SORs for historical sampling locations were not tabulated but were qualitatively considered. None of the historic sampling locations would have a nonradionuclide SOR greater than 1 unless benzo(a)pyrene is considered. The surface soil sample from sampling location 01895 would have a nonradionuclide SOR greater than 1 if benzo(a)pyrene is included, but neither historical information or process knowledge indicate PAHs are likely to be present as process-related contaminants in this area. Asphalt pavement was present in the area of sampling location 01895 and probably was the source of the benzo(a)pyrene.

3.0 ACCELERATED ACTION

Accelerated action activities are discussed below. The discussion includes identification of potential sources of contamination, remediation goals, and soil removal. Starting and ending dates of significant IHSS Group 500-3 accelerated action activities are listed in Table 8.

Table 8
IHSS Group 500-3 Accelerated Action Activities

| Activity | Starting Date | Ending Date | Duration |
|--|---------------|-------------|-------------------------|
| IASAP Addendum #IA-03-12 Characterization Sampling | 10/15/03 | 09/13/04 | 334 days (intermittent) |
| Excavation of Building 528 | 01/03/05 | 01/20/05 | 17 days |
| Additional Characterization Sampling at Building 528 | 01/19/05 | 01/24/05 | 5 days |
| Backfilling Excavation at Building 528 | 01/20/05 | 01/25/05 | 5 days |
| Excavation of Building 559 Slab, Removal of Associated OPWL, and Supplemental Characterization Sampling | 03/15/05 | 04/15/05 | 29 days |
| Excavation of Building 559 Tunnel | 04/04/05 | 04/11/05 | 7 days |
| Excavation of Room 130 (CD44-005) Hot Spot and Confirmation Sampling | 03/15/05 | 04/14/05 | 30 days (intermittent) |
| Excavation of Air Tunnel Hot Spot and Confirmation Sampling | 04/07/05 | 04/08/05 | 1 day |
| Excavation of Building 561 | 03/16/05 | 03/27/05 | 11 days |

| Activity | : Starting Date | Ending Date | Duration |
|---|-----------------|-------------|------------------------|
| Backfilling of Excavation at Building 561 | 03/28/05 | 03/30/05 | 2 days |
| B528-B559 Manway Hot Spot Removal and Confirmation Sampling | 01/05/05 | 03/23/05 | 77 days (intermittent) |
| Backfilling Excavations at Building 559 | 04/16/05 | 05/26/05 | 40 days (intermittent) |

Source: Personal Communication, Robert Ferrera, May 24, 2005

3.1 Evaluation of WRW AL Exceedances

IHSS Group 500-3 historical and accelerated action results that exceeded WRW ALs are presented in Table 9.

Table 9
IHSS Group 500-3 Historical and Accelerated Action WRW AL Exceedances in Soil

| Area | Location Code | Depth Interval (ft bgs) | Analyte | Result | WRW AL | Background Mean Plus Two Standard Deviations | Unit |
|------------------------|------------------|-------------------------------|-------------------|--------|-----------|--|-------|
| Manway Hot | CD43-054 | 7.5-7.8 | Americium-241 | 317.5 | 76 | 0.020 | pCi/g |
| Spot | CD43-054 | 7.5-7.8 | Plutonium-239/240 | 1809.8 | 50 | 0.020 | pCi/g |
| Room 130 | CD44-005 | 0-0.5 | Americium-241 | 1200 | 76 | 0.0227 | pCi/g |
| Hot Spot | CD44-005 | 0-0.5 | Plutonium-239/240 | 8130 | 50 | 0.066 | pCi/g |
| A | CD44-009 | 5.0-5.3 | Plutonium-239/240 | 60.534 | 50 | 0.020 | pCi/g |
| Air Tunnel Hot Spot | CD44-012 | 9.0-9.3 | Plutonium-239/240 | 74.67 | 50 | 0.020 | pCi/g |
| 110t Spot | CD44-015 | 9.0-9.3 | Plutonium-239/240 | 157.83 | 50 | 0.020 | pCi/g |
| NW of Building 528 | 01895 | 0.0-0.5 | Benzo(a)pyrene | 10000 | 3490 | NA | μg/kg |

Radionuclide activities in surface soil (0.0 to 0.5 ft bgs) exceeded WRW ALs at one accelerated action characterization sampling location beneath the Building 559 slab (CD44-005). The remaining radionuclide exceedances were of plutonium-239/240 or americium-241 at depths ranging from 5.0 to 9.3 ft bgs. RFCA does not require remediation of these exceedances because they are deeper than 3 ft below the final grade and less than 3 nanocuries per gram (nCi/g) activity. As discussed in Section 3.3, these exceedances were remediated as best management practices (BMPs) based on an as low as reasonably achievable (ALARA) evaluation.

A benzo(a)pyrene exceedance occurred in a historical sample collected near Building 528. The exceedance was isolated from other benzo(a)pyrene detections and was less than three times the WRW AL. Asphalt pavement in the immediate area of the exceedance was considered to be the source of the benzo(a)pyrene. Based on the Elevated Measurements Comparison (EMC), this location did not require remediation. However, the asphalt in the area was removed as part of Building 559 Decontamination and Decommissioning (D&D), and soil in the area was removed during the removal of the underground vault at Building 528, which involved the excavation of a pit more than

20 ft deep around Building 528. Soil associated with the benzo(a)pyrene exceedance was removed incidentally as a result of these activities.

3.2 RAOs and Accelerated Action Goals

ER RSOP RAOs and accelerated action goals were established for the remediation of soil at IHSS Group 500-3 sites. The RAOs stated in ER RSOP Notification #05-02 (DOE 2005a) are as follows:

- Remove portions of the Building 559 slab and associated tunnels (the 200-ft-long east-west tunnel as well as the tunnel connecting to Building 561) as necessary to remove the facility to at least 3 ft below final grade and as agreed to through consultation with the Colorado Department of Public Health and Environment (CDPHE).
- Remove asbestos-containing material (i.e., transite) encountered during slab removal. Dispose appropriately based on waste characterization results.
- Remove foundation, sanitary, and storm drains within 3 ft of final grade.
- Remove OPWL drains and piping within 3 ft of the final grade in accordance with ER RSOP Notification #03-14 (DOE 2003b) and RFCA Attachment 14 (DOE et al. 2003). Remove any OPWL piping and associated soil found during slab removal. OPWL piping that is deeper than 3 ft below the final grade will be disrupted, drained, and grouted.
- To address contamination detected at CD44-005 and any other contamination found during slab removal, remove soil with plutonium-239/240 or americium-241 activities greater than the RFCA WRW AL to a depth of 3 ft bgs or to the applicable AL, whichever comes first. If activities are greater than 3 nCi/g between 3 and 6 ft bgs, characterize and remediate in accordance with RFCA Attachment 5 (DOE et al. 2003). If plutonium-239/240 or americium-241 is present deeper than 6 ft at activities greater than the RFCA WRW AL, conduct an SSRS.
- Where contaminated soil is removed, collect confirmation soil samples in accordance with the IA and Buffer Zone (BZ) SAP (IABZSAP) (DOE 2004c).

By accomplishing the above objectives, the following remediation goals are achieved:

- Provide a remedy consistent with the RFETS goal of protection of human health and the environment;
- Provide a remedy that minimizes the need for long-term maintenance and institutional or engineering controls; and
- Minimize the spread of contaminants during implementation of accelerated actions.

It is understood that after remediation there may be areas of soil with concentrations of metals, radionuclides, and organics greater than background means plus two standard deviations, or MDLs or RLs, but below RFCA WRW ALs.

3.3 D&D Activities

D&D activities at IHSS Group 500-3 included the following:

- Building 528 was completely removed.
- Building 559 was demolished and its slab and footers were completely removed.
- Building 561 was demolished and completely removed.
- The air tunnel beneath Building 559 and the tunnel connecting Buildings 559 and 561 were completely removed.
- A manway between Buildings 559 and 528 was completely removed.
- All OPWL and New Process Waste Lines (NPWL) beneath and adjacent to Buildings 559 and 528 were removed.
- All sanitary and storm drain lines beneath and adjacent to Buildings 559 and 528 were removed.
- All water supply lines beneath and adjacent to Buildings 559 and 528 were removed, however three manways associated with water supply lines on the north side of Building 559 were left in place.


IHSS Group 500-3 features removed as part of D&D are shown on Figure 6.

3.4 Accelerated Action Soil Removal Activities

Accelerated action soil removal activities were conducted in accordance with ER RSOP Notification #05-02 (DOE 2005a).

Excavation at the CD44-005 (Room 130) hot spot began in mid-March 2005 after a portion of the slab overlying the hot spot was removed. Contaminated soil was removed and sampling indicated that soil in the northern and eastern sidewalls of the excavation was below WRW ALs; however, plutonium activities in the bottom of the excavation exceeded the WRW AL. After slab removal was completed, excavation of the hot spot resumed and the results of confirmation samples collected from the four sidewalls and bottom of the excavation on April 13, 2005 demonstrated that the hot spot had been removed.

The two remaining hot spots identified during OPWL removal were both deeper than 3 ft below the final grade, and were remediated as BMPs even though they did not require remediation under RFCA. The hot spot adjacent to the Building 559 air tunnel was remediated, and confirmation sampling took place on April 7 and 8, 2005. The hot spot



51/

beneath the manway between Buildings 559 and 528 was discovered on April 13, 2005 and remediated on April 14, 2005. A confirmation sample was collected on April 14, indicating the remediation was complete. The confirmation sample was analyzed for both radionuclides and VOCs.

Figure 7 shows the excavation boundaries resulting from soil removal activities at Buildings 528 and 559.

4.0 CONFIRMATION SAMPLING

Confirmation samples were collected at each of the three hot spots that were excavated in IHSS Group 500-3. Field screening samples were collected routinely during excavation and were analyzed on site by HPGe gamma spectroscopy. The results of field screening samples were used to guide the progress of excavation and ensure that contaminated soil was accurately targeted for removal. All confirmation samples were analyzed for radionuclides by both alpha and gamma spectroscopy. Because plutonium-239/240 and americium-241 were the only contaminants above ALs at these locations prior to remediation, confirmation samples did not need to be analyzed for other analyte groups. Two confirmation samples were collected at the CD44-005 hot spot prior to the complete removal of the Building 559 slab. After complete slab removal, excavation continued and five additional confirmation samples were collected. Five confirmation samples were collected at the hot spot located south of the eastern end of the air tunnel. One confirmation sample was collected at the hot spot excavated beneath the manway between Buildings 559 and 528. This sample was analyzed for both radionuclides and VOCs.

Confirmation sampling and analysis were conducted in accordance with the IABZSAP (DOE 2004c). Confirmation samples are included in the actual sampling totals presented in Table 1 and in the sampling and analysis specifications in Table 2. Confirmation sampling results are incorporated in the summary statistics presented in Tables 4 and 5. Confirmation sample depths reflect the actual depth excavated at the sampling location. Because excavations may have irregular bottoms or may slope downward from the sidewalls to the center, there may be depth differences between sidewall samples and samples collected in the center of an excavation.

Analytical results greater than background means plus two standard deviations are shown on Figure 7 and presented in Table 10. All radionuclide activities in confirmation samples were less than WRW ALs based on alpha spectroscopy results. Plutonium was the only analyte detected in the confirmation samples at activities greater than 10 percent of the WRW AL. Radionuclide SORs for confirmation samples, presented in Table 11, are all less than 1.




Table 10
IHSS Group 500-3 Confirmation Sampling Results Greater Than RLs or Background Means Plus Two Standard Deviations

| Location Code | Location Description | Sample Depth Interval (ft bgs) | Analyte | Result | WRW AL | Background Mean Plus Two Standard Deviations | Unit |
|--|--|---|--------------------|--------|-----------|---|-------|
| | 9 Room 130 Ho | | | | | | |
| CA42-036 | slab removal) | 0-4.0 | Americium-241 | 5.070 | 76 | 0.020 | pCi/g |
| | | | Plutonium-239/240 | 25.300 | 50 | 0.020 | pCi/g |
| CA 42 030 | A42-039 Eastern side- wall (prior to slab removal) | 0-4.0 | Americium-241 | 6.210 | 76 - | 0.020 | pCi/g |
| CA42-039 | | 0-4.0 | Plutonium-239/240 | 45.200 | 50 | 0.020 | pCi/g |
| CD43-038 | Northern side- wall (after slab | 0-4.0 | Americium-241 | 0.218 | 76 | 0.020 | pCi/g |
| CD43-036 | removal) | 0-4.0 | Plutonium-239/240 | 1.260 | 50 | 0.020 | pCi/g |
| CD43-039 Center of ex- cavation (after slab removal) | 4.0-4.3 | Americium-241 | 2.320 | 76 | 0.020 | pCi/g | |
| | 7.07.5 | Plutonium-239/240 | 12.000 | 50 | 0.020 | pCi/g | |
| CD42 041 | Eastern side- wall (after slab removal) | 0-4.0 | Americium-241 | 0.306 | 76 | 0.020 | pCi/g |
| CD43-041 | | 0-4.0 | Plutonium-239/240 | 2.570 | 50 | 0.020 | pCi/g |
| CD43-042 Western side- wall (after slab removal) | | | Americium-241 | 2.970 | 76 | 0.020 | pCi/g |
| | 0-4.5 | Plutonium-239/240 | 17.600 | 50 | 0.020 | pCi/g | |
| | Southern side- wall (after slab | 2.5-5.0 | Americium-241 | 1.590 | 76 | 0.020 | pCi/g |
| CD43-044 | removal) | 2.3-3.0 | Plutonium-239/240 | 10.300 | 50 | 0.020 | pCi/g |
| Manway H | ot Spot Excavat | ion | | | | | |
| | | , | Americium-241 | 1.640 | 76 | 0.020 | pCi/g |
| | | | Plutonium-239/240 | 12.000 | 50 | 0.020 | pCi/g |
| | | | Acetone | 11.000 | 10200000 | NA | μg/kg |
| CD 40 055 | Center of | 0005 | 2-Butanone | 1.900 | 192000000 | NA | μg/kg |
| CD43-055 | Excavation | 9.0-9.5 | Ethylbenzene | 0.310 | 4250000 | NA | μg/kg |
| | | | Methylene chloride | 2.400 | 2530000 | NA | μg/kg |
| | Į. | | Styrene | 0.099 | 12300000 | NA | μg/kg |
| | | | Xylene | 1.400 | 2040000 | NA | μg/kg |
| Air Tunne | Hot Spot Excav | ation | | | | | |
| | Eastern | 9.0-9.3 | Americium-241 | 1.300 | 76 | 0.020 | pCi/g |
| CD44-013 | sidewall | 9.0-9.3 | Plutonium-239/240 | 5.700 | 50 | 0.020 | pCi/g |
| CD44-014 | Southern | 9.0-9.3 | Americium-241 | 0.122 | 76 | 0.020 | pCi/g |
| CD44-014 | sidewall | 7.0-7.3 | Plutonium-239/240 | 0.210 | 50 | 0.020 | pCi/g |
| CD44-016 | Center of | 9.0-9.3 | Americium-241 | 3.060 | 76 | 0.020 | pCi/g |
| CD44-010 | excavation | 3.0-3.3 | Plutonium-239/240 | 18.500 | 50 | 0.020 | pCi/g |
| CD44-017 | Northern | 11-11.3 | Americium-241 | 3.300 | 76 | 0.020 | pCi/g |
| OD44-017 | sidewall | * * * * * * * * * * * * * * * * * * * | Plutonium-239/240 | 10.000 | 50 | 0.020 | pCi/g |

| Location | Location | Sample Depth Interval | | | | Background Mean Plus Two Standard | |
|----------|-------------|-----------------------------|-------------------|--------|--------|---|-------|
| Code | Description | (ft bgs) | Analyte | Result | WRW AL | | Unit |
| CD44-018 | Western | 11-11.3 | Americium-241 | 5.700 | 76 | 0.020 | pCi/g |
| CD44-018 | sidewall | 11-11.3 | Plutonium-239/240 | 20.900 | 50 | 0.020 | pCi/g |

Table 11
Confirmation Sample Radionuclide SORs

| Location Code | Sample Starting Depth (ft bgs) | Sample Ending Depth (ft bgs) | SOR |
|------------------|---|---------------------------------------|---------|
| CA42-036 | 0 | 4 | 0.28481 |
| CA42-039 | 0 | 4 | 0.47137 |
| CD43-038 | 0 | 4 | 0.01373 |
| CD43-042 | 0 | 4.5 | 0.19080 |
| CD43-044 | 2.5 | 5 | 0.10971 |

5.0 RCRA UNIT CLOSURE

Table 8 of the ER RSOP identifies the Resource Conservation and Recovery Act (RCRA) units to be closed as part of ER accelerated actions (DOE 2004a). None of the listed RCRA units is located in IHSS Group 500-3.

6.0 POST-ACCELERATED ACTION CONDITIONS

Figures 8, 9, and 10 show the distribution of residual contamination in soil at IHSS Group 500-3 based on accelerated action characterization and confirmation sampling results, as well as historical data. Soil was removed at three hot spots and the excavations were backfilled with clean Site soil. Analytical results of the confirmation sampling of the excavations indicate radionuclide activities are below WRW ALs.

As Figures 8, 9, and 10 indicate, residual contaminant concentrations and activities are less than WRW ALs throughout IHSS Group 500-3; however, concentrations and activities exceeding background means plus two standard deviations (inorganics) or RLs (organics) are still present.

7.0 SSRS

The SSRS follows the steps identified on Figure 3 of Attachment 5 of RFCA (DOE et al. 2003).

Screen 1 – Are contaminant of concern (COC) concentrations below WRW Soil Action Levels?

Yes. As Figures 8, 9, and 10 indicate, residual COC concentrations in surface and subsurface soil are below WRW ALs. Screens 2 and 3 of the SSRS are therefore omitted.

Screen 4 – Is there an environmental pathway and sufficient quantity of COCs that would cause an exceedance of the surface water standards?

Based on the maps of residual contamination (Figures 8, 9, and 10), there is no significant contaminant source remaining in IHSS Group 500-3 following D&D and accelerated action. IHSS Group 500-3 is not located in an area of high erosion as shown in RFCA Attachment 5, Figure 1 (DOE et al. 2003). Moreover, erosion controls will be incorporated as part of the final ground surface reconfiguration in this area, and ongoing surface water quality monitoring will continue to ensure the long-term effectiveness of the accelerated action for protecting surface water.

Groundwater beneath IHSS Group 500-3 is part of the IA VOC Plume, which is being evaluated as part of the Groundwater Interim Measure/Interim Remedial Action (IM/IRA). Residual soil data for IHSS Group 500-3 (Figures 8, 9, and 10) do not indicate the presence of VOC sources in this area.

8.0 STEWARDSHIP EVALUATION

The IHSS Group 500-3 stewardship evaluation was based on current site conditions.

8.1 Current Site Conditions

Based on the accelerated action characterization and remediation activities, the following conditions exist at IHSS Group 500-3:

- Building 528 was completely removed.
- Building 559 was demolished and its slab and footers were completely removed.
- Building 561 was demolished and completely removed.
- The air tunnel beneath Building 559 and the tunnel connecting Buildings 559 and 561 were completely removed.
- A manway between Buildings 559 and 528 was completely removed.
- Plutonium- and americium-contaminated soil was excavated from three hot spots.
 Confirmation sampling demonstrated that activities in the remaining soil are less than WRW ALs.
- All excavations were backfilled with clean fill obtained on Site and the area has been regraded. Revegetation will follow.

- All OPWL and NPWL beneath and adjacent to Buildings 559 and 528 were removed.
- All sanitary and storm drain lines beneath and adjacent to Buildings 559 and 528 were removed.
- All water supply lines beneath and adjacent to Buildings 559 and 528 were removed; however, three manways associated with water supply lines on the north side of Building 559 were left in place.

8.2 Near-Term Management Recommendations

Contaminant concentrations in soil remaining at IHSS Group 500-3 do not require additional accelerated action. Near-term management actions are recommended because residual contaminant concentrations greater than RLs or background means plus two standard deviations remain in surface and subsurface soil at the IHSS Group 500-3 sites. The following near-term management actions are recommended:

- Access to the sites will be restricted.
- Soil excavation will be controlled.
- Groundwater pumping will be prohibited.
- Restrictions on access to the sites, controls on soil excavation, and the prohibition on groundwater pumping will remain in force until long-term management actions are implemented.

8.3 Long-Term Stewardship Recommendations

Based on the remaining environmental conditions discussed above, the long-term stewardship actions recommended for the IHSS Group 500-3 sites are the same as the near-term management actions discussed above. Through the imposition of physical and institutional controls, site access and soil excavation will be restricted, and groundwater pumping will be prohibited. Additional environmental engineering or monitoring activities are not required or recommended for soil at IHSS Group 500-3. IHSS Group 500-3 will be evaluated as part of the Accelerated Action Ecological Screening Evaluation (AAESE) and Sitewide Comprehensive Risk Assessment (CRA). The CRA is part of the RCRA Facility Investigation/Remedial Investigation (RFI/RI) and Corrective Measures Study/Feasibility Study (CMS/FS) that will be conducted for RFETS. If additional long-term stewardship actions are determined to be necessary, they will be included in the preferred alternative that will be presented in the Proposed Plan. The final long-term stewardship actions recommended for IHSS Group 500-3 will be summarized in the Rocky Flats Long-Term Stewardship Strategy, and will be contained in the Corrective Action Decision/Record of Decision (CAD/ROD), any post-closure Colorado Hazardous Waste Act (CHWA) permit that may be required, and any post-RFCA agreement.



9.0 DEVIATIONS FROM THE ER RSOP

There were no deviations from the ER RSOP. In addition to activities governed by the ER RSOP, IHSS Group 500-3 underwent extensive D&D activities, including the demolition and complete removal of Buildings 528, 559, and 561, and associated subgrade structures and OPWLs. D&D was conducted in accordance with the RSOP for Facility Disposition (DOE 2004d) and the RSOP for Facility Component Removal, Size Reduction, and Decontamination (DOE 2003c).

10.0 WASTE MANAGEMENT

Waste materials generated as part of the IHSS Group 500-3 accelerated action slab and soil removal included soil, concrete, nonfriable asbestos, and glass (Pyrex) piping. Contaminated soil, concrete, and asbestos associated with the removal of subgrade structures, such as the Building 559 slab and footers, were counted as remediation waste, while subgrade OPWL piping (typically Pyrex) was tracked as D&D waste, along with all concrete, metal, and asbestos debris associated with the demolition of the above-grade structure. Table 12 summarizes wastes associated with the accelerated action slab and soil removal at IHSS Group 500-3. With the exception of OPWL piping, wastes tracked as D&D wastes are not tabulated. Partway through the project, wastes from IHSS Group 500-3 began to be transferred to Building 776 to be packaged and handled with wastes from that project. Approximately 3,830 cubic yards of ER soil and concrete waste were transferred from IHSS Group 500-3 to Building 776.

Table 12
IHSS Group 500-3 Accelerated Action Slab and Soil Waste Removal Summary

| Description | Туре | Volume (cubic yards) | Containers |
|-------------------------------------|------|-------------------------|-----------------------------|
| Soil | LLW | 88 | 7 IML containers |
| Concrete | LLW | 409 | 23 IML containers |
| Concrete and Nonfriable Asbestos | LLW | · 18 | 1 IML container |
| Piping, Glass, Transite (D&D waste) | LLW | 46 | 3 IML containers |
| Soil | LLW | 1532 | Transferred to Building 776 |
| Concrete | LLW | 2298 | Transferred to Building 776 |

11.0 SITE RECLAMATION

The excavations associated with soil remediation were surveyed and backfilled with clean Site soil. The excavations associated with D&D activities were also backfilled with clean Site soil. Documentation regarding backfilling is provided in an ER Regulatory Contact Record dated April 14, 2005 (Appendix A).

12.0 NLR SAMPLING LOCATIONS

The characterization data from eight sampling locations are considered NLR because the soil once present at those sampling locations was excavated and removed as a remedial

action. The NLR sampling locations are listed in Table 13. For those locations listed that have multiple sample depths, all samples are NLR.

Table 13 NLR Sampling Locations

| Location Code | Actual Northing | Actual Easting |
|------------------|--------------------|----------------|
| CC43-030 | 750098.180 | 2083515.490 |
| CD43-034 | 750198.392 | 2083468.364 |
| CD43-054 | 750102.153 | 2083516.970 |
| CD44-005 | 750184.640 | 2083459.240 |
| CD44-009 | 750125.190 | 2083465.114 |
| CD44-012 | 750126.916 | 2083466.281 |
| CD44-015 | 750124.613 | 2083461.325 |
| 01895 | 750070.000 | 2083508.000 |

13.0 DQA

The data quality objectives (DQOs) for this project are described in the IASAP (DOE 2001). All DQOs for this project were achieved based on the following:

- Regulatory agency-approved sampling program design in accordance with the IASAP (DOE 2001) and IABZSAP (DOE 2004c);
- Collection of samples in accordance with the sampling design;
- Implementation of remediation activities in accordance with ER RSOP Notification #05-02 (DOE 2005a); and
- Results of the DQA, as described in the following sections.

13.1 DQA Process

The DQA process ensures that the type, quantity, and quality of environmental data used in decision making are defensible, and is based on the following guidance and requirements:

- U.S. Environmental Protection Agency (EPA), 1994a, Guidance for the Data Quality Objective Process, QA/G-4;
- EPA, 1998, Guidance for the Data Quality Assessment Process, Practical Methods for Data Analysis, QA/G-9; and
- DOE, 1999, Quality Assurance, Order 414.1A.

Verification and validation (V&V) of data are the primary components of the DQA. The final data are compared with original project DQOs and evaluated with respect to project decisions; uncertainty within the decisions; and quality criteria required for the data,



specifically precision, accuracy, representativeness, completeness, comparability, and sensitivity (PARCCS). Validation criteria are consistent with the following RFETS-specific documents and industry guidelines:

- EPA, 1994b, USEPA Contract Laboratory Program National Functional Guidelines for Organic Data Review, 540/R-94/012;
- EPA, 1994c, USEPA Contract Laboratory Program National Functional Guidelines for Inorganic Data Review, 540/R-94/013;
- Kaiser-Hill Company, L.L.C. (K-H), 2002a, General Guidelines for Data Verification and Validation, DA-GR01-v2, October;
- K-H, 2002b, V&V Guidelines for Isotopic Determinations by Alpha Spectrometry, DA-RC01-v2, October;
- K-H, 2002c, V&V Guidelines for Volatile Organics, DA-SS01-v3, October;
- K-H, 2002d, V&V Guidelines for Semivolatile Organics, DA-SS02-v3, October;
- K-H, 2002e, V&V Guidelines for Metals, DA-SS05-v3, October; and
- K-H, 2002f, V&V Guidelines for Radiochemistry by Gamma Spectrometry DA-GAM-v1.
- Lockheed-Martin, 1997, Evaluation of Radiochemical Data Usability, ES/ER/MS-5.

This report will be submitted to the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) AR for permanent storage 30 days after being provided to CDPHE and/or EPA.

13.2 V&V of Results

Verification ensures that data produced and used by the project are documented and traceable in accordance with ER Program requirements. Validation consists of a technical review of all data that directly support the project decisions so that any limitations of the data relative to project goals are identified and the associated data are qualified accordingly. The V&V process defines the criteria that constitute data quality, namely PARCCS parameters. Data traceability and archiving are also addressed. V&V criteria include the following:

- Chain-of-custody;
- Preservation and hold times;
- Instrument calibrations;

- Preparation blanks;
- Interference check samples (metals);
- Matrix spikes/matrix spike duplicates (MS/MSDs);
- Laboratory control samples (LCSs);
- Field duplicate measurements;
- Chemical yield (radiochemistry);
- Required quantitation limits/minimum detectable activities (sensitivity of chemical and radiochemical measurements, respectively); and
- Sample analysis and preparation methods.

Evaluation of V&V criteria ensures that PARCCS parameters are satisfactory (that is, within tolerances acceptable to the project). V&V findings are captured through application of validation "flags" or qualifiers to individual records.

Raw hard-copy data (that is, individual analytical data packages) are currently filed by report identification number (RIN) and maintained by K-H Analytical Services Division (ASD). Older hard copies may reside at the Federal Center in Lakewood, Colorado. Electronic data are stored in the RFETS Soil-Water Database (SWD). Standardized real and QC data are included on the enclosed CD.

13.2.1 Accuracy

The following measures of accuracy were evaluated:

- LCSs;
- Surrogates;
- Field blanks; and
- Sample MSs.

Results are compared to method requirements and project goals. The results of these comparisons are summarized for RFCA COCs where uncertainty associated with analytical accuracy is potentially great enough to affect project decisions. Particular attention is paid to those results that approach ALs, where unacceptable QC results could indicate unacceptable levels of uncertainty for decision-making purposes.

LCS Evaluation

As indicated in Table 14, LCS analyses were run for all methods except gamma spectroscopy. When the In-Situ Counting System (ISOCS) technique is used for gamma spectroscopy, an internal standard approach is used instead of LCSs. The on-site



laboratory that performs gamma spectroscopy uses ISOCS and is therefore not required to provide LCS data.

Table 14 LCS Summary

| 图 图 图 图 图 图 图 | Laboratory | LCS |
|----------------------|------------|------|
| Test Method | Batch | Run? |
| ALPHA SPEC | 3351162 | Yes |
| ALPHA SPEC | 3351171 | Yes |
| ALPHA SPEC | 3351176 | Yes |
| ALPHA SPEC | 357524 | Yes |
| ALPHA SPEC | 357526 | Yes |
| ALPHA SPEC | 357528 | Yes |
| ALPHA SPEC | 359219 | Yes |
| ALPHA SPEC | 360421 | Yes |
| ALPHA SPEC | 361139 | Yes |
| ALPHA SPEC | 366445 | Yes |
| ALPHA SPEC | 366446 | Yes |
| ALPHA SPEC | 366447 | Yes |
| ALPHA SPEC | 5028426 | Yes |
| ALPHA SPEC | 5028428 | Yes |
| ALPHA SPEC | 5028432 | Yes |
| ALPHA SPEC | 5082474 | Yes |
| ALPHA SPEC | 5082477 | Yes |
| ALPHA SPEC | 5082480 | Yes |
| ALPHA SPEC | 5103466 | Yes |
| ALPHA SPEC | 5103469 | Yes |
| ALPHA SPEC | 5103470 | Yes |
| ALPHA SPEC | 5107077 | Yes |
| ALPHA SPEC | 5107078 | Yes |
| ALPHA SPEC | 5107079 | Yes |
| ALPHA SPEC | 5109558 | Yes |
| ALPHA SPEC | 5109559 | Yes |
| ALPHA SPEC | : 5109560 | Yes |
| ALPHA SPEC | 5113101 | Yes |
| ALPHA SPEC | 5116456 | Yes |
| ALPHA SPEC | 5116459 | Yes |
| SW-846 6010 | 3290580 | Yes |
| SW-846 6010 | 3292097 | Yes |
| SW-846 6010 | 3294581 | Yes |
| SW-846 6010 | 3294600 | Yes |
| SW-846 6010 | 3295497 | Yes |
| SW-846 6010 | 3295521 | Yes |
| SW-846 6010 | 3296538 | Yes |
| SW-846 6010 | 3296541 | Yes |
| SW-846 6010 | 3350508 | Yes |
| SW-846 6010 | 3350510 | Yes |



| Test Method | Laboratory Batch | LCS Run? |
|-------------|---------------------|-------------|
| SW-846 6010 | 4225543 | Yes |
| SW-846 6010 | 4225545 | Yes |
| SW-846 6010 | 4229123 | Yes |
| SW-846 6010 | 4229297 | Yes |
| SW-846 6010 | 4230510 | Yes |
| SW-846 6010 | 4232444 | Yes |
| SW-846 6010 | 4232455 | Yes |
| SW-846 6010 | 4232611 | Yes |
| SW-846 6010 | 4232615 | Yes |
| SW-846 6010 | 4233203 | Yes |
| SW-846 6010 | 4259583 | Yes |
| SW-846 6010 | 4264486 | Yes |
| SW-846 6010 | 5109586 | Yes |
| SW-846 6010 | 5111217 | Yes |
| SW-846 8081 | 3295210 | Yes |
| SW-846 8082 | 3295224 | Yes |
| SW-846 8260 | 3351321 | Yes |
| SW-846 8260 | 4225468 | Yes |
| SW-846 8260 | 4229384 | Yes |
| SW-846 8260 | 4264333 | Yes |
| SW-846 8260 | 5112263 | Yes |
| SW-846 8260 | MS1 VOA_031017A | Yes |
| SW-846 8260 | MS1 VOA_031021A | Yes |
| SW-846 8260 | MS1 VOA_031022A | Yes |
| SW-846 8260 | MS1 VOA_040809A | Yes |
| SW-846 8260 | MS1 VOA_040811A | Yes |
| SW-846 8260 | MS1 VOA_040812A | Yes |
| SW-846 8260 | MS1 VOA_040817A | Yes |
| SW-846 8260 | MS1 VOA_040901A | Yes |
| SW-846 8260 | MS2 VOA_031016A | Yes |
| SW-846 8260 | MS2 VOA_050411A | Yes |
| SW-846 8260 | MS3 VOA_031021A | Yes |
| SW-846 8260 | MS3 VOA_031022A | Yes |
| SW-846 8260 | MS3 VOA_040809A | Yes |
| SW-846 8260 | MS3 VOA_040811A | Yes |
| SW-846 8260 | MS3 VOA_040816A | Yes |
| SW-846 8260 | MS3 VOA_040816B | Yes |
| SW-846 8260 | MS3 VOA_040902A | Yes |

The minimum and maximum LCS results for IHSS Group 500-3 are tabulated by chemical in Table 15. LCS recoveries are not indicative of matrix effects because they are not prepared using site samples, but LCS results do indicate whether the laboratory may be introducing a bias in the results. LCS results outside of tolerances were reviewed to determine whether a potential bias might be indicated. Recoveries reported above the

upper limit may indicate the actual sample results are less than reported. Because this is environmentally conservative, no further evaluation is needed. The analytes with unacceptably low recoveries were evaluated further. If the highest sample result divided by the lowest LCS recovery for that analyte is less than the AL, no further evaluation is warranted because any indicated bias is not great enough to affect project decisions. Based on this analysis, the LCS recoveries for IHSS Group 500-3 did not indicate that project decisions had been affected.

Table 15
LCS Evaluation Summary

| | CAS | | Minimum Percent | Maximum Percent |
|-------------|------------|---------------------------|--------------------|--------------------|
| Test Method | Number | Analyte | Recovery | Recovery |
| SW-846 8260 | 71-55-6 | 1,1,1-Trichloroethane | 77.27 | 126 |
| SW-846 8260 | 79-34-5 | 1,1,2,2-Tetrachloroethane | 85 | 112.6 |
| SW-846 8260 | 79-00-5 | 1,1,2-Trichloroethane | 89 | 112 |
| SW-846 8260 | 75-34-3 | 1,1-Dichloroethane | 82.09 | 111.3 |
| SW-846 8260 | 75-35-4 | 1,1-Dichloroethene | 73.8 | 112 |
| SW-846 8260 | 120-82-1 | 1,2,4-Trichlorobenzene | 88.67 | 115.2 |
| SW-846 8260 | 95-50-1 | 1,2-Dichlorobenzene | 92 | 110.1 |
| SW-846 8260 | 107-06-2 | 1,2-Dichloroethane | 83.24 | 129 |
| SW-846 8260 | 78-87-5 | 1,2-Dichloropropane | 84.5 | 109.2 |
| SW-846 8260 | 106-46-7 | 1,4-Dichlorobenzene | 92 | 110.9 |
| SW-846 8260 | 78-93-3 | 2-Butanone | 44.72 | 136 |
| SW-846 8081 | 50-29-3 | 4,4'-DDT | 117 | 117 |
| SW-846 8260 | 108-10-1 | 4-Methyl-2-pentanone | 79.62 | 123 |
| SW-846 8260 | 67-64-1 | Acetone | 41.05 | 176.4 |
| SW-846 8081 | 309-00-2 | Aldrin | 103 | 103 |
| SW-846 6010 | 7429-90-5 | Aluminum | 93 | 100 |
| SW-846 6010 | 7440-36-0 | Antimony | 83 | 99 |
| SW-846 8082 | 12674-11-2 | Aroclor-1016 | 109 | 109 |
| SW-846 8082 | 11096-82-5 | Aroclor-1260 | 110 | 110 |
| SW-846 6010 | 7440-38-2 | Arsenic | 85 | 99 |
| SW-846 6010 | 7440-39-3 | Barium | 95 | 104 |
| SW-846 8260 | 71-43-2 | Benzene | 82.92 | 107.9 |
| SW-846 6010 | 7440-41-7 | Beryllium | 94 | 104 |
| SW-846 8260 | 75-27-4 | Bromodichloromethane | 79.21 | 117 |
| SW-846 8260 | 75-25-2 | Bromoform | 84.59 | 122 |
| SW-846 8260 | 74-83-9 | Bromomethane | 75.06 | 116 |
| SW-846 6010 | 7440-43-9 | Cadmium | 88 | 100 |
| SW-846 8260 | 75-15-0 | Carbon Disulfide | 69 | 132.4 |
| SW-846 8260 | 56-23-5 | Carbon Tetrachloride | 77.36 | . 123 |
| SW-846 8260 | 108-90-7 | Chlorobenzene | 94 | 122.1 |
| SW-846 8260 | 75-00-3 | Chloroethane | 80.09 | 122.2 |
| SW-846 8260 | 67-66-3 | Chloroform | 83.46 | 116 |
| SW-846 8260 | 74-87-3 | Chloromethane | 67.74 | 126.7 |

| | CAS | organism (September 1981) Makati ng katebangsi s | Minimum Percent | Maximum Percent |
|-------------|------------|---|--------------------|--------------------|
| Test Method | Number | Analyte | Recovery | Recovery |
| SW-846 6010 | 7440-47-3 | Chromium | 89 | 102 |
| SW-846 8260 | 10061-01-5 | cis-1,3-Dichloropropene | 83.65 | 111 |
| SW-846 6010 | 7440-48-4 | Cobalt | 86 | 99 |
| SW-846 6010 | 7440-50-8 | Copper | 88 | 101 |
| SW-846 8260 | 124-48-1 | Dibromochloromethane | 89.45 | 120 |
| SW-846 8081 | 60-57-1 | Dieldrin | 112 | 112 |
| SW-846 8081 | 72-20-8 | Endrin | 106 | 106 |
| SW-846 8260 | 100-41-4 | Ethylbenzene | 95 | 121.5 |
| SW-846 8081 | 58-89-9 | gamma-BHC | 101 | 101 |
| SW-846 8081 | 76-44-8 | Heptachlor | 110 | 110 |
| SW-846 8260 | 87-68-3 | Hexachlorobutadiene | 89.22 | 115.1 |
| SW-846 6010 | 7439-89-6 | Iron | 93 | 102 |
| SW-846 6010 | 7439-92-1 | Lead | 91 | 100 |
| SW-846 6010 | 7439-93-2 | Lithium | 93 | 103 |
| SW-846 6010 | 7439-96-5 | Manganese | 89 | 101 |
| SW-846 6010 | 7439-97-6 | Mercury | 93 | 107 |
| SW-846 8260 | 75-09-2 | Methylene chloride | 82.4 | 109.9 |
| SW-846 6010 | 7439-98-7 | Molybdenum | 86 | 100 |
| SW-846 8260 | 91-20-3 | Naphthalene | 81 | 119 |
| SW-846 6010 | 7440-02-0 | Nickel | 89 | 100 |
| SW-846 6010 | 7782-49-2 | Selenium | 84 | 98 |
| SW-846 6010 | 7440-22-4 | Silver | 86 | 100 |
| SW-846 6010 | 7440-24-6 | Strontium | 92 | 102 |
| SW-846 8260 | 100-42-5 | Styrene | 95.37 | 113.5 |
| SW-846 8260 | 127-18-4 | Tetrachloroethene | 92.54 | 111.7 |
| SW-846 6010 | 7440-31-5 | Tin | 81 | 101 |
| SW-846 8260 | 108-88-3 | Toluene | 91 | 116.3 |
| SW-846 8260 | 10061-02-6 | trans-1,3-Dichloropropene | 91 | 120 |
| SW-846 8260 | 79-01-6 | Trichloroethene | 79.3 | 110.5 |
| SW-846 6010 | 11-09-6 | Uranium, Total | 92 | 107 |
| SW-846 6010 | 7440-62-2 | Vanadium | 89 | 101 |
| SW-846 8260 | 75-01-4 | Vinyl chloride | 78.08 | 122 |
| SW-846 8260 | 1330-20-7 | Xylene | 95 | 121.9 |
| SW-846 6010 | 7440-66-6 | Zinc | 82 | 98 |

Surrogate Evaluation

A summary of surrogate results for IHSS Group 500-3 samples is presented in Table 16. Surrogate frequency was adequate based on at least one set per VOC sample. Surrogates are added to every sample; therefore, surrogate recoveries pertain to individual samples only. Unacceptable surrogate recoveries can indicate matrix effects. The highest and lowest surrogate recoveries for this project were reviewed, and results indicated no adverse impact to project decisions due to matrix effects. All organic compounds



associated with poor surrogate recoveries had maximum concentrations significantly less than WRW ALs.

Table 16
Surrogate Recovery Summary

| Number of Samples | CAS Number | Analyte | Minimum Percent Recovery | Maximum Percent Recovery |
|-------------------|---------------|-------------------------------|--------------------------------|--------------------------------|
| .76 | 460-00-4 | 4-Bromofluorobenzene | 79 | 119.4 |
| 76 | 17060-07-0 | Deuterated 1,2-dichloroethane | 66 | 126 |
| 76 | 2037-26-5 | Deuterated toluene | 79 | 114.8 |

Field Blank Evaluation

Results of IHSS Group 500-3 field blank analyses are given in Table 17. Detectable contamination in field blanks could indicate cross-contamination of samples if the same contaminant is also detected in the associated real samples. When the real result is less than 10 times the blank result for common laboratory contaminants or 5 times the result for other contaminants, the real result is eliminated. None of the chemicals were detected in the blanks at concentrations greater than one-tenth the AL. Therefore, evaluation of field blank results indicated no cross-contamination that could adversely impact project decisions.

Table 17
Field Blank Summary

| Laboratory | CAS Number | Analyte | Sample QC Code | Detected Result | Result Unit | |
|------------|---------------|----------------------|-------------------|--------------------|-------------|--|
| ESTLDEN | 78-93-3 | 2-Butanone | TB | 2.2 | μg/L | |
| GEL | 67-64-1 | Acetone | ТВ | 4.6 | μg/L | |
| ESTLDEN | 67-64-1 | Acetone | ТВ | 15 | μg/L | |
| ESTLDEN | 7429-90-5 | Aluminum | RNS | 0.3 | mg/L | |
| ESTLDEN | 7429-90-5 | Aluminum | FB | 0.03 | mg/L | |
| ESTLDEN | 7440-36-0 | Antimony | FB | 0.0036 | mg/L | |
| ESTLDEN | 7440-39-3 | Barium | RNS | 0.0022 | mg/L | |
| ESTLDEN | 7440-39-3 | Barium | FB | 0.00068 | mg/L | |
| ESTLDEN | 7440-43-9 | Cadmium | FB | 0.00059 | mg/L | |
| URS | 56-23-5 | Carbon Tetrachloride | FB | 36.2 | μg/L | |
| URS | 56-23-5 | Carbon Tetrachloride | ТВ | 35.6 | μg/L | |
| URS | 67-66-3 | Chloroform | FB | 1.7 | μg/L | |
| URS | 67-66-3 | Chloroform | ТВ | 1.7 | μg/L | |
| ESTLDEN | 7440-48-4 | Cobalt | RNS | 0.0007 | mg/L | |
| ESTLDEN | 7440-48-4 | Cobalt | FB | 0.00068 | mg/L | |
| ESTLDEN | 7440-50-8 | Copper | FB | 0.0047 | mg/L | |
| ESTLDEN | 7440-50-8 | Copper | RNS | 0.025 | mg/L | |
| URS | 100-41-4 | Ethylbenzene | ТВ | 1.2 | μg/L | |
| ESTLDEN | 7439-89-6 | Iron | FB | 0.031 | mg/L | |

| Alban Arak | CAS | | Sample QC | Detected | |
|------------|------------|--------------------|-----------|----------|-------------|
| Laboratory | Number | Analyte | Code | Result | Result Unit |
| ESTLDEN | 7439-89-6 | Iron | RNS | 0.22 | mg/L |
| ESTLDEN | 7439-92-1 | Lead | FB | 0.003 | mg/L |
| ESTLDEN | 7439-92-1 | Lead | RNS | 0.0043 | mg/L |
| ESTLDEN | 7439-93-2 | Lithium | FB | 0.0019 | mg/L |
| ESTLDEN | 7439-93-2 | Lithium | RNS | 0.0027 | mg/L |
| ESTLDEN | 7439-96-5 | Manganese | RNS | 0.0026 | mg/L |
| ESTLDEN | 7439-96-5 | Manganese | FB | 0.00069 | mg/L |
| ESTLDEN | 7439-97-6 | Mercury | FB | 0.00023 | mg/L |
| ESTLDEN | 75-09-2 | Methylene chloride | ТВ | 0.26 | μg/L |
| ESTLDEN | 7439-98-7 | Molybdenum | RNS | 0.003 | mg/L |
| URS | 91-20-3 | Naphthalene | FB | 1.4 | μg/L |
| ESTLDEN | 91-20-3 | Naphthalene | ТВ | 0.6 | μg/L |
| ESTLDEN | 7440-02-0 | Nickel | FB | 0.036 | mg/L |
| ESTLDEN | 7440-24-6 | Strontium | FB | 0.00067 | mg/L |
| ESTLDEN | 7440-24-6 | Strontium | RNS | 0.0068 | mg/L |
| ESTLDEN | 7440-31-5 | Tin | RNS | 0.0089 | mg/L |
| ESTLDEN | 108-88-3 | Toluene | TB | 0.3 | μg/L |
| URS | 108-88-3 | Toluene | RNS | 2 | μg/L |
| URS | 108-88-3 | Toluene | FB | 2.7 | μg/L |
| URS | 108-88-3 | Toluene | TB | 2.1 | μg/L |
| URS | 15117-96-1 | Uranium-235 | FB · | 0.181 | pCi/g |
| URS | 15117-96-1 | Uranium-235 | RNS | 0.191 | pCi/g |
| URS . | 7440-61-1 | Uranium-238 | FB | 3.38 | pCi/g |
| URS | 7440-61-1 | Uranium-238 | RNS | 3.31 | pCi/g |
| URS | 1330-20-7 | Xylene | RNS | 2.5 | μg/L |
| ESTLDEN | 7440-66-6 | Zinc | FB | 0.0055 | mg/L |
| ESTLDEN | 7440-66-6 | Zinc | RNS | 0.018 | mg/L |

Sample MS Evaluation

The minimum and maximum MS results for IHSS Group 500-3 are summarized by chemical in Table 18. According to EPA data validation guidelines (EPA 1994b), if organic MS recoveries are low, the data reviewer may evaluate the MS and MSD results in conjunction with other QC criteria. For this project, LCS recoveries were reviewed for organic analytes with unacceptably low MS recoveries. For 1,1,2,2-tetrachloroethane, the minimum MS recovery was less than 5 percent, but the LCS recovery was 85%. The LCS result indicated that the laboratory was able to detect the analyte in a matrix free of interferences, but the very low MS recovery suggests that matrix interference was significant in the particular sample that exhibited the low MS recovery, which was collected at CD44-005. A review of individual 1,1,2,2-tetrachloroethane recoveries in all IHSS Group 500-3 MS and MSD samples indicates that recoveries exceeded 90% in half of all MS and MSD samples and exceeded 60% in three-quarters of all MS and MSD samples. Thus the apparent matrix effects on 1,1,2,2-tetrachloroethane appear to be isolated to certain samples and are not pervasive throughout the data set.

For inorganics, the maximum sample result for each analyte was divided by the lowest percent recovery for that analyte. If the resulting number was less than the AL, data quality was sufficient for making project decisions and no further evaluation was required. For this project, all results were acceptable. Low recoveries of antimony, copper, mercury, and manganese did not adversely affect project decisions because the associated RFCA WRW ALs were at least two times greater than the highest sample result.

Table 18
Sample MS Evaluation Summary

| Test Method | CAS Number | Analyte | Minimum Percent Recovery | Maximum Percent Recovery | Number of Samples | Number of Lab Batches |
|-------------|---------------|---------------------------|--------------------------------|--------------------------------|-------------------|-----------------------------|
| SW-846 8260 | 71-55-6 | 1,1,1-Trichloroethane | 82 | 108.7 | 12 | 12 |
| SW-846 8260 | 79-34-5 | 1,1,2,2-Tetrachloroethane | 3.039 | 143.4 | 12 | 12 |
| SW-846 8260 | 79-00-5 | 1,1,2-Trichloroethane | 83 | 108.8 | 12 | 12 |
| SW-846 8260 | 75-34-3 | 1,1-Dichloroethane | 80 | 107.8 | 12 | 12 |
| SW-846 8260 | 75-35-4 | 1,1-Dichloroethene | 89 | 113.8 | 12 | 12 |
| SW-846 8260 | 120-82-1 | 1,2,4-Trichlorobenzene | 32.01 | 90 | 12 | 12 |
| SW-846 8260 | 95-50-1 | 1,2-Dichlorobenzene | 72.76 | 97.13 | 12 | 12 |
| SW-846 8260 | 107-06-2 | 1,2-Dichloroethane | 82 | 117 | 12 | 12 |
| SW-846 8260 | 78-87-5 | 1,2-Dichloropropane | 82 | 111.2 | 12 | 12 |
| SW-846 8260 | 106-46-7 | 1,4-Dichlorobenzene | 74 | 97.51 | 12 | 12 |
| SW-846 8260 | 78-93-3 | 2-Butanone | 72.73 | 135.8 | 12 | 12 |
| SW-846 8081 | 50-29-3 | 4,4'-DDT | 122 | 122 | 1 | 1 |
| SW-846 8260 | 108-10-1 | 4-Methyl-2-pentanone | 83 - | 109 | 12 | 12 |
| SW-846 8260 | 67-64-1 | Acetone | 52.44 | 178.6 | 12 | 12 |
| SW-846 8081 | 309-00-2 | Aldrin | 99 | 99 | 11 | 11 |
| SW-846 6010 | 7429-90-5 | Aluminum | 1290 | 5110 | 7 | 7 |
| SW-846 6010 | 7440-36-0 | Antimony | 36 | 75 | 7 | 7 |
| SW-846 8082 | 12674-11-2 | Aroclor-1016 | 90 | 90 | 1 | 1 |
| SW-846 8082 | 11096-82-5 | Aroclor-1260 | 115 | 115 | 1 | 1 |
| SW-846 6010 | 7440-38-2 | Arsenic | 88 | 95 | 7 | 7 |
| SW-846 6010 | 7440-39-3 | Barium | 93 | 108 | 7 | 7 |
| SW-846 8260 | 71-43-2 | Benzene | 85 | 103 | 12 | 12 |
| SW-846 6010 | 7440-41-7 | Beryllium | 89 | 106 | 7 | 7 |
| SW-846 8260 | 75-27-4 | Bromodichloromethane | 79.56 | 107.5 | 12 | 12 |
| SW-846 8260 | 75-25-2 | Bromoform | 80.94 | 111.8 | 12 | 12 |
| SW-846 8260 | 74-83-9 | Bromomethane | 79 | 133.4 | 12 | 12 |
| SW-846 6010 | 7440-43-9 | Cadmium | 87 | 98 | 7 | 7 |
| SW-846 8260 | 75-15-0 | Carbon Disulfide | 57 | 86.79 | 12 | 12 |
| SW-846 8260 | 56-23-5 | Carbon Tetrachloride | 81.18 | 107.3 | 12 | 12 |
| SW-846 8260 | 108-90-7 | Chlorobenzene | 80.26 | 136.2 | 12 | 12 |
| SW-846 8260 | 75-00-3 | Chloroethane | 82 | 112.2 | 12 | 12 |
| SW-846 8260 | 67-66-3 | Chloroform | 84 | 107.1 | 12 | 12 |
| SW-846 8260 | 74-87-3 | Chloromethane | 87 | 140 | 12 | 12 |

| Test Method | CAS Number | Analyte | Minimum Percent Recovery | Maximum Percent Recovery | Number of Samples | Number of Lab Batches |
|-------------|---------------|---------------------------|--------------------------------|--------------------------------|----------------------|-----------------------------|
| SW-846 6010 | 7440-47-3 | Chromium | 100 | 560 | 7 | 7 |
| SW-846 8260 | 10061-01-5 | cis-1,3-Dichloropropene | 81.53 | 104 | 12 | 12 |
| SW-846 6010 | 7440-48-4 | Cobalt | 74 | 114 | 7 | 7 |
| SW-846 6010 | 7440-50-8 | Copper | 0 | 211 | 7 | 7 |
| SW-846 8260 | 124-48-1 | Dibromochloromethane | 74.54 | 103.1 | 12 | 12 |
| SW-846 8081 | 60-57-1 | Dieldrin | 102 | 102 | 11 | 1 |
| SW-846 8081 | 72-20-8 | Endrin | 99 | 99 | 11 | 1. |
| SW-846 8260 | 100-41-4 | Ethylbenzene | 79.37 | 125.7 | 12 | 12 |
| SW-846 8081 | 58-89-9 | gamma-BHC | 111 | 111 | 1 | 1 |
| SW-846 8081 | 76-44-8 | Heptachlor | 97 | . 97 | 11 | 1 |
| SW-846 8260 | 87-68-3 | Hexachlorobutadiene | 31.49 | 87 | · 12 | 12 |
| SW-846 6010 | 7439-89-6 | Iron | 703 | 2290 | 7 | 7 |
| SW-846 6010 | 7439-92-1 | Lead | 92 | 98 | 7 | 7 |
| SW-846 6010 | 7439-93-2 | Lithium | 91 | 107 | 7 | 7 |
| SW-846 6010 | 7439-96-5 | Manganese | 0 | 235 | 7 | 7 |
| SW-846 6010 | 7439-97-6 | Mercury | 22 | 98 | 7 | 7 |
| SW-846 8260 | 75-09-2 | Methylene chloride | 85 | 106 | 12 | 12 |
| SW-846 6010 | 7439-98-7 | Molybdenum | 87 | 95 | 7 | 7 |
| SW-846 8260 | 91-20-3 | Naphthalene | 54.85 | 90 | 12 | 12 |
| SW-846 6010 | 7440-02-0 | Nickel | 89 | 175 | 7 | 7 |
| SW-846 6010 | 7782-49-2 | Selenium | 87 | 93 | 7 | 7 |
| SW-846 6010 | 7440-22-4 | Silver | 89 | 100 | 7 | 7 |
| SW-846 6010 | 7440-24-6 | Strontium | 89 | 105 | 7 | .7 |
| SW-846 8260 | 100-42-5 | Styrene | 80.57 | 116.3 | 12 | 12 |
| SW-846 8260 | 127-18-4 | Tetrachloroethene | 67.45 | 98.86 | 12 | 12 |
| SW-846 6010 | 7440-31-5 | Tin | 82 | 91 | 7 | 7 |
| SW-846 8260 | 108-88-3 | Toluene | 80 | 98.01 | 12 | 12 |
| SW-846 8260 | 10061-02-6 | trans-1,3-Dichloropropene | 78.69 | 108 | 12 | 12 |
| SW-846 8260 | 79-01-6 | Trichloroethene | 87 | 165.4 | 12 | 12 |
| SW-846 6010 | 11-09-6 | Uranium, Total | 93 | 100 | 7 | 7 |
| SW-846 6010 | 7440-62-2 | Vanadium | 99 | 114 | 7 | 7 |
| SW-846 8260 | 75-01-4 | Vinyl chloride | 77 | 114.5 | 12 | 12 |
| SW-846 8260 | 1330-20-7 | Xylene | 78.24 | 115.3 | 12 | 12 |
| SW-846 6010 | 7440-66-6 | Zinc | 93 | 386 | 7 | 7 |

13.2.2 Precision

Precision is measured by evaluating both MSDs and field duplicates, as described in the following sections.

Sample MSD Evaluation

Laboratory precision is evaluated by computing the maximum relative percent differences (RPDs) between MS and MSD samples for each analyte, as summarized in

Table 19. Analytes with the highest relative percent differences (RPDs) were reviewed by comparing the highest sample result to the RFCA WRW AL. For analytes with RPDs greater than 35 percent, if the highest sample concentrations were sufficiently below the AL, no further evaluation is needed. Review of analytes listed in Table 19 with an RPD greater than 35 percent indicated no adverse impact to project decisions.

Table 19
Sample MS-MSD RPD Summary

| Test Method | CAS | Analyte | Maximum RPD | | | |
|-------------|------------|---------------------------|----------------|--|--|--|
| SW-846 8260 | 71-55-6 | 1,1,1-Trichloroethane | 19.368 | | | |
| SW-846 8260 | 79-34-5 | 1,1,2,2-Tetrachloroethane | 86.173 | | | |
| SW-846 8260 | 79-00-5 | 1,1,2-Trichloroethane | 9.326 | | | |
| SW-846 8260 | 75-34-3 | 1,1-Dichloroethane | 14.778 | | | |
| SW-846 8260 | . 75-35-4 | 1,1-Dichloroethene | 19.053 | | | |
| SW-846 8260 | 120-82-1 | 1,2,4-Trichlorobenzene | 32.868 | | | |
| SW-846 8260 | 95-50-1 | 1,2-Dichlorobenzene | 12.155 | | | |
| SW-846 8260 | 107-06-2 | 1,2-Dichloroethane | 15.020 | | | |
| SW-846 8260 | 78-87-5 | 1,2-Dichloropropane | 15.228 | | | |
| SW-846 8260 | 106-46-7 | 1,4-Dichlorobenzene | 9.825 | | | |
| SW-846 8260 | 78-93-3 | 2-Butanone | 22.764 | | | |
| SW-846 8081 | 50-29-3 | 4,4'-DDT | 7.660 | | | |
| SW-846 8260 | 108-10-1 | 4-Methyl-2-pentanone | 16.034 | | | |
| SW-846 8260 | 67-64-1 | Acetone | 23.077 | | | |
| SW-846 8081 | 309-00-2 | Aldrin | 5.181 | | | |
| SW-846 6010 | 7429-90-5 | Aluminum | 113:653 | | | |
| SW-846 6010 | 7440-36-0 | Antimony | 22.727 | | | |
| SW-846 8082 | 12674-11-2 | Aroclor-1016 | 30.986 | | | |
| SW-846 8082 | 11096-82-5 | Aroclor-1260 | 3.540 | | | |
| SW-846 6010 | 7440-38-2 | Arsenic | 5.464 | | | |
| SW-846 6010 | 7440-39-3 | Barium | 11.659 | | | |
| SW-846 8260 | · 71-43-2 | Benzene | 16.708 | | | |
| SW-846 6010 | 7440-41-7 | Beryllium | 27.184 | | | |
| SW-846 8260 | 75-27-4 | Bromodichloromethane | 15.247 | | | |
| SW-846 8260 | 75-25-2 | Bromoform | 28.295 | | | |
| SW-846 8260 | 74-83-9 | Bromomethane . | 18.391 | | | |
| SW-846 6010 | 7440-43-9 | Cadmium | 6.383 | | | |
| SW-846 8260 | 75-15-0 | Carbon Disulfide | 17.964 | | | |
| SW-846 8260 | 56-23-5 | Carbon Tetrachloride | 21.856 | | | |
| SW-846 8260 | 108-90-7 | Chlorobenzene | 28.523 | | | |
| SW-846 8260 | 75-00-3 | Chloroethane | 18.378 | | | |
| SW-846 8260 | 67-66-3 | Chloroform | 15.525 | | | |
| SW-846 8260 | 74-87-3 | Chloromethane | 20.559 | | | |
| SW-846 6010 | 7440-47-3 | Chromium | 133.333 | | | |
| SW-846 8260 | 10061-01-5 | cis-1,3-Dichloropropene | 13.198 | | | |
| SW-846 6010 | 7440-48-4 | Cobalt | 15 | | | |

| Test Method | CAS | Analyte | Maximum RPD |
|-------------|------------|---------------------------|----------------|
| SW-846 6010 | 7440-50-8 | Copper | 200 |
| SW-846 8260 | 124-48-1 | Dibromochloromethane | 10.628 |
| SW-846 8081 | 60-57-1 | Dieldrin | 6.061 |
| SW-846 8081 | 72-20-8 | Endrin | 6.25 |
| SW-846 8260 | 100-41-4 | Ethylbenzene | 26.008 |
| SW-846 8081 | 58-89-9 | gamma-BHC | 13.462 |
| SW-846 8081 | 76-44-8 | Heptachlor | 3.0457 |
| SW-846 8260 | 87-68-3 | Hexachlorobutadiene | 45.580 |
| SW-846 6010 | 7439-89-6 | Iron | 200 |
| SW-846 6010 | 7439-92-1 | Lead | 8.780 |
| SW-846 6010 | 7439-93-2 | Lithium | 5.769 |
| SW-846 6010 | 7439-96-5 | Manganese | 70.423 |
| SW-846 6010 | 7439-97-6 | Mercury | 58.065 |
| SW-846 8260 | . 75-09-2 | Methylene chloride | 16.216 |
| SW-846 6010 | 7439-98-7 | Molybdenum | 5.405 |
| SW-846 8260 | 91-20-3 | Naphthalene | 22.917 |
| SW-846 6010 | 7440-02-0 | Nickel | 56.410 |
| SW-846 6010 | 7782-49-2 | Selenium | 5.525 |
| SW-846 6010 | 7440-22-4 | Silver | 6.383 |
| SW-846 6010 | 7440-24-6 | Strontium | 10 |
| SW-846 8260 | 100-42-5 | Styrene | 20.495 |
| SW-846 8260 | 127-18-4 | Tetrachloroethene | 21.313 |
| SW-846 6010 | 7440-31-5 | Tin | 5.848 |
| SW-846 8260 | 108-88-3 | Toluene | 10.701 |
| SW-846 8260 | 10061-02-6 | trans-1,3-Dichloropropene | 14.074 |
| SW-846 8260 | 79-01-6 | Trichloroethene | 31.076 |
| SW-846 6010 | 11-09-6 | Uranium, Total | 6.316 |
| SW-846 6010 | 7440-62-2 | Vanadium | 68.966 |
| SW-846 8260 | 75-01-4 | Vinyl chloride | 17.978 |
| SW-846 8260 | 1330-20-7 | Xylene | 24.058 |
| SW-846 6010 | 7440-66-6 | Zinc | 13.333 |

Field Duplicate Evaluation

Field duplicate results reflect sampling precision, or the overall repeatability of the sampling process. The frequency of field duplicate collection should exceed 1 field duplicate per 20 real samples, or 5 percent. This goal is applied to the overall ER project and not on a specific IHSS Group basis.

Table 20 indicates field duplicate frequencies were slightly below 5 percent for radionuclides analyzed by gamma spectroscopy. Frequencies were zero for pesticides (SW-846 8081), PCBs (SW-846 8082), and herbicides (SW-846 8151A); however, this is expected because only two IHSS Group 500-3 samples were analyzed using each of these methods.

Table 20
Field Duplicate Sample Frequency Summary

| Test Method | Number of Real Samples | Number of Duplicate Samples | Percent Duplicate Samples | |
|--------------------|------------------------------|-----------------------------------|---------------------------|--|
| Alpha spectroscopy | 22 | 3 | 13.0 % | |
| Gamma spectroscopy | 116 | 5 | 4.3 % | |
| SW-846 6010 | 71 | 5 | 7.0 % | |
| SW-846 6200 | 7 | 1 | 14.3 % | |
| SW-846 8081 | 2 | 0 | 0% | |
| SW-846 8082 | 2 | 0 | 0% | |
| SW-846 8151A | 2 | 0 | 0% | |
| SW-846 8260 | 76 | 5 | 6.6 % | |

The field duplicate RPD values indicate how much variation exists in the field duplicate analytical results obtained from analyzing samples collected at the same time and from the same location and depth. EPA data validation guidelines state "there are no required review criteria for field duplicate analyses comparability" (EPA 1994b). For the DQA, the highest RPD values were reviewed (Table 21), and no adverse impact on project decisions was indicated.

Table 21
Field Duplicate RPD Evaluation Summary

| Lab Code | Test Method | Analyte | Maximum RPD |
|----------|-------------|-------------|----------------|
| ESTLDEN | SW-846 6010 | Aluminum | 40.00 |
| ESTLDEN | SW-846 6010 | Arsenic | 39.25 |
| ESTLDEN | SW-846 6010 | Barium | 35.90 |
| ESTLDEN | SW-846 6010 | Beryllium | 57.89 |
| ESTLDEN | SW-846 6010 | Chromium | 41.51 |
| ESTLDEN | SW-846 6010 | Cobalt | 37.50 |
| URS | SW-846 6200 | Cobalt | 0.00 |
| ESTLDEN | SW-846 6010 | Copper | 38.55 |
| ESTLDEN | SW-846 6010 | Iron | 18.18 |
| URS | SW-846 6200 | Iron | 7.90 |
| ESTLDEN | SW-846 6010 | Lead | 33.33 |
| ESTLDEN | SW-846 6010 | Lithium | 46.15 |
| ESTLDEN | SW-846 6010 | Manganese | 37.84 |
| ESTLDEN | SW-846 6010 | Mercury | 16.09 |
| ESTLDEN | SW-846 6010 | Nickel | 40.00 |
| URS | SW-846 6200 | Nickel | 2.99 |
| URS | SW-846 6200 | Strontium | 7.68 |
| ESTLDEN | SW-846 6010 | Strontium | 42.42 |
| ESTLDEN | SW-846 6010 | Tin | 35.15 |
| GEL | ALPHA SPEC | Uranium-234 | 29.28 |
| GEL | ALPHA SPEC | Uranium-238 | 35.00 |

| Läb Code | Test Method | Analyte | Maximum RPD |
|----------|-------------|----------|----------------|
| ESTLDEN | SW-846 6010 | Vanadium | 32.26 |
| ESTLDEN | SW-846 6010 | Zinc | 38.46 |

13.2.3 Completeness

Based on original project DQOs, a minimum of 25 percent of ER Program analytical (and radiological) results must be formally verified and validated. Of that percentage, no more than 10 percent of the results may be rejected, which ensures that analytical laboratory practices are consistent with quality requirements. The number and percentage of validated records (codes without "1"), the number and percentage of verified records (codes with "1"), and the percentage of rejected records for each analyte group for this project are listed in Table 22.

Table 22
Validation and Verification Summary

| | | Number of Records by Test Method | | | | | | |
|---------------------------------|----------------------------------|----------------------------------|----------------------------|----------------|----------------|----------------|----------------|----------------|
| Validation Qualifier Code | Total Number of Records | Alpha Spectro- scopy | Gamma Spectro- scopy | SW-846 6010 | SW-846 6200 | SW-846 8081 | SW-846 8082 | SW-846 8260 |
| None | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 |
| 1 | 4 | 0 | - 4 | 0 | 0 | 0 | 0 | 0 |
| J | 96 | 0 | 0 | 91 | 4 | 0 | 0 | 1 |
| J1 | 226 | -5 | 0 | 201 | 17 | 0 | 0 | 3 |
| JB | 9 | 0 | 0 | 0 | 0 | 0 | 0 | 9 |
| JB1 | 8 | 0 | 0 | 0 | 0 | 0 | 0 | 8 |
| R | 1 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| U | 2 | 0 | 0 | 0 | 0 | . 0 | 0 | 2 |
| UJ | 31 | 0 | 0 | 19 | 4 | 0 | 0 | 8 |
| UJ1 | 100 | 0 | 0 | 74 | 7 | 0 | 0 | 19 |
| V | 1449 | 0 | 72 | 396 | 29 | 0 | 0 | 952 |
| V1 | 3231 | 110 | 272 | 852 | 71 | 34 | 14 | 1878 |
| Total | 5159 | 115 | 350 | 1633 | 133 | 34 | 14 | 2880 |
| Validated | 1588 | 0 | 72 | 506 | 38 | 0 | 0 | 972 |
| %Validated | 30.8% | 0.0% | 20.6% | 31.0% | 28.6% | 0.0% | 0.0% | 33.8% |
| Verified | 3569 | 115 | 276 | 1127 | 95 | 34 | 14 | 1908 |
| %Verified | 69.2% | 100.0% | 78.9% | 69.0% | 71.4% | 100.0% | 100.0% | 66.3% |
| Rejected | 1 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| %Rejected | 0.02% | 0.00% | 0.00% | 0.00% | 0.75% | 0.00% | 0.00% | 0.00% |

Out of 5,159 total results, one metal result was rejected (0.02 percent). The rejection of this record did not affect project decisions. For this project, 30.8 percent of the analyses were validated. However, less than 25 percent of results for alpha spectroscopy, gamma

spectroscopy, SW-846 8081 (pesticides), and SW-846 8082 (PCBs), were validated. This is below Program requirements; however, the overall ER Program V&V goal of 25 percent is being met.

13.2.4 Sensitivity

RLs, in units of micrograms per kilogram ($\mu g/kg$) for organics, milligrams per kilogram (mg/kg) for metals, and pCi/g for radionuclides, were compared with RFCA WRW ALs. Adequate sensitivities of analytical methods were attained for all COCs that affect remediation decisions. "Adequate" sensitivity is defined as an RL less than an analyte's associated AL, typically less than one-half the AL.

13.3 Summary of Data Quality

RPDs greater than 35 percent indicate the sampling precision limits of some analytes have been exceeded. Also, IHSS Group 500-3 validation percentages for pesticides, PCBs, and radionuclides were below 25 percent; however, the ER Program V&V goal of 25 percent is being met. Data collected and used for accelerated action at IHSS Group 500-3 are adequate for decision making.

14.0 CONCLUSIONS

Results of the accelerated action justify an NFAA determination for IHSS Group 500-3. This justification is based on the following:

- No additional accelerated action is required based on surface soil characterization and confirmation sample data, because there are no longer any WRW AL exceedances in surface soil or subsurface soil.
- No additional accelerated action is required based on the SSRS, as described in Section 7.0.
- No additional accelerated action is required based on the stewardship evaluation, as described in Section 8.0

15.0 REFERENCES

DOE, 1992, Historical Release Report for the Rocky Flats Plant, Golden, Colorado.

DOE, 1999, Order 414.1A, Quality Assurance.

DOE, 2000, Industrial Area Data Summary Report, Rocky Flats Environmental Technology Site, Golden, Colorado, September.

DOE, 2001, Industrial Area Sampling and Analysis Plan, Rocky Flats Environmental Technology Site, Golden, Colorado, June.

DOE, 2003a, Industrial Area Sampling and Analysis Plan Addendum #IA-03-12, IHSS Group 500-3, Rocky Flats Environmental Technology Site, Golden, Colorado, August.

DOE, 2003b, Environmental Restoration RFCA Standard Operating Protocol for Routine Soil Remediation Notification #03-14, Rocky Flats Environmental Technology Site, Golden, Colorado, October.

DOE, 2003c, RFCA Standard Operating Protocol for Facility Component Removal, Size Reduction, and Decontamination Revision 3, Rocky Flats Environmental Technology Site, Golden, Colorado, May.

DOE, 2004a, Environmental Restoration RFCA Standard Operating Protocol for Routine Soil Remediation Modification 2, Rocky Flats Environmental Technology Site, Golden, Colorado, September.

DOE, 2004b, Waste Stream and Residue Identification and Characterization Building Book, Building 561, Version 7.0, Rocky Flats Environmental Technology Site, Golden, Colorado, August.

DOE, 2004c, Industrial Area and Buffer Zone Sampling and Analysis Plan, Rocky Flats Environmental Technology Site, Golden, Colorado.

DOE, 2004d, RFCA Standard Operating Protocol for Facility Disposition Modification 1, Rocky Flats Environmental Technology Site, Golden, Colorado, March.

DOE, 2005a, Environmental Restoration RFCA Standard Operating Protocol for Routine Soil Remediation Notification #05-02, Rocky Flats Environmental Technology Site, Golden, Colorado, February.

DOE, 2005b, 2005 Historical Release Report, Rocky Flats Environmental Technology Site, Golden, Colorado (in preparation).

DOE, CDPHE, and EPA, 2003, Modifications to the Rocky Flats Cleanup Agreement Attachment, U.S. Department of Energy, Colorado Department of Public Health and Environment, and U.S. Environmental Protection Agency, Rocky Flats Environmental Technology Site, Golden, Colorado, June.

EPA, 1994a, Guidance for the Data Quality Objective Process, QA/G-4.

EPA, 1994b, USEPA Contract Laboratory Program National Functional Guidelines for Organic Data Review, 540/R-94/012.

EPA, 1994c, USEPA Contract Laboratory Program National Functional Guidelines for Inorganic Data Review, 540/R-94/013.

EPA, 1998, Guidance for the Data Quality Assessment Process, Practical Methods for Data Analysis, QA/G-9.

K-H, 2002a, General Guidelines for Data Verification and Validation, DA-GR01-v2, December.

K-H, 2002b, V&V Guidelines for Isotopic Determinations by Alpha Spectrometry, DA-RC01-v2.

K-H, 2002c, V&V Guidelines for Volatile Organics, DA-SS01-v2.

K-H, 2002d, V&V Guidelines for Semivolatile Organics, DA-SS02-v3.

K-H, 2002e, V&V Guidelines for Metals, DA-SS05-v1.

K-H, 2002f, V&V Guidelines for Radiochemistry by Gamma Spectrometry DA-GAM-v1.

Lockheed-Martin, 1997, Evaluation of Radiochemical Data Usability, ES/ER/MS-5.

APPENDIX A CORRESPONDENCE

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE ER REGULATORY CONTACT RECORD

| Date/Time: | August 5, 2004 / 1515 | | |
|---|---|---|--|
| Site Contact(s): | Annette Primrose | Norma Castaneda | |
| Phone: | 303 966-9883 | 303 966-4226 | |
| Regulatory Contact: | Harlen Ainscough | | |
| Phone: | 303 692-3337 | | |
| Agency: | CDPHE | | |
| Purpose of Contact: | Modifications to the | 500-3 Sampling and Analysis Plan Addendu | |
| a water sample is antic | ipated to be collected. lose to the building as | sperience coring through subsurface structure. Therefore, it is agreed that this location will possible. Samples will be collected from the side the building. | |
| | | | |
| Contact Record Prep | | | |
| Contact Record Preparetes Required Distribution: | | | |
| | | nrose Additional Distribution: -H RISS Karen Maley, K-H RISS | |
| Required Distribution: M. Aguilar, USEPA H. Ainscough, CDPHE | ared By: Annette Prin D. Mayo, K- J. Mead, K-I | Additional Distribution: -H RISS Karen Maley, K-H RISS H ESS Sherry Lopez, K-H RISS | |
| Required Distribution: M. Aguilar, USEPA | ared By: Annette Prin D. Mayo, K- | Additional Distribution: -H RISS Karen Maley, K-H RISS H ESS Sherry Lopez, K-H RISS | |
| Required Distribution: M. Aguilar, USEPA H. Ainscough, CDPHE S. Bell, DOE-RFPO J. Berardini, K-H | D. Mayo, K-J. Mead, K-J. Norland, J. Norland, J. | Additional Distribution: -H RISS Karen Maley, K-H RISS H ESS Sherry Lopez, K-H RISS H RISS Sam Garcia, USEPA K-H RISS Nan Elzinga, URS | |
| Required Distribution: M. Aguilar, USEPA H. Ainscough, CDPHE S. Bell, DOE-RFPO J. Berardini, K-H B. Birk, DOE-RFPO | D. Mayo, K-J. Mead, K-J. Norland, J. North, K- | Additional Distribution: -H RISS Karen Maley, K-H RISS H ESS Sherry Lopez, K-H RISS H RISS Sam Garcia, USEPA K-H RISS Nan Elzinga, URS -H ESS Tom Hanson, URS | |
| Required Distribution: M. Aguilar, USEPA H. Ainscough, CDPHE S. Bell, DOE-RFPO J. Berardini, K-H B. Birk, DOE-RFPO L. Brooks, K-H ESS | D. Mayo, K-J. Mead, K-J. Norland, J. North, K-E. Pottorff, C | Additional Distribution: -H RISS Karen Maley, K-H RISS H ESS Sherry Lopez, K-H RISS H RISS Sam Garcia, USEPA K-H RISS Nan Elzinga, URS -H ESS Tom Hanson, URS CDPHE | |
| Required Distribution: M. Aguilar, USEPA H. Ainscough, CDPHE S. Bell, DOE-RFPO J. Berardini, K-H B. Birk, DOE-RFPO L. Brooks, K-H ESS L. Butler, K-H RISS | D. Mayo, K-J. Mead, K-J. North, K-E. Pottorff, CA. Primrose, | Additional Distribution: -H RISS Karen Maley, K-H RISS H ESS Sherry Lopez, K-H RISS H RISS Sam Garcia, USEPA K-H RISS Nan Elzinga, URS -H ESS Tom Hanson, URS CDPHE , K-H RISS | |
| Required Distribution: M. Aguilar, USEPA H. Ainscough, CDPHE S. Bell, DOE-RFPO J. Berardini, K-H B. Birk, DOE-RFPO L. Brooks, K-H ESS L. Butler, K-H RISS G. Carnival, K-H RISS | D. Mayo, K-J. Mead, K-J. Norland, J. North, K-E. Pottorff, CA. Primrose, R. Schassbur | Additional Distribution: H RISS Karen Maley, K-H RISS H ESS Sherry Lopez, K-H RISS H RISS Sam Garcia, USEPA K-H RISS Nan Elzinga, URS H ESS Tom Hanson, URS CDPHE , K-H RISS rger, DOE-RFPO | |
| Required Distribution: M. Aguilar, USEPA H. Ainscough, CDPHE S. Bell, DOE-RFPO J. Berardini, K-H B. Birk, DOE-RFPO L. Brooks, K-H ESS L. Butler, K-H RISS | D. Mayo, K-J. Mead, K-J. Norland, J. North, K-E. Pottorff, CA. Primrose, R. Schassbur | Additional Distribution: H RISS Karen Maley, K-H RISS H ESS Sherry Lopez, K-H RISS H RISS Sam Garcia, USEPA K-H RISS Nan Elzinga, URS H ESS Tom Hanson, URS CDPHE K-H RISS rger, DOE-RFPO K-H RISS | |

C. Spreng, CDPHE

S. Surovchak, DOE-RFPO J. Walstrom, K-H RISS

K. Wiemelt, K-H RISS

C. Zahm, K-H Legal

N. Demos, SSOC S. Gunderson, CDPHE

M. Keating, K-H RISS G. Kleeman, USEPA

D. Kruchek, CDPHE

J. Legare, DOE-RFPO

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE ER REGULATORY CONTACT RECORD

Date/Time:

April 14, 2005, 10:30

Site Contact(s):

Annette Primrose

Norma Castaneda

Phone:

966-4385

966-4226

Regulatory Contact:

Phone:

David Kruchek 303 692-3328

Agency:

CDPHE

Purpose of Contact:

Backfill of B559 Remediation Areas

Discussion

After removal of the process waste line in this area, the hotspot around sample location CD44-005 was excavated in an area approximately 20 by 24 feet and 4 ½ feet deep. Screening results from the bottom and sides of the excavation are all very low, well below action levels. Therefore, this area will be backfilled at risk, pending final analytical results.

A previous, hot spot associated with the process waste lines but nearer to the air tunnel was already backfilled. This area was approximately 6 feet deep, and had low levels of contamination slightly above the action levels prior to excavation. Screening results at this location were below action levels. This hotspot was backfilled at risk, pending final analytical results, to allow continued work on removal of the B559 structures.


An additional approximately two feet of soil was removed from the base of the excavation for the OPWL manway between 528 Pit and Building 559. The excavation is now approximately 9 feet deep. The screening level sample result for this excavation was far below action levels.

Contact Record Prepared By: Annette Primrose

| Required Distribution: | • * | Additional Distribution: |
|------------------------|---------------------------|--------------------------|
| M. Aguilar, USEPA | J. Legare, DOE-RFPO | K. Maley, K-H RISS |
| H. Ainscough, CDPHE | D. Mayo, K-H RISS | G. Pudlik, K-H RISS |
| J. Berardini, K-H | S. Nesta, K-H RISS | R. Ferrera, K-H RISS |
| B. Birk, DOE-RFPO | L. Norland, K-H RISS | |
| L. Brooks, K-H ESS | E. Pottorff, CDPHE | |
| G. Carnival, K-H RISS | A. Primrose, K-H RISS | |
| N. Castaneda, DOE-RFPO | M. Roy, DOE-RFPO | |
| C. Deck, K-H Legal | R. Schassburger, DOE-RFPO | |
| N. Demos, SSOC | S. Serreze, K-H RISS | |
| S. Garcia, USEPA | D. Shelton, K-H ESS | |
| S. Gunderson, CDPHE | C. Spreng, CDPHE | |
| S. Johnson, K-H ESS | S. Surovchak, DOE-RFPO | <u> </u> |
| M. Keating, K-H RISS | J. Walstrom, K-H RISS | |
| L. Kimmel, USEPA | K. Wiemelt, K-H RISS | <u> </u> |
| D. Kruchek, CDPHE | C. Zahm, K-H Legal | |
| | | |

APPENDIX B PROJECT PHOTOGRAPHS


APPENDIX B PROJECT PHOTOGRAPHS




Excavation of Room 130 hot spot with Building 559 slab in place.




Building 559 slab during initial excavation of Room 130 hot spot.



Partially excavated manway between Buildings 528 and 559.



Removal of asphalt mixed with gravel during Building 559 D&D.




Pipe stub exposed during Building 559 excavation.




Workers look for shards of Pyrex released by breaking of Pyrex OPWL during removal.



Pyrex shard generated by breaking of Pyrex OPWL during removal.




Scattering of Pyrex shards generated by breaking Pyrex OPWL lines during removal.




Scattering of Pyrex shards generated by breaking Pyrex OPWL lines during removal.


ENCLOSURE


COMPACT DISC IHSS GROUP 500-3 ACCELERATED ACTION DATA






IA-A-002725






IHSS Group 500-3 Residual **Surface Soil Contamination Background Means Plus Two**

- or background means plus



Rocky Flats Environmental Technology Site





TA-A-002725

